

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001



No. F6/DFS/MS/GH/NDZ/2025/253

Dated: 24 /04/2025

FIRE SAFETY CERTIFICATE

Certified that the M/s Krishna Dx. Guest House located at 43, Arakashan Road, Pahar Ganj, New Delhi - 110055, building comprised of Ground + 05 upper floors (total 47 Guest Rooms), Ground floor (Reception + 08 Guest Rooms + office), 1st floor to 3rd floor (13 guest rooms to each floor), 4th & 5th floor owned / occupied by M/s Krishana Dx. Guest House was granted FSC by this department vide letter No. F6/DFS/MS/GH/2022/492 dated 28/10/2022. The premises was re-inspected by the officer concerned of this department on 17/04/2025 in the presence of Mr. Jitu & Mr. Chandan (Manager) and found that the said guest house building having given an affidavit dated 17.04.2025 regarding not to use any floor above third floor, has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Group - A "Residential Building" Sub Division-A-1, Ground + 03 upper floors (total 47 Guest Rooms), Ground floor (Reception + 08 Guest Rooms + office), 1st floor to 3rd floor (13 guest rooms to each floor) up to third floor only with effect from 24/04/2025 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010. Subject to conditions printed below.

Issued 24/04/2025 at New Delhi by.

(ATUL GARG)
DIRECTOR
O) DELHI FIRE SERVICE

Copy to: -

- 1. The Commissioner, MCD Civic Center, New Delhi: to ensure the occupancy as detailed above.
- 2. The Joint Commissioner of Police (Lic.), first Floor, Police Station Defence Colony, New Delhi 110024. w.r.t.- MCD portal ID 202540505698 dated 05/04/2025.
- 3. The Owner, M/s Krishana Dx. Guest House located at 43, Arakashan Road, Pahar Ganj, New Delhi 110055

Conditions for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an

8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

e.

at

he

INSPECT

nahar Ganj, New Dellin 22000

			7	NCDECTY				
1	Nam	ie d	& address of the	INSPECTION RE	PORT			
1	build		x address of the	M/s Krishana D	X Guest Hand			
2			is comprised of	M/s Krishana Dx. Guest House located at 43, Arakashan Road, Pahar Ganj, New Delhi - 110055.				
2	Dun	anng l	is comprised of	Ground + 05 upper floors (total 47 Guest Rooms) Ground floor (Reception + 22 Guest Rooms)				
				Ground floor (Reception + 08 Guest Rooms) to 3 rd floor (13 guest rooms to each floor), 4 th & 5 th floor given an affidayit dated 17/04/2025				
3	Type	ofo	ccupancy			, 4 th & 5 th floor		
4	Type	ofc	ase	Residential, Sub Division-A-1				
5	Type of case			Renewal				
6	Details of previous FSC			F6/DFS/MS/GH/2022/492 dated 28/10/2022				
7	Data							
8	Date of inspection 17/04/2025							
	Name of the inspecting officers			Vachwant C: 13	Meena, A.D.O / Laxmi Na			
9	Name of the designation of			Mr. Jitu & Mr. Ch	andan (Managar)	agar		
	officer From the building side			Mr. Jitu & Mr. Chandan (Manager)				
10	Year of construction			1981				
11	Applicant's letter no							
				MCD Portal application No. 202540505698 dated 05/04/2025				
	I	Mini	mum Standards on	Requirement		Damasalas		
S.N	o 1	fire P	Prevention and fire	Existing	Provided at Site	Remarks MR/NMR		
_	sa	fety 1	requirements U/R 33	8	223,7434 47 57,0	MICHAIN		
1	Access to building							
	a		oad width	N/A	06 mtr. Approx	MR		
	b		ate width	N/A	N/A	N/A		
	С		idth of internal road	N/A	N/A	N/A		
2	Number, Width, Type and Ai			rrangement of Exits	S			
	A	N	Number of staircases					
		a	Upper floor	01 no.	01 no.	MR		
in the second		b	Basement	N/A	N/A	N/A		
	В		Width of staircases			1071		
		a	Upper floor	1.25 meter	1.50 meter	MR		
l		b	Basement	N/A				
	C	Pro		=	N/A	34502		
			otection of exits		N/A	N/A		
		a	Fire check door	Required		N/A		
		a b	Fire check door Pressurization		Provided	N/A MR		
	D	a b No.	Fire check door Pressurization of continuous	Required	Provided N/A	N/A MR N/A		
		a b No. stai	Fire check door Pressurization of continuous rcases to terrace	Required N/A	Provided	N/A MR		
	Е	a b No. stai	Fire check door Pressurization of continuous reases to terrace dth of corridor	Required N/A	Provided N/A 01 no.	MR N/A MR		
	E F	a b No. stai Wid	Fire check door Pressurization of continuous rcases to terrace dth of corridor or size	Required N/A 01 no.	Provided N/A 01 no. 125 cms & 150 cms	MR N/A MR N/A		
3	E F Con	a b No. stai Wic	Fire check door Pressurization of continuous reases to terrace dth of corridor or size rementation	Required N/A 01 no. N/A	Provided N/A 01 no.	MR N/A MR		
3	E F Con	a b No. stai Wic	Fire check door Pressurization of continuous reases to terrace dth of corridor or size rementation check door	Required N/A 01 no. N/A N/A	Provided N/A 01 no. 125 cms & 150 cms 85 x 220 cms	N/A MR N/A MR N/A MR		
3	E F Con a b	a b No. stai Wice Doc mpar Fire Seali	Fire check door Pressurization of continuous reases to terrace dth of corridor or size rementation check door	Required N/A 01 no. N/A N/A N/A	Provided	MR N/A MR N/A		
3	E F Con a b c	a b No. stai Wid Dod mpar Fire Seali	Fire check door Pressurization of continuous reases to terrace of the of corridor or size rementation check door ing of electrical shafts rating of shaft door	Required N/A 01 no. N/A N/A N/A N/A N/A	Provided	N/A MR N/A MR N/A MR		
3	E F Coo	a b No. stai Wic Doc mpar Fire Seali Fire Wate	Fire check door Pressurization of continuous reases to terrace dth of corridor or size rementation check door ing of electrical shafts rating of shaft door er curtain	Required N/A 01 no. N/A N/A N/A N/A N/A N/A N/A	Provided	MR N/A MR N/A MR N/A N/A MR		
	E F Coo a b c d e	a b No. stai Wid Dod mpar Fire Seali Fire Wate	Fire check door Pressurization of continuous reases to terrace of the of corridor or size rementation check door ing of electrical shafts rating of shaft door or curtain dampers	Required N/A 01 no. N/A N/A N/A N/A N/A N/A N/A N/A	Provided	N/A MR N/A MR N/A N/A N/A N/A		
	E F Coo a b c d e Smo	a b No. stai Wice Doc mpar Fire Seali Fire Wate Fire Coke M	Fire check door Pressurization of continuous reases to terrace dth of corridor or size rementation check door ing of electrical shafts rating of shaft door or curtain dampers Ianagement System	Required N/A 01 no. N/A N/A N/A N/A N/A N/A N/A	Provided	N/A MR N/A MR N/A MR N/A N/A N/A N/A N/A		
	E F Con a b c d e Smo	a b No. stai Wid Dod mpar Fire Seali Fire Wate Fire o bke M Baser	Fire check door Pressurization of continuous reases to terrace of the of corridor or size rementation check door ing of electrical shafts rating of shaft door or curtain dampers Management System ment	Required N/A 01 no. N/A N/A N/A N/A N/A N/A N/A N/A N/A N/	Provided	N/A MR N/A MR N/A MR N/A N/A N/A N/A		
3	E F Con a b c d e Smo	a b No. stai Wid Dod mpar Fire Seali Fire Wate Fire o bke M Baser	Fire check door Pressurization of continuous reases to terrace dth of corridor or size rementation check door ing of electrical shafts rating of shaft door or curtain dampers Ianagement System	Required N/A 01 no. N/A N/A N/A N/A N/A N/A N/A N/A	Provided	N/A MR N/A MR N/A MR N/A N/A N/A N/A N/A		

Krishana Dx. Guest House located at 43, Arakashan Road, Pahar Ganj, New Delhi – 110055. Fire Extinguisher 14/1 Total numbers 17 nos. 17 nos. MR b **Types** CO₂ & ABC CO₂ & ABC MR ISI marking ISI marked ISI marked MR First-aid-Hose Reels. 6 Total numbers of each floor 01 no. 01 no. MR 30 mtrs Length of hose reel hose b 30 mtrs MR 05 mm Nozzle diameter 05 mm MR Automatic Fire Detection & Alarming System. 7 Type of detectors CO Required Provided MR Ground floor Location of main panel Provided MR b Location of repeater panel N/A N/A N/A С Alternate source of power Required Provided MR d Ground floor Hooter's location Provided MR e Provided MR Required **MOEFA** 8 Provided MR Required Public Address System. Automatic Sprinkler System. 10 N/A N/A N/A Basement N/A N/A N/A Upper floors b N/A N/A Sprinkler above false ceiling N/A **Internal Hydrants** 11 MR 100 mm 100 mm Size of riser/down-comer MR 01 no 01 no Number of hydrants per floor MR 01 no 01 no Hose Box Yard Hydrants. 12 N/A N/A N/A Total number of hydrants N/A N/A N/A Hose Box **Pumping Arrangements.** 13 Ground Level A N/A N/A Discharge of main Pump N/A a Head of Main Pump N/A N/A N/A Number of main pumps N/A N/A N/A d Jockey pump out put N/A N/A N/A Jockey pump head N/A N/A N/A f Stand by pump out put N/A N/A N/A Stand by pump head g N/A N/A N/A Auto starting /manual N/A N/A N/A stopping B Terrace Level Discharge of pump 450 LPM 450 LPM MR



40 mtrs.

Required

Required

Head of the Pump

Auto Starting of pump

Power supply

c



40 mtrs.

Provided

Provided

MR

MR

MR

M/s Krishana Dx. Guest House located at 43, Arakashan Road, Pahar Ganj, New Delhi – 110055.

14	Captive Water Storage for Fire Fighting									
	a	Underground tank capacity	N/A	N/A	N/A					
	b	Draw-off connection	N/A	N/A	N/A					
	c	Fire service inlet	Required	Provided	MR					
,	d	Access to tank	Required	Provided	MR					
	e	Overhead Tank capacity	50,000 liters.	50,000 liters	MR					
15	Ex	kit Signage.	Required	Provided	MR					
16	Provision of Lifts									
	a	Pressurization of Lift Shaft	NA	NA	NA					
	b	Pressurization of Lift lobby	NA	NA	NA					
	С	Communication in lift car	Required	Provided	MR					
	d	Firemen's switch	Required	Provided	MR					
	e	Lift Signage	Required	Provided	MR					
17	St	andby power supply	Required	Provided	MR					
18	Refuge Area.									
	a	Total area	NA	NA	NA					
	b	Location	NA	NA	NA					
19	Fire Control Room									
	a	Detector system panel	N/A	N/A	N/A					
	b	Flow switch panel	N/A	N/A	N/A					
	c	PA system panel	N/A	N/A N/A	N/A					
	d	Battery backup	N/A	N/A N/A	N/A					
	-		N/A		N/A					
20	e Building Floor Plans Special Fire Protection systems for protection of special Risks, if									
	any:									

Note: At the time of inspection 4th & 5th floor found closed (Given an affidavit dated 17/04/2025).

The fire protection system was randomly checked and tested and was found functional at the time of inspection.

Keeping in view the compliance of the minimum standards of fire prevention and fire safety measures as required under the rules. The FSC issued vide letter no. F6/DFS/MS/GH/2022/492 dated 28/10/2022 renewal under rule 35(6) of the Delhi Fire Service rules 2010 is recommended.

Signature of the Inspecting Officer
Name: Yaswant Singh Meena

Designation: ADO /Laxmi Nagar

7/4/25

reeta M

Dineeter My

AND AND