

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001

The CITY

No. F6/DFS/MS/Hospital/NDZ/2025/512

Dated: 01 /04/2025

To,

Dr. H.S. Kukreja, Kukreja Hospital D-36, Acharya Niketan Mayur Vihar Phase-1, Delhi - 110091.

Subject: - Regarding grant of Fire Safety Certificate in r/o Kukreja Hospital at D - 36, Acharya Niketan Mayur Vihar Phase – I, Delhi – 110091.

Sir,

Please refer to your outdoor diary no. 14120 dated 05/03/2025 on the subject cited above. In this connection, it is to inform you that the site was visited by officer concerned of this department on dated 24/03/2025 and observed that the shortcoming has still not complied with as issued by this department vide letter no. F6/DFS/MS/Hospital/NDZ/2025/88 dated 04/03/2025 (copy overleaf).

In view of above, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Yours faithfully,

Enclosed: As above

(ATUL/GARG)
DIRECTOR
OCCUPANTINE SERVICE

Copy to:-

 The Executive Engineer (Bldg), Municipal Corporation of Delhi, Plot No.419, Patparganj Industrial Area, Delhi-110092.



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001



Dated 4 /03/2025

No. F6/DFS/MS/Hospital/NDZ/2025/ 88

To.

Dr. H.S. Kukreja, Kukreja Hospital, D-36, Acharya Niketan Mayur Vihar Phase-1, Delhi-110091.

Subject: - Regarding grant of Fire Safety Certificate in r/o Kukreja Hospital at D-36, Acharya Niketan Mayur Vihar Phase-1, Delhi-110091.

Sir.

This has a reference to your outdoor diary letter No. 11941 dated 29/01/2025, on the subject cited above. In this connection, it is to inform you that premises was inspected by the officers concerned of this department on 21/02/2025 to ascertain the availability and operability of fire Safety measures laid down in BBL in the presence of Dr. H.S. Kukreja (Owner) and observed that building comprised of Basement + Ground + three upper floors only.

Following shortcomings were observed during time of inspection:

- Fire pump of capacity 1620 LPM (electrical) one diesel pump of capacity 1620 LPM and one Jockey pump of 180 LPM are not provided.
- 2. Under ground water storage tank of 50,000 Ltr. not provided.
- 3. Exit signage/Lift signage not provided.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

OCHECHOR OCHECHOR

Copy to:-

 The Executive Engineer (Bldg), Municipal Corporation of Delhi, Plot No.419, Patparganj Industrial Area, Delhi-110092.