



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001**

23/10/2025

No.F.6/DFS/MS/School/2025/NDZ/ 782

Dated: 23/10/2025

To,

The Manager,
K.V.M Model School,
1/7014, Shivaji Park, Shahdara,
Delhi-110094.

Sub:- Regarding renewal of Fire Safety Certificate r/o K.V.M Model School at 1/7014, Shivaji Park, Shahdara, Delhi-110032.

Sir,

This is in reference to your email Id. kvmmmodelschool@gmail.com dated 29/08/2025 on the subject cited above. In this connection, it is to inform you that officer concerned of this department has visited the school on dated 19/09/2025 in presence of Sh. Sunil Chadha and observed that the shortcomings as communicated earlier vide letter No. F.6/DFS/MS/School/2022/NDZ/635 dated 10/10/2022 (copy enclosed) have not been complied yet.

In view of the above, Fire Safety Certificate cannot be considered at this stage. You are requested to rectify the shortcomings communicated vide above mentioned letter under intimation to this office for further action.

Yours faithfully,

Encl:- As above


23/10/2025
(Dr. S. K. TOMAR)

**DY. CHIEF FIRE OFFICER
DELHI FIRE SERVICE**

Copy to:-

The Dy. Director of Education,
B-Block, Yamuna Vihar, Delhi- 110053

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001

No. F.6/DFS/MS/School/2022/NDZ/ 635

Dated 10/10/22

To,

The Manager,
K.V.M Model School,
1/7014, Shivaji park, Shahdara,
Delhi-110032.

Sub:- Regarding Issuance Fire Safety Certificate r/o K.V.M. Model School located at 1/7014, Shivaji Park, Shahdara, Delhi-110032.


Sir,

This is in reference to your letter No. nil dated 21/07/2022 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection of the above mentioned School from fire safety point of view on dated 06/09/2022 in presence of Mr. Sunil Kumar, Manager. The school is running on ground plus one upper floor of the building comprised of ground plus two upper floors. Following shortcomings were observed during the time of inspection.

1. The width of staircase shall be 1.50 meter or an additional staircase of 0.75 meter shall be required.

In view of the above, the building cannot be considered for issuance of Fire Safety Certificate at this stage. Therefore, you are requested to provide the above mentioned fire safety arrangements under intimation to this office for further course of action.

Yours faithfully


(S.K. DUA)

DY. CHIEF FIRE OFFICER
DELHI FIRE SERVICE

o/c
2 -

Copy to:-

1. The Dy. Director of Education
B-Block, Yamuna Vihar,
Delhi-110053