

C/41

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No.F.6/DFS/MS/School/2025/NDZ/895

Dated: 14 / 07 / 2025

FIRE SAFETY CERTIFICATE

Certified that the M/s St. Lawrence Public School located at A-K Facility Center, Opp.-LIC Colony, Dilshad Garden, Delhi-110095, building comprised of Basement, Ground, first floor & Temporary rooms on Terrace (Second Floor) but school is running on Basement, Ground and First Floor only, owned / occupied by St. Lawrence Public School, was issued FSC vide letter No. F6/DFS/MS/School/2022/NDZ/866 Dt. 08/08/2022. The school building was re-inspected by the officer concerned of this department on 02/07/2025 in presence of Mrs. Sunita Dhingra (Voice Principal) and observed that all the Fire Prevention and Fire Safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with D.O.E. Circular No. 262-362 Dated 17/01/2005 issued by Director of Education and that the building is fit for occupancy class "Educational" (Group-B) with effect from 14 / 07 / 2025 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010.

Issued on 14/07/2025 at New Delhi by.

(ATUL GARG)
DIRECTOR

DELHI FIRE SERVICE

Copy to :-

1. The Principal, St. Lawrence Public School, A-K Facility Center, Opp.-LIC Colony, Dilshad Garden, Delhi-110095.
2. The Dy. Director of Education, B-Block, Yamuna Vihar, Delhi-110053.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided their in shall be maintained in good working conditions at all times.
2. Loss of life or property due to non-functional fire safety measure shall be at the responsibility of the Management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
6. "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
7. At present Basement is being used for storage/music purpose.
8. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in.

INSPECTION REPORT

1. Name & address of the building: St. Lawrence Public School,
A-K Facility Center, Opp.-LIC Colony, Dilshad Garden,
Delhi-110095.
2. Building is comprised of : Basement, Ground, First floor & Temporary rooms on
Terrace (Second Floor).
3. Type of Occupancy : Educational
4. Type of Case : Renewal
5. Details of previous NOC : F6/DFS/MS/School/2022/NDZ/866 Dt. 08/08/2022
6. Fire Safety directives Letter No.: D.O.E. Circular No. 262-362 Dated 17/01/2005
7. Date of inspection : 02/07/2025
8. Name of the Inspecting Officer : D.O. (E.D.)
9. Name and designation of Officer from the building side : Mrs. Sunita Dhingra (Voice Principal)
10. Year of Construction : 2006
11. Applicant's letter No. : Nil dt. 17/06/2025

S. No	Minimum Standards on fire prevention and fire safety U/R 33	Circular Requirement	Provided at Site	Remarks
1	Access to building	6.0 M	7.0 M	MR
	• Road width	N/A	N/A	N/A
	• Gate width	N/A	N/A	N/A
	• Width of internal road	N/A	N/A	N/A
2	Number, Width, Type and Arrangement of Exits			
	a. Number of Staircases	02 Nos.	02 Nos.	MR
	• Upper Floor	N/A	N/A	N/A
	• Basement			
	b. Width of Staircases	1.50 M	1.68 M & 1.53 M	MR
	• Upper Floor	1.50 M	1.68 M & 1.53 M	MR
	• Basement			
	c. Protection of exits	N/A	N/A	N/A
	• Fire check door	N/A	N/A	N/A
	• Pressurization			
	d. No. of continuous staircases to terrace	01 Nos.	01 Nos.	MR
	e. Width of Corridor	1.50 M	1.73 M	MR
	f. Door size	1.0 M	1.10 M	MR
3	Compartmentation			
	• Fire check Door	N/A	N/A	N/A
	• Sealing of electrical Shafts	N/A	N/A	N/A
	• Fire rating of Shaft Door	N/A	N/A	N/A
	• Water Curtain	N/A	N/A	N/A
	• Fire Dampers	N/A	N/A	N/A
4	Smoke Management System			
	• Basement	N/A	N/A	N/A
	• Upper Floor	N/A	N/A	N/A
5	Fire Extinguishers			
	• Total Numbers	10 Nos.	10 Nos.	MR
	• Types	ABC & Co2	ABC & Co2	MR
	• IS Marking	ISI Marked	ISI Marked	MR

2/18

6	First-aid-Hose Reels			MR
	Total numbers of each floor	01 Nos.	01 Nos.	MR
	• Length of hose reel hose	30 M	30 M	MR
	• Nozzle diameter	05 mm	05 mm	MR
7	Automatic fire detection and alarming system			N/A
	• Type of detectors	N/A	N/A	N/A
	• Location of main panel	N/A	N/A	N/A
	• Location of repeater panel	N/A	N/A	N/A
	• Alternate source of power	N/A	N/A	N/A
8	MOEFA	N/A	N/A	N/A
9	Public address System	N/A	N/A	N/A
10	Automatic Sprinkler System			MR
	• Basement	Required	Provided	N/A
	• Upper Floor	N/A	N/A	N/A
	• Sprinkler above false Ceiling	N/A	N/A	N/A
11	Internal Hydrants			N/A
	• Size of rise/down-comer	N/A	100 mm	N/A
	• Number of Hydrants per Floor	N/A	01 Nos.	N/A
	• Hose Box	N/A	01 Nos.	N/A
12	Yard Hydrants			N/A
	• Total number of Hydrants	N/A	N/A	N/A
	• Hose Box	N/A	N/A	N/A
13				
	• Ground Level			N/A
	➤ Discharge of main Pump	N/A	N/A	N/A
	➤ Head of Main Pump	N/A	N/A	N/A
	➤ Number of main Pumps	N/A	N/A	N/A
	➤ Jockey pump output	180 LPM	180 LPM	MR
	➤ Jockey pump head	40 MH	40 MH	MR
	➤ Standby pump output	N/A	N/A	N/A
	➤ Standby pump head	N/A	N/A	N/A
	➤ Auto starting/Manual stopping	Required	Provided	MR
	➤ Pump house access	N/A	N/A	N/A
	• Terrace Level			
	➤ Discharge of pump	450 LPM	450 LPM	MR
	➤ head of the pump	40 MH	40 MH	MR
	➤ Power supply	Required	Provided	MR
	➤ Auto Starting of pump	Required	Provided	MR
14	Captive Water Storage for Fire Fighting			
	• Underground tank capacity	N/A	N/A	N/A
	➤ Draw-off connection	N/A	N/A	N/A
	➤ Fire service inlet	N/A	N/A	N/A
	➤ Access to tank	N/A	N/A	N/A
	• overhead Tank capacity	5,000 Ltrs.	5,000 Ltrs.	MR
15	Exit Signage	Required	Provided	MR


2/19

16	Provision of Lifts			
	• Pressurization of Lift Shaft	N/A	N/A	N/A
	• Pressurization of Lift lobby	N/A	N/A	N/A
	• Communication in lift car	N/A	N/A	N/A
	• Firemen's grounding switch	N/A	N/A	N/A
	• Lift Signage	N/A	N/A	N/A
17	Standby power supply	N/A	N/A	
18	Refuge Area			N/A
	• Total area	N/A	N/A	N/A
	• Location	N/A	N/A	
19	Fire Control Room			N/A
	• Detector system panel	N/A	N/A	N/A
	• Flow switch panel	N/A	N/A	N/A
	• PA system panel	N/A	N/A	N/A
	• Battery backup	N/A	N/A	N/A
	• Building floor plans	N/A	N/A	N/A
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	

Note:- Building comprised of Basement, Ground, First floor & Temporary rooms on Terrace (Second Floor) but Management has given an undertaking placed at C-39 that they will not use second floor for school purpose in any case. FSC is recommended for Ground & First Floor only.

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, The Fire Safety Certificate issued vide letter no. F6/DFS/MS/School/2022/NDZ/866 Dt. 08/08/2022 has grant under D.O.E. Circular No. 262-362 Dated 17/01/2005 is recommended.


 Signature of the Inspecting Officer
 Name : Ashok Kumar Jaiswal
 Designation : D.O. (East. Div.)

By C.F.O. (NDZ)

King
04/08/25

C.F.O.
9/11/2025

Director

11/07/21
N/Sel