




No. F6/DFS/MS/EH/SZ/2025/ 394

Dated: 21 / 11 / 2025

FIRE SAFETY CERTIFICATE

Certified that the M/s Le Cantine (A Unit of Sister Food Craft Private Limited) Situated at Pro. 301 & 301A, Second floor, DLF Promenade Mall, Vasant Kunj, New Delhi – 110070 in a building comprised of Two tier Basements, Lower Ground floor and Upper Ground floor and 02 upper floor owned/occupied by A Unit of Sister Food Craft Private Limited was issued earlier Fire Safety Certification vide letter No. F6/DFS/MS/EH/2022/SZ/346 dated 12/12/2022. The premises was re-inspected by the officer concerned of this department on 07/11/2025 in presence of Mr. Rajender Kumar (Liaison Manager) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in the accordance with rule 33 of Delhi Fire Service Rules, 2010 and that the building is fit for occupancy class Group - D “Assembly Building” (Restaurant running at Second floor only) with effect from 21 / 11 / 2025 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010.

Issued on 21/11/2025 at New Delhi by.


(A.K. Malik)
Dy. Chief Fire Officer
o/c Delhi Fire Service

Copy to: -

1. The Commissioner, MCD Civic Center, New Delhi, w.r.t.- MCD portal ID - 2025102814428 dated 28/10/2025.
2. Mr. Rajender Kumar, M/s Le Cantine (A Unit of Sister Food Craft Private Limited) Situated at Pro. 301 & 301A, Second floor, DLF Promenade Mall, Vasant Kunj, New Delhi – 110070.

Conditions for the validity of Fire Safety Certificate

1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry
2. All the means of escape shall be kept free of all the type of obstruction all the time.
3. All the employees shall be acquainted with the use and maintenance of all fire equipment's and method of smooth and speedy safe evacuation of occupants in case of emergency.
4. All the firefighting equipment's shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
7. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

INSPECTION REPORT

1	Name & address of the building	M/s Le Cantine (A Unit of Sister Food Craft Private Limited) Situated at Pro. 301 & 301A, Second floor, DLF Promenade Mall, Vasant Kunj, New Delhi - 110070.		
2	Building is comprised of	Two tier Basements, LGF, UGF & 2 nd upper floor		
3	Type of occupancy	Assembly Building Group - D (Restaurant)		
4	Type of case	Renewal Case		
5	Details of previous FSC	F6/DFS/MS/EH/2022/SZ/346 dated 12/12/2022		
6	Fire safety directives letter no.	Nil		
7	Date of inspection	07/11/2025		
8	Name of the inspecting officers	Yashwant Singh Meena, A.D.O/BCP		
9	Name of the designation of officer from the building side	Mr. Rajender Kumar (Liaison Manager)		
10	Year of construction	2005	FSC has been issued to DLF Promenade mall vide letter no. F.6/DFS/MS/Mall/2025/SZ/483 dated 15/09/2025.	
11	Applicant's letter no.	MHA Application ID No. 2025102814428 dated 28/10/2025		
S. No	Minimum standard of fire prevention and fire safety U/R 33	BBL/NBC-2005 Requirement	Provided at site	Remarks MR/NMR
1.	Access to Building: FSC No. F.6/DFS/MS/Mall/2025/SZ/483 dated 15/09/2025 of Promenade Mall			
	A Road width	Restaurant within DLF Promenade Mall	As above	MR
	B Gate width		As above	N/A
	C Width of internal road		As above	N/A
2.	Number, Width, Type and Arrangement of Exits:			
	A Number of staircases	Provided & Maintained by DLF Promenade Mall		
	a Upper floor	02 nos.	As above	MR
	b Basement	N/A	As above	MR
	B Width of staircases	Provided & Maintained by DLF Promenade Mall		
	a Upper floor	1.5 mtr.	As above	MR
	b Basement	N/A	As above	N/A
	C Protection of exits	Provided & Maintained by DLF Promenade Mall		
	a Fire check door	Required	As above	MR
	b Pressurization	N/A	As above	N/A
	D No. of continuous staircases to terrace	Required	As above	MR
	E Width of corridor	N/A	N/A	N/A
	F Door size	2m/1m	2m & 1.38m	MR
3.	Compartmentation: Provided & Maintained by DLF Promenade Mall			
	A Fire check door	Required	As above	MR
	B Sealing of electrical shafts	Required	As above	MR
	C Fire rating of shaft door	N/A	As above	N/A
	D Water curtain	N/A	As above	N/A
	E Fire dampers	N/A	As above	N/A
4.	Smoke Management System: Provided & Maintained by DLF Promenade Mall			
	A Basement	30 ACPH	N/A	N/A
	B Upper floor	12 ACPH	Provided	MR

5. Fire Extinguisher:					
	A	Total numbers	Required ABC & CO ₂ ISI Marked	06 nos.	MR
	B	Types		ABC & CO ₂	MR
	C	ISI marking		Provided	MR
6 First-Aid-Hose Reel: Provided & Maintained by DLF Promenade Mall					
	A	Total numbers of each floor	One 30 m 5 mm	As above	MR
	B	Length of hose reel hose		As above	MR
	C	Nozzle diameter		As above	MR
7 Automatic Fire Detection and Alarming System: Provided & Maintained by DLF Promenade Mall					
	A	Type of detectors	Required	As above	MR
	B	Location of main panel	Required	As above	MR
	C	Location of repeater panel	N/A	As above	N/A
	D	Alternate source of power	Required	As above	MR
	E	Hooter's Location	Required	As above	MR
8	MOEFA:		Required	Provided	MR
9	Public Address System:		N/A	Provided	N/A
10 Automatic Sprinkler System: Provided & Maintained by DLF Promenade Mall					
	A	Basement	N/A	As above	N/A
	B	Upper floor	Required	Provided in rest.	MR
	C	Sprinkler above false ceiling	N/A	As above	N/A
11 Internal Hydrants: Provided & Maintained by DLF Promenade Mall					
	A	Size of riser/down-comer	Required	As above	MR
	B	Number of hydrants per floor	Required	As above	MR
	C	Hose box	Required	As above	MR
12 Yard Hydrants:					
	A	Total number of hydrants	N/A	As above	N/A
	B	Hose box	N/A	As above	N/A
13 Pumping Arrangements: Provided & Maintained by DLF Promenade Mall					
1 Ground level					
	A	Discharge of main pump	N/A	4500 LPM	N/A
	B	Head of main pump	N/A	70 mtrs.	N/A
	C	Number of main pumps	N/A	02 nos.	N/A
	D	Jockey pump out put	N/A	180 LPM	N/A
	E	Jockey pump head	N/A	70 mtrs.	N/A
	F	Standby pump out put	N/A	4500 LPM	N/A
	G	Standby pump head	N/A	70 mtr	N/A
	H	Auto starting /manual stopping	N/A	Provided	N/A
	I	Pump House Access	N/A	Provided	N/A
2 Terrace Level Provided & Maintained by DLF Promenade Mall					
	A	Discharge of pump each block	450 LPM	As above	MR
	B	Head of the pump	40 m	As above	MR
	C	Power supply	Required	As above	MR
	D	Auto starting of pump	Required	As above	MR

M/s Le Cantine (A Unit of Sister Food Craft Private Limited) Situated at Pro. 301 & 301A, Second floor, DLF Promenade Mall, Vasant Kunj, New Delhi - 110070.

14	Captive Water Storage for Fire Fighting:		Provided & Maintained by DLF Promenade Mall	
	A	Underground tank capacity	N/A	4,60,000 Ltr.
	B	Draw-off connection	N/A	Provided
	C	Fire service inlet	Required	Provided
	D	Access to tank	N/A	Provided
	E	Overhead tank capacity	20,000 liters	30,000 liters
15	Exit Signage:		Required	Provided
16	Provision of Lifts:		Provided & Maintained by DLF Promenade Mall	
	A	Pressurization of lift shaft	N/A	As above
			N/A	As above
	B	Pressurization of lift lobby	N/A	As above
	C	Communication in lift car	N/A	As above
	D	Firemen's grounding switch	N/A	As above
	E	Lift signage	N/A	As above
17	Standby Power Supply:		Required	Provided
18	Refuge Area:			
	A	Total area	N/A	N/A
	B	Location	N/A	N/A
19	Fire Control Room:		Provided & Maintained by DLF Promenade Mall	
	A	Detector system panel	N/A	As above
	B	Flow switch panel	N/A	As above
	C	PA system panel	N/A	As above
	D	Battery backup	N/A	As above
	E	Building floor plans	N/A	As above
20	Special Fire Protection systems for protection of special Risks, if any:			N/A

The fire protection system was randomly checked and tested and was found functional at the time of inspection. Further, Fire Safety Certificate has already been issued to Mall vide letter No. F.6/DFS/MS/Mall/2025/SZ/483 dated 15/09/2025.

Keeping In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the rules of Directorate of Education the FSC issued vide letter no. F6/DFS/MS/EH/2022/SZ/346 dated 12/12/2022, renewal under Rule 35 of the Delhi Fire Service rules 2010, is recommended to be renewed.

Date of Deemed Compliance is 29/11/25

Signature of the Inspecting Officer
Name: - Yashwant Singh Meena
Designation: - ADO/ BCP

D.O/S

13/11/25
Ravinder Singh

02/12/25

A. K. MALIK
Principal Director

A. K. MALIK
my. CFS (SZ)

my. CFS to Dm.

18/11/25