

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001**



No. F6/DFS/MS/2025/School/ 139

Dated: 11/02/2025

FIRE SAFETY CERTIFICATE

Certified that the Little Star Convent School located at Khasra No. 56/1/10, Parasram Enclave, Burari, Delhi-110084 comprised of Ground & first floor owned/ occupied by Little Star Convent School was issued Fire Safety Certificated by this department vide letter no. F6/DFS/MS/School/2021/WZ/1068 dated: 24.12.2021. The premises was inspected by the officer concerned of this department on 28.01.2025 in presence of Mr. S.K. Tyagi (Manager) and observed that all the fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements of circular issued by Director of Education vide letter no 3298-3398 dated 01.03.2011 and the building/ premise is fit for occupancy class "Group B Educational (School)" with effect from11. .02. 2.25 for a period of three years, subject to compliance of the conditions mentioned below:

Copy to: -

1. The Deputy Director of Education, GNCT of Delhi, Zone-VII, District North Lucknow Road, Timarpur, Delhi – 110054.

2. The Manager, Little Star Convent School located at Parasram Enclave, Burari, Delhi-110084.

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.

3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

4. All the staff members must know the correct method of operation of firefighting system.

5. The owner / occupier shall submit a declaration every year in Form "K" provided in the first available The form Rules 2010. Service of Delhi Fire http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

INSPECTION REPORT

: Little Star Convent School located at Khasra No. 56/1/10, Parasram 1. Name & address of the building

Enclave, Burari, Delhi-110084

: Ground & first floor only 2. Composition of building

: Educational Type of Occupancy

: Renewal 4. Type of Case

: F6/DFS/MS/School/2021/WZ/1068 dated: 24.12.2021 Details of previous NOC

: Director of Education Circular dated 01.03.2011 Fire Safety directives letter No

: 28.01.2025 7. Date of inspection

Name of the Inspecting Officers : ADO (RN)

9. Name and designation of officers

: Mr. S.K. Tyagi (Manager) from the building side

: 2002/ 2013 10. Year of Construction

	Applicant's letter No. : Letter No. Minimum Standards on fire prevention and fire safety U/R 33	Requirements as per Rule 35 (6)	Provided at site	Remarks MR/NMR		
	Access to building		TOP IN	MR		
	Road width	6m	6m	estate to		
	Gate width	NA	4.5m	NA		
	Width of internal road	NA	NA	NA		
	Number, Width, Type & Arrangement of E	Exits				
	a. Number of staircases					
		02	03	MR		
	Upper FloorsBasements	NA	NA	NA		
	• Daschients					
	b. Width of staircases • Upper Floors	1.50m	1.50m & 1.08m each	MR		
	Basements	NA	NA NA	NA		
	c. Protection of exits					
	Fire check door	NA	NA	NA		
	Pressurization	NA	NA	NA		
	d. No. of continuous staircases to terrace	NA	NA	NA		
	e. Width of Corridor	NA	NA	NA		
	f, Door Size	01m	01m	MR		
3	Compartmentation.					
	Fire check door	NA	NA	NA		
	Sealing of electrical shafts	NA	NA	NA		
	Fire Rating of shaft door	NA	NA	NA		
	Water Curtain	NA	NA	NA		
	Fire Dampers	NA	NA	NA		
4	Smoke Management System.					
	Basements	NA	NA	NA		
	Upper floors	Required	Natural Ventilated	MR		
5	Fire Extinguishers					
	Total numbers	08nos	12nos	MR		
	• Types	ABC/CO2	ABC—8, Co2-4	MR		
	ISI marking	ISI Marked	Yes	MR		

	First-Aid Hose Reels.				
	Total numbers on each floor NA NA				
×	Length of hose reel hose	NA NA	NA	NA	
		Actional	NA NA	NA NA	
7	Nozzle diameter Automotic fire detection and clarming sy	NA NA	INA		
f)	Automatic fire detection and alarming system.				
	Type of detectors	NA NA	NA NA	NA	
	Location of Main Panel	NA NA	NA NA	NA	
	Location of Repeater Panel		NA NA	NA	
	Alternate source of power	NA	52199451	NA	
	Hooters' Location	NA	NA NA	NA NA	
8	MOEFA	NA		NA NA	
9	Public Address System.	NA	NA	NA	
10	Automatic Sprinkler System.				
E.	Basement	NA	NA	NA	
	Upper Floor	NA	NA	NA	
	Sprinkler above false ceiling	NA	NA	. NA	
11	Internal Hydrants				
11	The state of the s	NA NA	NA	NA	
	Size of riser/down-comerNumber of hydrants per floor	NA	NA	NA	
	Hose Box	NA	NA	NA	
2	Yard Hydrants.		p=17 + 15	P	
	Total number of hydrants	NA	NA	NA	
	Total number of hydranics Hose Box	NA	NA	NA	
3	Pumping Arrangements.	4			
-	Ground Level			K	
	Discharge of main Pump	N/A	N/A	N/A	
	> Head of Main pump	N/A	N/A	N/A	
	> Number of main pumps	N/A	N/A	N/A	
	➢ Jockey Pump out put	N/A	N/A	N/A	
	Jockey pump head	N/A	N/A	N/A	
•	➤ Standby Pump out put	N/A	N/A	N/A	
	➤ Standby Pump Head	N/A	N/A	N/A	
	 Auto Starting/ Manual stopping Pump House Access 	C1259/25/34H	neweers.	47.00.22.947.	
	Terrace level	N/A	N/A	N/A	
-	➤ Discharge of pump	NA	N/A	NTA	
	➤ Head of the pump	NA NA	N/A N/A	NA NA	
1	➤ Power Supply	N/A	N/A		
	➤ Auto Starting of pump	N/A		N/A	
10	Captive Water Storage for fire fighting.	N/A	P	N/A	
	Underground tank capacity	NA			

			MISS					
	>	Draw-off connection	NA	NA	NA			
	>	Fire service inlet	NA	NA	NA			
	>	Access to tank	NA	NA NA	NA			
	•	Overhead Tank capacity	NA	N/A	NA			
5	Exit S	ignage.	N/A	N/A	N/A			
6	Provision of Lifts.							
		Pressurization of Lift Shaft	N/A	N/A	N/A			
		Pressurization of Lift lobby	N/A	N/A	N/A			
	•	Communication In lift Car	N/A	N/A	N/A			
	•	Fireman's Grounding Switch	N/A	N/A	N/A			
	•	Lift Signage	N/A	N/A	N/A			
17	Stan	dby power supply	N/A	N/A	N/A			
18	Ref	Refuge Area.						
		> Total Area	N/A	N/A	N/A			
	1	Location	N/A	N/A	N/A			
19	Fir	Fire Control Room						
		Detector System Panel	N/A	N/A	N/A			
		Flow Switch Panel	N/A	N/A	N/A			
		PA System Panel	N/A	N/A	N/A			
		Batter backup	N/A	N/A	N/A			
		 Building Floor Plans 	N/A	N/A	N/A			
20	Sp Pr	pecial Fire Protection Systems for otection of special Risks, if any:	N/A	N/A	N/A			

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in director of education Circular dated 01.03.2011, it is recommended to renewal of fire safety certificate issued vide this department letter of even no. F6/DFS/MS/School/2021/WZ/1068 dated: 24.12.2021.

DO (NW)

04/04/2021

by 000 (w2) - MR

do

Director 12 45

Anyth

conf -. P.T.O.

Signature of the Inspecting Officer

Name :-C.L. Meena Designation:- ADO/RN