C/134 C



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001



No. F6/DFS/MS/2025/Residential/ 450

Dated: 26 /08 /2025

FIRE SAFETY CERTIFICATE

Azadpur, New Delhi comprised of A to G seven blocks & B,C,D,E blocks, 03 tier Basement + stilt + 19 upper floors, A block 03 tier basement + stilt + 07 upper floor, F block 03 tier basement + stilt + 11 upper floors & G block 03 tier basement + stilt + 05 upper floors owned/occupied by M2K Victoria Gardens (M/s Negolice India Ltd.) was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/CGHS/2020/236 dated 03/07/2020. The premises was reinspected by the officers concerned of this department on 11/07/2025 in the presence of Mr. Ravinder Kr. Swain have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premise is fit for occupancy class "Residential Sub Group A-4" with effect from 2.6.08. Delah.... for a period of Five years, in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010

Issued on 26 08 2025 at New Delhi

Virendra Singh Chief Fire Officer Delhi Fire Service

Copy to: -

1. The Authorized Signatory, M2K Victoria Gardens, (M/s Negolice India Ltd.), Ring Road Azadpur, New Delhi.

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape shall be kept free from any type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipment and method of smooth and speedy safe evacuation of occupants in case of emergency

3. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seem during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities. This Fire Safety Certificate is valid only for permanent building structure as per plan.

5. This fire safety certificate may not be treated in any case of regularizations of unauthorized construction/unauthorized use of land or activities, if any.

6. Basement shall not be used for any other purpose except as specified in UBBL, subject to permission from concerned local authority.

7. The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on the official website of Delhi Fire Service i.e. www.dfs.delhigovt.nic.in.

8. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

INSPECTION REPORT

: M2K Victoria Gardens, (M/s Negolice India Ltd.) Ring Road, Azadpur, Name & address of the building 1

New Delhi-110033.

Type of Occupancy : Residential 2

Type of Case : Renewal 3

: F.6/DFS/MS/CGHS/2020/236 Details of previous NOC dated 03/07/2020 (Residential Building) 4

Fire Safety directives letter No : F 6/DFS/MS/BP/2011/1102 dated 03/06/2011 & 5 : F.6/DFS/MS/CGNS/2012/4284 date 16/11/2012

: 11/07/2025 Date of inspection A block-3 B+S+7 upper floor 6

Name of the Inspecting Officers : ADO (RN) B block-3 B+S+19 upper floor

Name and designation of officers C block-3 B+S+19 upper floor

: Sh. Ravinder Kr. Swain (GM) D block-3 B+S+ 19 upper floor from the building side E block -3 B+S+19 upper floor

Year of Construction : Letter No. Nil Dated 18/06/2025 F block-3 B+S+11 upper floor 10. Applicant's letter

		G block-3 B+S+5 upper							
	Minimum Standards on fire prevention and fire safety U/R 33	NBC/ BBL Requirements	Provided at site	Remarks MR/NMR					
1	Access to building								
	Road width	45m	45m	MR					
	Gate width	06m	6.79m	MR					
	Width of internal road	06m	06m	MR					
2	Number, Width, Type & Arrangement of Exits								
.5	a. Number of staircases								
	Upper Floors	A Block-2 B Block-2 C block-2 D Block-2 E Block-2 F Block-2 G Block-2	02 02 02 02 02 02 02 02	MR					
	Basements (common for all the blocks)	13 S/C from basement III to II nd basement to G.F	13 S/C from basement III to II nd basement to G.F	MR					
100	b. Width of staircases								
	Upper Floors	Tower's A,B,C,D,E,F,G 1.25m each	Provided	MR As per letter no 4284 Date 16/11/2012					
	20 20	12 S/C of 1.25m Each & 02 ramp	Provided	MR					
	Basements	Eden & 02 1mm-F		1 10					
	c. Protection of exits	Lift lobby S/C electric & in each block	Lift lobby S/C electric & in each block	MR					
	Fire check door	Required	Provided	MR					
	Pressurization	06	12-	MR					
	d. No. of continuous staircases to terrace	1.50m	Provided	MR					
	e. Width of Corridor f. Door Size	01mtr	Provided	MR					
3	Compartmentation.								
	Fire check door	Required	Provided	MR					
	Sealing of electrical shafts	Required	Provided	MR					
	Fire Rating of shaft door Water Curtain	Required Required in basement	Provided Provided	MR					
	Fire Dampers	NA	NA	NA					



+	Smoke Management System. Basements 30 a/c per hour Provided					
	Basements	30 a/c per hour	Natural Ventilated	MR		
	 Upper floors 	12 a/c per hour	Natural Ventuates			
	Fire Extinguishers					
	Total numbers	220DCP+99WCO2	Provided	MR		
	• Types	ABC & Co2	Provided			
	ISI marking	Yes	Yes	MR		
6	First-Aid Hose Reels.					
	Total numbers on each floor	01each blocks	01	MR MR		
	Length of hose reel hose	30m	30m			
	Nozzle diameter	5mm	5mm	MR		
7	Automatic fire detection and alarming system					
	Type of detectors	Required	Provided	MR		
	Location of Main Panel	GF	Provided	MR		
	Location of Repeater Panel	NA	NA	NA		
	Alternate source of power	Required	Provided	MR		
	Hooters' Location	NA	NA	NA		
8	MOEFA	Required	Provided	MR		
9	Public Address System.	Required	Provided	MR		
10	Automatic Sprinkler System.					
	Basement	Required	Provided	MR		
	Upper Floor	Required in all	Provided	MR		
	Sprinkler above false ceiling	blocks NA	NA	NA		
11	Internal Hydrants					
(0.20.0	Size of riser/down-comer	100mm & 150mm	Provided	MR		
-	Number of hydrants per floor	01each blocks & 01	Provided	MR		
	Hose Box	01each blocks & 01	Provided	MR		
12	Yard Hydrants.	community centre		1		
	Total number of hydrants	21	Provided	MR		
	Hose Box	01	Provided	1		
13	Pumping Arrangements.	E-1	Tiovided	MR		
	Ground Level		1 10 0			
	The state of the s		a transplant	+		
	➤ Discharge of main Pump	2850 LPM	Provided	MR		
	➤ Head of Main pump	120m	Provided	MR		
	> Number of main pumps	02	Provided	MR		
-	> Jockey Pump out put	180 LPM	Provided			
10	➢ Jockey pump head	120m	Provided	MR		
	The second secon		- 10 AIGEG	MR		
1	Standby Pump out put	Required	Provided	MIK		

	- >	Standby Pump Head	Required	Provided	MR
T	1 1	Auto Starting/ Manual stopping	Required	Provided	MR
	>		Required	Provided	MR
	>				
	• 7	Terrace level	900 LPM for A & G	Provided	MR
		Discharge of pump	block	NA	NA
		> Head of the pump	NA	Provided	MR
			Required	1	MR
		Power SupplyAuto Starting of pump	Required	Provided	MIN
1				· - 11.17	100
14	Captive	Water Storage for fire fighting.	1,00,000 LTR	1,00,000 LTR	MR
	•	Underground tank capacity	Required	Provided	MR
	>	Draw-off connection	Required	Provided	MR
	>	Fire service inlet	***	Provided	MR
4	>	Access to tank	Required A & G tower 25,000 LTR each, B,C,D,E,F, tower-	Provided	MR
		Overhead Tank capacity	10,000 LTR. each blocks	Provided	MR
			Required	-11	
15		gnage.		Provided	MR
16	Provis	ion of Lifts.	Required	11 151.5	MR
	•	Pressurization of Lift Shaft	Required	Provided	
		Pressurization of Lift lobby	Required	Provided	MR
		Communication In lift Car	1000	Provided	MR
		Fireman's Grounding Switch	Required	Provided	MR
	•		Required		MR
	8.€	Lift Signage	Required	Provided DG Set	
17	Stan	dby power supply			
18	Refu	ge Area.	N/A	N/A	N/A
		> Total Area	N/A N/A	N/A	N/A
		Location	N/A		
19	Fire	Control Room	Required	Provided	MR
		Detector System Panel	No.	Provided	MR
		Flow Switch Panel	Required	Provided	MR
		PA System Panel	Required	Provided	MR
		A Company of the Comp	Required	and the second second	MR
2		Batter backup	Required	Provided	NA
		Building Floor Plans	NA	NA	1363
2	0 Sp	ecial Fire Protection Systems for		A. W. A.	
	Pr	otection of special Risks, if any:	de the	850	<u> </u>
		ale shall the	de	and the same of	
		1.0	p Angles & Kray		

The fire protection systems provided in the building were tested/ checked and found in good working order at the time of inspection. The observations/ shortcomings issued and communicated vide this department letter of even no. F6/DFS/MS/2025/Residential/226 dated 15/05/2025 have been compiled by the management.

Keeping in view of satisfactory compliance of the minimum standards on fire prevention and fire safety required under the rules and fire safety guidelines issued vide letter of even no. 1102 dated 03.06.2011 and 4284 dated 16.112012, it is recommended to renew Fire Safety Certificate vide this department letter of even no. 236 dated 03/07/2020 under rule 37 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer Name: - C.L. Meena Designation:- ADO/RN

OCFO/.3 Dated.2 Sv,

1- In above/soild complex two types occupancies (i.e. one Assembly/Community Centre and another Residential) are there.

2. The five safety certificate for assembly building was renewed an dated of. 05. 2023 after three years.

3. The above said recommended renewal is for Residential building for which earlier FSC was issued on 03.07. 2020 as placed at C-106 (Flag-A) after fine years. 4. Submitted as desired bleasp. 12/81/2025 The details dray be

Principal Director toriefed to one, how can a brildie is beforested and isend file for desperent time validing (even the the Rules provide this time validity, West about the occupancy?

12206725

Sir, in caupieur,
There are two buildings, are is residential
Accountre i.e. Assembly. By this way the validty of FSC for both is different.

Submitted blease. Principal Directar Di