## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/GH/NDZ/2025/ 414

Dated:- 11/06/2025

DIRECTOR

## FIRE SAFETY CERTIFICATE

Certified that the Guest House owned/occupied by Madhu Surana located at 9 BT 111 & 9 BT 112, Subhash Gali, Vishwas Nagar, Shadhara, Delhi-110032, comprised of basement (vacant) stilt (parking) ground floor to 3<sup>rd</sup> floor (09 guest rooms at each floor) Total 32 guest rooms only owned/occupied by M/. Madhu Surana, was issued Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/GH/2022/NDZ/357 dated 26/07/2022. The said premise was re-inspected by the officer concerned of this department on 05/06/2025 in the presence of Ms. Madhu Surana (Owner) and found that the said guest house building has deemed complied with the fire prevention and fire safety requirements in accordance with the Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises/building is fit for occupancy class "Residential" Group A-1 with effect from 11 06 2025 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010 printed below.

Issued on 1106 2025 at New Delhi by

Copy to:-

- 1. The Commissioner, Municipal Corporation of Delhi, Civic Centre, Minto Road, New Delhi-110002:in r/o computer IDs no. 2025060309551 & 2025051208327, to ensure occupancy as detailed above and deviation, if any.
- 2. The Joint Commissioner of Police (Lic), 1st Floor, Licensing Unit, Police Station, Defence Colony,
- 3. The Authorized Signatory, Madhu Surana (Guest House), 9 BT 111 & 9 BT 112, Shubhash Gali, Vishwas Nagar, Shadhara, Delhi-110032.

## Conditions for the validity of fire safety certificate:-

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional if fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /
- 6. All comments / directions of licensing Department shall always be permitted and followed.
- 7. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.

## INSPECTION REPORT

: Guest House owned/occupied by Madhu Surana, 1. Name & address of the building located at 9 BT 111 and 9 BT 112, Subhash Gali,

Vishwas Nagar, Shahdara, Delhi-110032

: Residential, Group A (Guest House) the building is 2. Type of Occupancy

comprised of basement (vacant) stilt (parking), ground floor to 3rd floor (09 guest rooms at each

floor) Total 32 guest rooms only

: Renewal 3. Type of Case

: F6/DFS/MS/GH/2022/NDZ/357 dated 26/07/2022 4. Details of previous NOC

5. Fire Safety directives Letter No. : Nil

: 05/06/2025 6. Date of inspection 7. Name of the Inspecting Officer

: Aman Kumar Lathar, ADO (JWP)

8. Name and designation of Officer

: Ms. Madhu Surana (Owner) from the building side

: 2019 Year of Construction

: 2025060309551 & 2025051208327

A Vo	pplicant's online application no. :  Minimum standards on fire	NBC (Part-IV) Requirements	Provided at site	Remarks MR/NMR			
Vo	prevention and fire safety U/R 33   Requirements   Site						
1	Access of building	06 m	09 m	MR			
	Road width	NA	NA	NA			
×	Gate width	NA	NA	NA			
	Width of internal road	Service Service					
2.	Number, width, Type & Arrangements of exits						
	a. Number of staircases	02	Provided	MR			
	<ul> <li>Upper floors</li> </ul>	02	Provided	MR			
	Basements	02					
1	b. Width of staircases	1.5 m each	1.5 m each	MR			
	Upper floors	1.5 m each	1.5 m & 1.8 m	MR			
	Basements	1.5 III cacii	1.5 11 00 210				
	c. Protection of exits	and the	Provided	MR			
	<ul> <li>Fire check door</li> </ul>	Required	NA	NA			
1	<ul> <li>Pressurization</li> </ul>	NA		MR			
	d. No of continuous	02	Provided	IVIIX			
	staircase to terrace e. Width Of Corridor	1.5 m (single loaded)	Provided	MR			
	f. Door Size	1.0 m	Provided	MR			
В.	Compartmentation						
Ť.	Fire check door	Required	Provided	MR			
	<ul> <li>Sealing of electrical shafts</li> </ul>	NA	NA	NA			
-	Fire Rating of shaft door	NA	NA	NA			
	Water Curtain	NA	NA	NA			
1	Fire Dampers	NA	NA	NA			
4.	Smoke managements System						
	Basements	Required	Provided	MR			
	Upper floors	Required	Natural Ventilation	MR			
5.	Fire Extinguishers						
	Total numbers	12 nos.	14 nos.	MR			
	Types	ABC & CO <sub>2</sub>	Provided	MR			
	IS marking	Required	Provided	MR			

	the second secon	TOTAL TOTAL		— XX
_	First – Aid Hose Reels	01	Provide	d N
6.	Total numbers on each in	30 m	Provide	- A
1.1	Length of hose reel hose		Provide	
		05 mm	=753	
	Nozzle diameter  Automatic fire detection and alar	ming system	Provided	M
7.	Type of detectors		N/A	N/A
	Location of Main Panel	N/A	N/A N/A	N/A
	Location of Repeater Pan	el N/A		N/A
	Alternate source of power	r N/A	N/A	N/A
	Hooters' Location	N/A	N/A	MR
		Required	Provided	N/A
8.	MOEFA	N/A	N/A	IN/A
9.	Public Address System		- 1.1	MR
10.	Automatic Sprinkler System	Required	Provided	N/A
	Basements  Floor  Flor  Floor  F	N/A	NA	N/A
	Upper Floor     Section shows false	N/A	N/A	14/21
	Sprinkler above false     siling			
	ceiling Internal Hydrants:	117	7 11 1	MR
11.	Size of riser/down-comer	100 mm	Provided	MR
l l	Number of hydrants per	01 no.	Provided	TVIIC .
	floor		Provided	MR
	Hose Box	01 no.	FIOVILLE	1
12.	Yard Hydrants	<u> </u>	N/A	N/A
12.	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	IVA	
13.	Pumping Arrangements:			
-	<ul> <li>Ground Level</li> </ul>	N/A	N/A	N/A
	<ul> <li>Discharge of main pump</li> </ul>	N/A	N/A	N/A
	> Head of main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
- 1	> Jockey pump out put	N/A	N/A	N/A
	<ul><li>Jockey pump head</li><li>Standby Pump out put</li></ul>	N/A	. N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	> Auto Staring/Manual	N/A	N/A	N/A
	stopping		NI/A	N/A
	Pump House Access	N/A	N/A	14/21
- 1	Terrace level	2001	Provided	MR
	Discharge of pump	900 lpm	Provided	MR
-	> Head of the pump	40 m	Provided	MR
	> Power supply	Required	Provided	MR
	Auto starting of pump	Required	11011111	
4. (	<ul> <li>Under ground tank</li> </ul>	ng: N/A	N/A	N/A
	capacity	N/A	N/A	N/A
	> Draw off connection	N/A	NA	N/A
	Fire service inlet	N/A	N/A	N/A
	Access to tank  Access to tank	15,000 ltrs.	25,000 ltrs.	MR
	Overhead Tank capacity	Required	Provided	MR
_	xit Signage			7/4
. P1	rovision of Lifts	N/A	N/A	N/A
	<ul> <li>Pressurization of Lift Shaft</li> <li>Pressurization of lift lobby</li> </ul>	N/A	N/A	N/A N/A
	> Communication in lift Car	N/A	N/A	N/A
	> Fireman's Grounding	N/A	N/A	IN/ 47
	Switch		DT/A	N/A
	➤ Lift Signage	N/A	N/A Provided	MR
1005		Required	Provided	
O4-	ndby power supply			

15.	Refuge Area	- 10 M		
7	➤ Total area			
	➤ Location	N/A	NUA	
19.	Fire control room	N/A	N/A	N/A
	Detector system now 1		N/A	N/A
	Flow Switch Panel	N/A	111	
	PA System Panel	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Special Fire Protection	N/A	N/A	N/A
20.		N/A	N/A	N/A
	for Protection of	N/A	N/A	N/A
	for Protection of special Risks, if any;		N/A	N/A
	The fire protection such			P

The fire protection systems provided in the building were checked and found functional at the time of inspection. Shortcoming issued vide letter no. F6/DFS/MS/GH/NDZ/2025/184 dated 17/04/2025 found rectified.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no. F6/DFS/MS/GH/2022/NDZ/357 dated 26/07/2022, renewal under rule 37 of the Delhi Fire Service Rule 2010, is recommended.

Accordingly, DFA is put up for approval & signature please.

ED) 106/225

Aman Kumar Lathar ADO (JWP)

by cro (D)29

LIVE

2 Golsons

Directory

Bylon

Su

F.T. letter is mit-up for your vignature M.

Directory

AMOGWP)