

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001



No. F6/DFS/MS/2025/School/ 329

Dated: 02/04/2025

FIRE SAFETY CERTIFICATE

Certified that the Maharana Pratap Global School located at J-Block, Gali No-1, Swaroop Nagar, Delhi-110042 comprised of lower ground, upper ground & 02 upper floors owned/ occupied by the Maharana Pratap Global School have complied with the fire prevention and safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and verified by the officer concerned of Fire Service on 22.03.2025 in the presence of Mr. Surject Singh and that the building/premises is fit for occupancy Class "Group B Educational (School)" with effect from 0.2 64. 2025. for a period of three years, in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 02 04 2025 at New Delhi

(Atúl Garg) Director

Ph:-011-23414000

Copy to: -

- 1. The Deputy Director of Education, Zone-VII, District North Lucknow Road, Timarpur, Delhi – 110054.
- 2. The Chairmen, Maharana Pratap Global School located at J-Block, Gali No-1, Swaroop Nagar, Delhi-110042.

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.

3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

4. All the staff members must know the correct method of operation of firefighting system.

5. The owner / occupier shall submit a declaration every year in Form "K" provided in the first Delhi Fire Service Rules The 2010. form is available http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-

2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

"The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

INSPECTION REPORT

1. Name & address of the building : Maharana Pratap Global School at J-Block, Gali No-1, Swaroop

Nagar, Delhi-110042.

2. Type of Occupancy

: Educational

Composition of building

: Lower Ground, Upper Ground & 02 upper floors only

4. Type of Case

5. Details of previous NOC

Fire Safety directives letter No

: Nil : Nil

7. Date of inspection

: 22.03.2025

8. Name of the Inspecting Officers : ADO (RN)

9. Name and designation of officers

from the building side

: Mr. Surjeet Singh

10. Year of Construction

: 2023-24

	Minimum Standards on fire prevention and fire safety U/R 33	UBBL/ NBC Part- IV Requirements	Provided at site	Remarks MR/NMR			
	Access to building.						
OK C	Road width	06m	06m	MR			
	Gate width	4.50m	4.50m	MR			
	Width of internal road	NA	NA	NA			
	Number, Width, Type & Arrangement of Exits.						
	a. Number of staircases						
	Upper Floors	02	02	MR			
	Basements	NA	NA	NA			
	b. Width of staircases			1 10			
s	Upper Floors	1.50m each	1.60m & 1.50m	MR			
	Basements	NA	NA	NA			
	c. Protection of exits						
	Fire check door	NA	NA	NA			
	Pressurization	NA	NA .	NA			
	d. No. of continuous staircases to	02	02	MR			
	terrace e. Width of Corridor	1.50m	2.30m	MR			
	f. Door Size	1.20m	Provided	MR			
3	Compartmentation.						
	Fire check door	- NA	NA	NA			
	 Sealing of electrical shafts 	NA	NA	NA			
	Fire Rating of shaft door	NA	NA	NA			
	Water Curtain	NA	NA	NA			
	Fire Dampers	NA	NA	NA			
4	Smoke Management System.						
	Basements	NA	NA	NA			
	Upper floors	Required	Natural Ventilation	MR			
5	Fire Extinguishers.	0 0					
	Total numbers	08nos	Provided	MR			

	M						
	• Types	ABC/CO2	Provided	M			
	ISI marking	ISI Marked	Provided	M			
	First-Aid Hose Reels.						
	 Total numbers on each floor 	01	Provided	M			
	 Length of hose reel hose 	30m	Provided	M			
	Nozzle diameter	5mm	Provided	М			
	Automatic fire detection and alarming system.						
-	m f detectors	NA	NA	N			
	Location of Main Panel	NA	NA	N			
		NA	NA	N			
	Location of Repeater Panel	NA	NA	N			
	Alternate source of power	NA	NA	N			
	Hooters' Location	NA NA	NA	N			
	MOEFA	NA NA	NA NA	N			
	Public Address System.	INA					
0	Automatic Sprinkler System.	NA NA	NA	N			
	Basement	NA NA	NA	- N			
	Upper Floor		NA	N			
	 Sprinkler above false ceiling 	NA	NA	***			
1	Internal Hydrants.		NA	N			
_	 Size of riser/down-comer 	NA	NA NA	N			
	Number of hydrants per floor	NA	NA NA	N			
	Hose Box	NA					
12	Yard Hydrants.	NA I	NA	N			
	 Total number of hydrants 	NA	NA	N			
	Hose Box	NA	NA NA	100			
13	Pumping Arrangements.						
15	Ground Level	III g					
	> Discharge of main Pump	N/A	N/A	N/			
	> Head of Main pump	N/A	N/A	N/			
	> Number of main pumps		N/A	N/			
	Jockey Pump out put	N/A	N/A	N/			
	> Jockey pump head	N/A	N/A	N/			
,v	➤ Standby Pump out put	N/A	N/A	- N/.			
	> Standby Pump Head	N/A		N/.			
	> Auto Starting/ Manual	N/A	N/A				
	stopping > Pump House Access	N/A	N/A	N/.			
	Terrace level						
	➤ Discharge of pump	450 LPM	Provided	MI			
	➤ Head of the pump	40m	Provided	MI			
	➤ Power Supply	Required	Provided	MI			
	> Auto Starting of pump	Required	Provided	MI			
14	Captive Water Storage for fire fightin Underground tank capacity	g. NA	NA	NA.			
	onderground tank capacity	A 34-A	98,000	_			

				NA	NA
1	>	Draw-off connection	NA	NA .	NA
	۶	Fire service inlet	NA	NA	NA
	A	Access to tank	NA TR	Provided	MR
	•	Overhead Tank capacity	10,000 LTR	Provided	MR
	Exit Si	gnage.	Required	1000	
-	Provision of Lifts.			N/A	N/A
' †	Pressurization of Lift Shaft	N/A	N/A	N/A	
		Pressurization of Lift lobby	N/A	N/A	N/A
h		Communication In lift Car	N/A	N/A	N/A
		Fireman's Grounding Switch	N/A	(5)VV/5500	N/A
		Lift Signage	N/A	N/A Provided for corridor	MR
17	Stand	lby power supply	Required	lighting & staircase	
		ge Area.		21/4	N/A
18			N/A	N/A	N/A
	7	Total Area Location	N/A	N/A	INZ
3020	1	The Control of the Co		I N/A	N/A
19	Fire	Control Room Detector System Panel	N/A		N/A
		Flow Switch Panel	N/A	N/A	
		PA System Panel	N/A	N/A	N/A
		Batter backup	N/A	N/A	N/A
		Building Floor Plans	N/A	N/A	N/A
20	Spec	ial Fire Protection Systems for ection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition at the time of inspection. The management has complied all the shortcomings issued and communicated by this department vide letter of even no. F6/DFS/MS/2024/School/837

Keeping in view of the substantial compliance of the minimum standards on fire prevention and dated 19.12.2024. fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting

Name :-C.L. Meena

Designation:- ADO/RN

D.B. Mukharjee (DO/NW)

Aprif En cont -.. P.To

1 2 L 6 ? 0 ć ć è 1, 2

00 0 1191-NW Dated 27/08/25.

2 C