




No. F6/DFS/MS/Audi./2025/SZ/ 572

Dated 24/10/2025

**FIRE SAFETY CERTIFICATE**

Certified that Main Auditorium & Mini Auditorium I & II, located at Baha'i House of Worship Lotus Temple Road, Bahapur, Kalaji, New Delhi - 110019 comprised of Ground floor only was issued FSC by this department vide letter no. F6/DFS/MS/Audi./2022/SZ/441 dated 30/09/2022. The premise was re-inspected by the officer concerned of this department on 10/10/2025 in the presence of Mr. Jay Prakash (Manager) and found that the said Auditorium have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building is fit for (03 Auditorium, Seating Capacity, Main Audi 408 Mini Audi-1 & II -70 each) occupancy Group "D" Assembly Building (Auditorium) with effect 24/10/2025 for a period of three years in accordance with rule 36 unless renewed under rule 37 of sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 24/10/2025 at New Delhi by

  
(A.K. Malik)  
Dy. Chief Fire Officer  
o/c Delhi Fire Service

Copy to:-

1. The commissioner, MCD, Civic Centre New Delhi.
2. Baha'i House of Worship Lotus Temple Road, Bahapur, Kalkaji, New Delhi-110019.

**Conditions for the validity of Fire Safety Certificate**

1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry
2. All the means of escape shall be kept free of all the type of obstruction all the time.
3. All the employees shall be acquainted with the use and maintenance of all fire equipment's and method of smooth and speedy safe evacuation of occupants in case of emergency.
4. All the firefighting equipment's shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in).



## INSPECTION REPORT

01.	Name & address of the building	Main Auditorium & Mini Auditorium 1 & II, Baha'i House of Worship Lotus Temple Road, Bahapur, Kalkaji, Delhi - 110019.		
02.	Building is comprised of	Ground floor only, (03 Auditorium, Seating Capacity, Main Audi 408 Mini Audi-1 & II -70 each)		
03.	Type of occupancy	Assembly Building		
04.	Type of case	Renewal		
05.	Details of previous FSC	F6/DFS/MS/Audi./2022/SZ/441 dated 30/09/2022		
06.	Fire safety directives letter no.	F6/DFS/MS/BP/92/1744-B dated 24/09/1992.		
07.	Date of inspection	10.10.2025.		
08.	Name of the inspecting officers	Yashwant Singh Meena ADO (BCP)		
09.	Name of the designation of officer from the building side	Mr. Jay Prakash (Manager)		
10.	Year of construction	1994		
11.	Applicant's letter no.	Outdoor dairy no. 6502 dated 26/09/2025		
S.No	Minimum standard of fire prevention and fire safety U/R 33	Old NOC Requirement	Provided at site	Remarks MR/NMR
01.	<b>Access to Building:</b>			
	A Road width	Required	12 mtrs	MR
	B Gate width	Required	Provided	MR
	C Width of internal road	Required	Provided	MR
02.	<b>Number, Width, Type and Arrangement of Exits:</b>			
	A Number of staircases			
	a Upper floor	N/A	N/A	N/A
	C Basement	N/A	N/A	N/A
	B Width of staircases			
	a Upper floor	N/A	N/A	N/A
	C Basement	N/A	N/A	N/A
	C Protection of exits			
	a Fire check door	N/A	N/A	N/A
	b Pressurization	N/A	N/A	N/A
	D No. of continuous staircases to terrace	Required	Provided	MR
	E Width of corridor	N/A	N/A	N/A
	F Door size	2.0 mtr.	6 nos in main audi & 2 nos each in mini Audi's	MR
03.	<b>Compartmentation:</b>			
	A Fire check door	N/A	N/A	N/A
	B Sealing of electrical shafts	N/A	N/A	N/A
	C Fire rating of shaft door	N/A	N/A	N/A
	D Water curtain	N/A	N/A	N/A
	E Fire dampers	N/A	N/A	N/A
04.	<b>Smoke Management System:</b>			
	A Basement	N/A	N/A	N/A
	B Upper floor	N/A	N/A	N/A
05.	<b>Fire Extinguishers</b>			
	A Total numbers	16 nos.	Provided	MR
	B Types	ABC/W.CO <sub>2</sub> /CO <sub>2</sub>	6/5/5	MR
	C ISI marking	Required	Provided	MR



170012					
06.	First-Aid-Hose Reel:				
	A	Total numbers of each floor	02 nos	Provided	MR
	B	Length of hose reel hose	30 m	Provided	MR
	C	Nozzle diameter	05 mm	Provided	MR
07.	Automatic Fire Detection and Alarming System:				
	A	Type of detectors	Smoke & Heat	Provided	MR
	B	Location of main panel	Required	Ground floor	MR
	C	Location of repeater panel	N/A	N/A	N/A
	D	Alternate source of power	Required	Provided	MR
	E	Hooters	Required	All Floors	MR
08.	MOEFA:		Required	Provided	MR
09	Public Address System:		Required	Provided	MR
10.	Automatic Sprinkler System:				
	A	Basement	N/A	N/A	N/A
	B	Ground & Above Floors	Required	Provided	MR
	C	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants:				
	A	Size of riser/down-comer	150 mm	Provided	MR
	B	Number of hydrants per floor	02 nos	Provided	MR
	C	Hose box	02 nos	Provided	MR
12.	Yard Hydrants:				
	A	Total number of hydrants	N/A	N/A	N/A
	B	Hose box	N/A	N/A	N/A
13.	Pumping Arrangements:				
1	Ground level				
	A	Discharge of main pump	1620 LPM	N/A	N/A
	B	Head of main pump	55 m	N/A	N/A
	C	Number of main pumps	02 nos	N/A	N/A
	D	Jockey pump out put	180 LPM	N/A	N/A
	E	Jockey pump head	55 m	N/A	N/A
	F	Standby pump out put	N/A	N/A	N/A
	G	Standby pump head	N/A	N/A	N/A
	H	Auto starting /manual stopping	Required	Provided	MR
	I	Pump house access	Required	Provided	MR
2	Terrace Level				
	A	Discharge of pump	N/A	N/A	N/A
	B	Head of the pump	N/A	N/A	N/A
	C	Power supply	N/A	N/A	N/A
	D	Auto starting of pump	N/A	N/A	N/A
14.	Captive Water Storage for Fire Fighting:				
	A	Underground tank capacity	1,00,000 ltrs	Provided	MR
	B	Draw-off connection	Required	Provided	MR
	C	Fire service inlet	Required	Provided	MR
	D	Access to tank	Required	Provided	MR
	E	Overhead tank capacity	20,000 ltrs	Provided	MR



Main Auditorium, Bahapur, Kalkaji, Delhi-110019. N/A

Shri Yashwanth Lotus Temple

15.	Exit Signage:	Required	Provided	MR
16.	Provision of Lifts:			
A	Pressurization of lift shaft	N/A	N/A	N/A
B	Pressurization of lift lobby	N/A	N/A	N/A
C	Communication in lift car	N/A	N/A	N/A
D	Firemen's grounding switch	N/A	N/A	N/A
E	Lift signage	N/A	N/A	N/A
17.	Standby Power Supply:	Required	Provided(DG)	MR
18.	Refuge Area:			
A	Total area	N/A	N/A	N/A
B	Location	N/A	N/A	N/A
19.	Fire Control Room:			
A	Detector system panel	Required	Provided	MR
B	Flow switch panel	N/A	N/A	N/A
C	PA system panel	Required	Provided	MR
D	Battery backup	Required	Provided	MR
E	Building floor plans	Required	Provided	MR
20.	Special Fire Protection systems for protection of special Risks, if any:	Required	Provided	MR

The fire protection systems provided in the building were text checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no. F6/DFS/MS/Audi./2022/SZ/441 dated 30/09/2022, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Signature of the Inspecting Officer  
 Name: - Yashwant Singh Meena  
 Designation: - ADO/BCP

DO/\$D

*[Signature]*  
 18/10/25

*[Signature]*

*[Signature]*  
 12/10/25  
**A. K. MALIK**  
 Principal Director

*[Signature]*  
 Dy. CFO (SZ)

*[Signature]*  
 Dy. CFO to Secy.  
 17/10/25

DO/\$D

*[Signature]*  
 21/10/25  
**A.K. MALIK**

*[Signature]*  
 22/10/25