

c/10  
SPM

7  
आज़ादी का  
अमृत महोत्सव

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No. F6/DFS/MS/School/WZ/2025/ 113

Dated: 17/02/2025

To,

The Principal,  
M.C. Primary (Co-Ed), School,  
Ganesh Pura, Tri Nagar,  
New Delhi – 110035.  
mcpsganeshpura@gmail.com

Sub: - Inspection report in r/o. M.C. Primary (Co-Ed), School, Located at Ganesh Pura, Tri Nagar, New Delhi – 110035.(School ID- 13554003)

Sir,

With reference to your letter no. Nil dated 10/12/2024, received through outdoor diary no. 10311 dated 13/12/2024 of this department, on the subject cited above. In this connection, it is to inform you that the said premises was inspected by the officer concerned of this department on 10/02/2025, in the presence of Sh. Kalil Kant Sharma (Incharge) to see the functioning of the fire safety arrangements/equipment's provided in the building.

During inspection, it has been observed that the said school is comprised of Ground + Three Upper Floor, Fire Safety Arrangements such as, Fire Extinguishers, First Aid Hose Reels, Terrace pump, etc. are provided. However, following shortcomings were observed: -

1. If one stair is less than 1.5 mtr other should not less than 0.75 mtr & both stairs should reach upto terrace.
2. First Aid Hose Reel is provided but not functional.
3. Terrace fire pump of 450lpm provided but not functional.
4. Overhead tank capacity of 4000ltrs is provided against the requirement of 10,000ltrs.
5. Exit signage's are not provided.

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(Atul Garg)  
Director

Copy To:-

1. The Directorate of Education Old Secretariat Delhi – 110054.

SPM  
11/2/2025