



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**



No: F.6/DFS/MS/School/2025/WZ/225

Dated: 16/04/2025

To,  
The Principal,  
M.C. Primary Co-ed School,  
J.J. Wazirpur Old, B Block,  
J.J. Colony, Wazirpur, Delhi-110052.

Sub: - Regarding issuance of Fire Safety Certificate in r/o M.C. Primary Co-ed School J.J. Wazirpur Old, (ID- 1354132) located at B- Block, J.J. Colony, Wazirpur, Delhi- 110052.



Sir,  
This has reference to your email id dated 10.03.2025 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 08.04.2025 to see the to see the compliance of the requisite fire safety measures. Smt. Puneeta (In-charge) was present at the time of inspection.

During the course of inspection it was observed that school building is comprised of 02 Blocks (Ground plus Two upper floors & Activity Hall at Ground floor). Your request for issuance of FSC is rejected due to the following shortcomings:-

1. Gate width found 3 m against the required width of 4.5 m.
2. There is only 01 staircase provided against the required 02 staircases up to the terrace.
3. First aid hose reels found provided but not functional.
4. Terrace level pump found provided but not functional.
5. Overhead tank of 2500 ltrs also connected with domestic line is provided against the required capacity of 10,000 ltrs exclusively for fire fighting pump.
6. Exit signage's not provided.
7. Electrical meter and panel installed under the staircase has to be removed to a safer place.

You are advised to rectify the above-mentioned shortcomings under intimation to this department.

Yours Faithfully

  
15/04/2025  
(Virendra Singh)  
Chief Fire Officer  


Copy to:-

1. Director of Education, MCD, Civic Centre, New Delhi.