



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001



C/22

No: F.6/DFS/MS/School/2025/WZ/ 508

Dated: 09/06/2025

To,

The Principal,
M.C. Primary School,
J.J. Sawda, B Block,
Delhi-110081.

Sub: - Regarding issuance of Fire Safety Certificate in r/o M.C. Primary School located at B Block,
J.J. Sawda, Delhi- 110081.

Sir,

This has reference to your form 'I' received through outdoor diary no. 871 dated 22.04.2025 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 04.06.2025 to see the to see the compliance of shortcomings issued vide letter no. F6/DFS/MS/School/2022/WZ/149 dated 29/03/2022. Sh. Dinesh (In-charge) was present at the time of inspection.

During the course of inspection it was observed that school building is comprised of Ground plus Two upper floors & Activity Hall at Ground floor. Your request for issuance of FSC is rejected due to the following shortcomings:-

1. Width of staircase found 1.5 m & 1.25 m against the required width of 1.5 m each.
2. Three doors in activity hall having 1.20 m each found provided against the requirement of two doors of 1.5 m width each.
3. First aid hose reels not provided.
4. Terrace level fire pump of 450 lpm discharge capacity not provided.
5. Overhead tank of 10,000 ltrs capacity not provided.
6. Electrical panel installed under the staircase has to be removed to a safer place.

You are advised to rectify the above-mentioned shortcomings under intimation to this department.

Yours Faithfully


(Virendra Singh)
Chief Fire Officer
Delhi Fire Service


Copy to:-

1. Director of Education, MCD, Civic Centre, New Delhi.


5/6