



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

F.6/DFS/MS/2025/SZ/203 No.

Dated: 24 /04 /2025

FIRE SAFETY CERTIFICATE

Certified that the building of Maccure Hospital situated at Plot No. 1, Block-B, Pocket-10, Sector-13, Opp. Iskcon Temple, Dwarka, New Delhi-110075, comprised of Basement, Stilt, Ground & 03 upper floors, owned/occupied by M/s Maccure Hospital, have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officers concerned of this department on dated 09/04/2025 in the presence of Dr. Sanjay Kumar Jain (Director) and that the said building/premises is fit for occupancy class "Institutional, Group-C" (Hospital) with effect from 24/04 /2025 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS Rules, 2010.

Issued on 94/64/2025 at New Delhi by

Copy to: -

- 1. The Director General of Health Services, F-17, Arjun Gali, Karkardooma, Anand Vihar,
- 2. The Executive Engineer-I (Bldg.) HQ, Municipal Corporation of Delhi, 9th Floor, Civic Centre, Minto Road, New Delhi-110002
- 3. Dr. Sanjay Kumar Jain (Director), Maccure Hospital situated at Plot No. 1, Block-B, Pocket-10, Sector-13, Opp. Iskcon Temple, Dwarka, New Delhi-110075

Conditions for the validity of Fire Safety Certificate:

- All the means of escape/entry/exit shall be kept free from any obstruction. 1.
- All the fire safety arrangement provided therein shall be maintained in good working conditions 2. at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management. 3.
- All the staff members must know the correct method of operation of firefighting system.
- The basement shall be used as per the provisions of BBL. 4.
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-5. 2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 6. 'J' [sub rule (1) of rule37] along with a copy of this Certificate, prior to its expiry.
- The owner/occupier shall submit a declaration every year in form "K" provided in the first 7. schedule of Delhi Fire Service Rules, 2010. The form is available on www.dfs.delhigovt.nic.in

/		INSPECTION REPORT				
	H	Name & Address of the Building	M/s Maccure Hospital at Plot No. 1, Block-B Pocket-10, Sector-13, Opp. Iskcon Temple, Dwarka, New Delhi-110075			
1	1	Type of Occupancy	Institutional Building "C" (Hospital)			
	1	Building Comprised of	Basement, Stilt, Ground + 03 Upper Floors			
	1	Type of Case	New			
	1	Details of Previous NOC	Nil			
	-}-	Fire Safety Directives Letter No	F.6/DFS/MS/BP/2024/410 dated 10/12/2024			
		Date of Inspection	09/04/2025			
		Name of the Inspecting Officers	(1) Control of the Co			
	9	Name & Designation of Officers from the building side				
	10	Year of construction	2022 (N/79)			
	111	Applicant letter No.	100 000 00	06/03/2025 received thr	ough	
	111	Applicant letter No.	No. Nil dated 26/03/2025 received through outdoor diary No. 15032 dated 26/03/2025			
	\$	Minimum standards on Fire	NBC / UBBL	Provided at Site I	Remarks	
	No.	Prevention and Fire Safety U/R 33	Requirement		IR/NMR	
4		Access to Building.				
		Road width	09 mtr	30 mtr	MR	
		Gate width	5 mtr	Abuts on road	MR	
		Width of internal road	N/A	N/A	N/A	
	-	Number, width, type and arrangeme	ents of exits.			
	1	a. Number of Staircase				
		> Upper floors	02 Nos	02 Nos	MR	
		> Opper noors > Basement floor	02 Nos	02 Nos	MR	
		b. Width of Staircase	V=			
		> Upper floors	2m & 1.5m	2m x 1, 1.5m x 1	MR	
		> Basement floor	2m & 1.5m	2m x 1, 1.5m x 1	MR	
		c. Protection of exits				
		> Fire check door	Required	Provided	MR	
		> Pressurization	Required	Provided	MR	
		d. No. of continuous staircase to terrace	02 Nos	Provided	MR	
		e. Width of corridor	2.40 mtr	Provided	MR	
		f. Door size	2m / 1.5m	Provided	MR	
	1	Compartmentation.		u de la companya de		
		Fire check door.	Required	Provided	MR	
		Sealing of electrical shafts.	Required	Provided	MR	
		Fire rating of shaft door.	2 Hr	Provided	MR	
	-	Water curtain	N/A	N/A	N/A	
		Fire dampers.	Required	Provided	MR	
		Smoke Management system.				
	4.	Smoke Management system.		D 11 1F 1 F.	MR	
	4.	Basement	12 ACPH	Provided Exh. Fan	- 100 MARK TAKE	
	4.	Basement	12 ACPH 12 ACPH	Exhaust fan/ Natural	MR	
	4.	BasementUpper floors	Section 1		- 100 MARK TAKE	
	5.	Basement	Section 1		- 1000 April 1000	
	5.	Basement Upper floors Fire Extinguishers. Total numbers	12 ACPH	Exhaust fan/ Natural	MR MR	
	5.	Basement Upper floors Fire Extinguishers. Total numbers Types	12 ACPH Required	Exhaust fan/ Natural 22 Nos	MR MR MR	
	5.	 Basement Upper floors Fire Extinguishers. Total numbers Types ISI Marking 	12 ACPH Required ABC/CO ₂	Exhaust fan/ Natural 22 Nos ABC & CO ₂	MR MR MR	
	5.	 Basement Upper floors Fire Extinguishers. Total numbers Types ISI Marking First Aid Hose Reels. 	12 ACPH Required ABC/CO ₂ Required	Exhaust fan/ Natural 22 Nos ABC & CO ₂	MR MR MR MR	
	5.	 Basement Upper floors Fire Extinguishers. Total numbers Types ISI Marking 	12 ACPH Required ABC/CO ₂	Exhaust fan/ Natural 22 Nos ABC & CO ₂ Provided	MR	

7	Automatic Fire Detection and Alarming	system.		MD
	Type of detectors (Smoke)	Smoke / Heat	Provided	MR
	Location of Main Panel	Required	Provided	MR
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	Required	Provided	MR
	Hooter's location	Each floor	Provided	MR
	MOEFA	Required	Provided	MR
8.		N/A	N/A	N/A
9. 10.	Public Address System Automatic Sprinkler System	1972	1 100	
10.		Required	Provided	MR
	Duschient	Required	Provided	MR
	Upper floors Sprinkler shows followed:	Required	Provided	MR
11.	Sprinkler above false ceiling Internal Hadrands	Required	Tiovides	
11.	Internal Hydrants.	Deminal	Provided	MR
	Size of Riser / Down-comer Number of Hudenstone State	Required	Provided	MR
	Number of Hydrant per floor Hess have	Required	411 (W. 45.11 (1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0	MR
12.	Hose box. Vard Hydronto	Required	Provided	IVIK
14.	Yard Hydrants.		D (1.1	M
	Total number of hydrants.Hose box.	Required	Provided	MR
13.		Required	Provided	MR
13.	Pumping arrangements. • Ground Level	11.7.1.		
		1600 1 77 6	2222771) (D
	Discharge of main pump.Head of main pump.	1620 LPM 70m	2280 LPM	MR
	Number of main pumps.	One .	Provided Provided	MR MR
	> Jockey Pump output.	180 LPM	180 LPM	MR
	Jockey Pump head.	70m	Provided	MR
	Standby Pump output.	1620 LPM	2280 LPM	MR
	Standby Pump head.Auto Starting/Manual Stopping.	70m	Provided	MR
	> Pump House Access		Provided	MR
	Terrace Level	Required	Provided	MR
	Discharge of pump.	N/A	N/A	NT/A
	➤ Head of pump.	N/A	N/A	N/A
	> Power supply.	N/A	N/A	N/A
	> Auto starting of pump.	N/A	N/A	N/A
14.	Captive water storage for Fire Fighting.	- 1111	N/A	N/A
	Underground tank capacity.	75,000 Ltr.	75,000 Ltr.	MR
	> Draw-off connection.	Required	Provided	MR
	Fire Service Inlet.	Required	Provided	MR
	Access to tank.	Required	Provided	MR
	Overhead tank capacity.	10,000 Ltr.	10,000 Ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts. (Lift is not serving baseme	ent and terminated at	stilt level)	IVIK
	Pressurization of lift shaft.	Required	Provided	MR
	Pressurization of lift lobby.	N/A	N/A	
	Communication in lift car.	Required	Provided	N/A
	Fireman's switch.	Required	12 GHEOLOGICAGE GOOGLO	MF
			Provided	MI
17	Lift signage. Standby Power Sweeter	Required	Provided	MI
	Standby Power Supply	Required	Provided	M
18.	Refuge Area			
	Total area	N/A	N/A	N/
	• Location	N/A	N/A	N/A
		W		

19.	Fire Control Room.			
	Detector system panel.	N/A	N/A	N/A
	 Flow switch panel. 	N/A	N/A	N/A
	PA system panel.	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
-	 Building floor plan 	N/A	N/A	N/A
20.	Special fire protection system for protection of special risk, if any.	Required	Provided	MR

Note: The applicant applied through online mode for completion as advised by this department but the status shows "Completion Rejected" copy attached (C/115) and upon enquiry, the MCD officials informed the applicant that the building already holds a valid Completion Certificate placed at C/122. Hence, the applicant has applied through offline mode for Fire NOC and we may consider the same, if agreed/approved please.

The fire protection systems provided in the building were checked, tested at random and found functional at the time of inspection. In view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules, issue of the fire safety certificate, under rule 35 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for perusal/approval & signature please.

Signature of the Inspecting Officer

Name: Rajender Atwal Designation: DO (SW)

Signature of the Inspecting Officer

Name: Santosh Kumar Designation: ADO (DWK)

CFO(HQ)

Please speak on above note

17 41 2015

Dolsas

1. Spoken with Do on 22.4.2025.

2. Submitted please.

Directar My

22 41 20x

23/4 ADD (D/M

Sir, f.T were is promp frogram &

8 man