FIRE SAFETY CERTIFICATE

Certified that the MCD Pratibha CO-ED Vidyalaya located at Mayur Vihar Phase-2, Pocket – C, Delhi -110091, building comprised Ground plus one upper floor owned/occupied by MCD Pratibha CO-ED Vidyalaya was issued Fire Safety Certificate vide letter No. F6/DFS/MS/School/NDZ/2022/884 dated 11/08/2022. The school building was re-inspected by the officer concerned of this department on 17/06/2025 in presence of Mr. Pragati Nagar (Principal) and observed that all the fire prevention and fire safety requirements in the premises found in good working condition. The premises have therefore deemed complied with the Fire Prevention and Fire Safety requirements in accordance with Circular No. F16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by Director of Education and that the building is fit for occupancy class "Educational Building" (Group-B) with effect from 20/06/2025 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010. Subject to conditions printed below.

ssued on 20/06/2025 at New Delhi by.

DELLII FIRE SERVICE

Copy to:-

1. Dy. Director of Education, B - Block, Yamuna Vihar, Delhi - 110053.

2. The Principal, MCD Pratibha CO-ED Vidyalaya Mayur Vihar Phase-2, Pocket - C, Delhi - 110091.

Conditions for the validity of Fire Safety Certificate

- 1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipment's and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the firefighting equipment's shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- 6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

HIS

		1	HIIS					
1	7	Ja	INSPE	CTION REPORT				
		one & addres	s of the building					
2				Viber Di	O-ED Vidyalaya lo	cated at Mayur		
3	4	uilding is com	prised of	vinai Phase-2, Po	ocket – C. Delhi -1	10091.		
1	T	ype of occupa	ncv	Ground plus one	upper floor			
1	I	ype of case		Educational Building				
5		etails of previ	Olle ESC	Renewal	7			
		Provi	ous r sc	F6/DFS/MS/Scho	ol/NDZ/2022/884	dated		
6	F	re safety direc	ctives letter no.	11/08/2022.	-			
		- J unce	tives letter no.	F.16/Estate/CC/F	re Safety/2011/32	98 to 3398		
7	D	ate of inspecti		dated 01/03/2011				
8	N	ame of the in-	on .	17/06/2025				
9	N	anc of the ins	pecting officers	Yashwant Singh I	Meena ADO (L.N)	i		
	1	aine of the des	ignation of officer	Mr. Pragati Nagar				
10	11 Y	om the buildin	g side					
	Y	ear of construc	nt'a lau		015 B Block			
11	A	oplicant's lette	er no.	Outdoor Dairy No. 2492 dated 06/06/2025				
		Minimum sta	andard on fire	Requirement as	Provided at	Remarks		
S.N	F	revention and	l fire safety U/R	per circular	site	MR/NMR		
0			33		_			
1	A	ccess to Build	ing:					
	A	Road width	and the same	6.0 mtrs.	9.0 mtrs.	MR		
A	B	Gate width		N/A	N/A	N/A		
	C	Width of int	ernal road	. N/A	N/A	N/A		
2	N	ımber, Width	, Type and Arran	gement of Exits:				
	A Number of staircases							
		a Upper flo	or	02 nos	03 nos.	MR		
		c Basement		N/A	N/A	N/A		
	В	Width of sta	ircases		1 1021	1471		
		a Upper flo	or	1.50 mtrs	1.50 mtr. each	MR		
		b Basement		N/A	N/A	N/A		
	C	Protection of			40 n3(0)	1071		
		a Fire check	c door	N/A	N/A	N/A		
		b Pressuriza	ition	N/A	N/A	N/A		
	D		inuous staircases	01 no.	01 no.	MR		
	_	to terrace	100	H ₂	A STATE OF THE REAL PROPERTY.			
	E	Width of cor	ridor	1.5 mtrs.	1.5 mtrs.	MR		
•	_	F Door size		1.0 mtr.	1.0 mtr. M			
3		mpartmentat		Territory Line	Lateral Addition	A. T		
	A	Fire check do	1180 00 00 000	NA	NA	NA		
	B		ectrical shafts	N/A	N/A	N/A		
	C	Fire rating of		N/A	N/A	N/A		
	D	Water curtain		N/A	N/A	N/A		
1	E	Fire dampers		N/A	N/A	N/A		
4	- 1	oke Managen	ient System:	27/4		US 324000		
1	A	Basement Upper floor		N/A	N/A	N/A		
	В	Upper floor	991	N/A	N/A	N/A		

(00 MM

5.	MCD Pratibha Co-ED Vidyalaya located at Mayur Vihar Phase-2, Pocket - C, Nelhi -110091						
	A	Total numbers	Wa -110091				
	B		07 nos.				
	C	Types		07 nos	MR		
6		ISI marking	CO ₂ & ABC	CO ₂ & AB	MR		
0	First-Aid-Hose Reel:		ISI Marked	Provided	MR		
	A	Total numbers of each floor			and the same		
	B	Length of hose reel hose	N/A	N/A	N/A		
	C	Nozzle diameter	N/A	N/A	N/A		
7	Automatic Fire Detection and Alam		N/A	N/A	N/A		
	Automatic Fire Detection and Alarming System: A Type of detectors						
	B	Location of main panel	N/A	N/A	N/A		
	C	Location of repeater panel	N/A	N/A	N/A		
	D	Alternate source of power	N/A	N/A	N/A		
	E	Hooters	N/A	N/A	N/A		
8		OEFA:	N/A	Provided	N/A		
9	Public Address System:		N/A	N/A	N/A		
10	Automatic Sprinkler System:		N/A	N/A	N/A		
1/2	A	Basement System:	I start and the	Section buy as an	1		
	В	Upper floor	· N/A	N/A	N/A		
	C	Sprinkler above false ceiling	- N/A	N/A	N/A		
11	Internal Hydrants:		N/A	N/A	N/A		
	·A	Size of riser/down-comer		155 10 11			
	В	Number of hydrants per floor	N/A	N/A	N/A		
	C	Hose box	N/A	N/A	N/A		
12	Yard Hydrants:		N/A	N/A	N/A		
	Taru Hydrants:						
	B	Total number of hydrants Hose box	N/A	N/A	N/A		
13		Self Constant and	N/A	N/A	N/A		
No. 1875	Pumping Arrangements:						
1	Ground level						
	A	Discharge of main pump	N/A	N/A	N/A		
	B	Head of main pump	N/A	N/A	N/A		
	C	Number of main pumps	N/A	N/A	N/A		
	D	Jockey pump out put	N/A	N/A	N/A		
	E	Jockey pump head	N/A	N/A	N/A		
	F	Standby pump out put	N/A	N/A	N/A		
	G	Standby pump head	N/A	N/A	N/A		
	H	Auto starting /manual stopping	N/A	N/A	N/A		
	I Pump house access		N/A	N/A	N/A		
2	Terrace Level						
	A Discharge of pump		N/A	N/A	N/A		
	B	Head of the pump	N/A	N/A	N/A		
	C	Power supply	N/A	N/A	N/A		
	D	Auto starting of pump	N/A	N/A	N/A		

(C)

14	Captive Water Storage for Fire Fighting:					
1	A	Underground tank capacity	N/A	N/A	N/A N/A	
	B Draw-off connection C Fire service inlet		N/A N/A	N/A N/A	N/A N/A	
1						
1	$\overline{\mathbf{D}}$	Access to tank	N/A	N/A N/A	N/A	
ŀ	E	Overhead tank capacity	N/A	N/A N/A	N/A	
15	Exit Signage:		N/A	N/A		
	Provision of Lifts:			NI/A	N/A	
-	A Pressurization of lift shaft		N/A	N/A N/A	N/A	
ŀ	B	Pressurization of lift lobby	N/A	N/A N/A	N/A	
-	C	Communication in lift car	N/A N/A	N/A N/A N/A	N/A N/A	
-	D	Firemen's grounding switch				
-	E	Lift signage	N/A	N/A	N/A	
17	Sto	ndby Power Supply:	N/A	N/A		
				NI/A	N/A	
18	Refuge Area:		N/A	N/A	N/A	
-	A	Total area	N/A	N/A		
	B Location				N/A	
19	Fir	e Control Room:	N/A	N/A	N/A	
	A	Detector system panel	N/A	N/A	N/A	
	В	Flow switch panel	N/A	N/A	N/A	
	C	PA system panel	N/A	N/A	N/A	
	D	Battery backup	N/A	N/A	N/A	
20	E Building floor plans N/A Special Fire Protection systems for protection of special Risks, if					

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

Keeping in view of the deemed compliance of minimum standards on fire prevention and fire safety measures as required under the Rules the Fire Safety Certificate issued vide letter no. F6/DFS/MS/School/NDZ/2022/884 dated 11/08/2022 under the Circular no F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011, Renewal is recommended.

Signature of the Inspecting Officer

Name: - Yashwant Singh Meena

Designation: - ADO (L.N)

D.O/EAST Discoul

by 00 (NDZ)

18706125

10 G/2015

Dinector/ Mon

Ms cell

JOHN QUE