

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001



No F 6/DFS/MS/2025/School/WZ/1227

Dated: 06/10/2025

FIRE SAFETY CERTIFICATE

Issued on 06 10 2025 at New Delhi

M. K Chattopadhyay Dy. Chief Fire Officer Delhi Fire Service

Copy to: -

1. The Director, Education, North MCD, Civic Center, New Delhi.

2. The Principal, M. C. D. Primary (Co-ed) School, Sector-20, Extension, Rohini, Delhi-86.

Conditions for the validity of Fire Safety Certificate:

- All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

5. This certificate cannot be treated in any case for regularizations of unauthorized construction.

6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months

7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on

8. C-Blk- Ground floor was also found in damaged condition. The school management has repaired.

1. C-Blk- Ground floor was also found in damaged condition. The school management has repaired.

http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/ http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms

INSPECTION REPORT

Name & address of the building: M. C. D. Primary (Co-ed) School, Sector-20, Extension, Rohini,

Delhi-110086.
: Educational

3. Comprised of building
4. Type of Case
5. Comprised of building
6. Comprised of building
7. Comprised of building
8. Comprised of building
8. Comprised of building
9. Comprised of Case
9. Compris

Type of Case
 Details of Previous NOC
 Renewal (School running at 02 blocks Gr. + 01 upper floors only)
 F.6/DFS/MS/2022/School/WZ/626 dated 10.06.2022(for-03 blocks)

Fire Safety directives letter No : Director of Education Cir. dated 01.03.2011

7. Date of inspection : 18.07.2025

8. Name of Inspecting Officer : A.K.Sharma ADO(Rohini)

9. Name and designation of officers

Type of Occupancy

From the building side : Mr. Sachin (Teacher)

10. Year of Construction : 1989

No.	Minimum Standards on fire prevention and fire safety U/R 33		Director of Education Cir. dated 01.03.2011	Provided at site	Remarks MR/NMR
	Acc	ess to building			
		Road width	Accessible	Accessible	MR
		Gate width	Accessible	Accessible	MR
		 Width of internal road 	-NA-	-NA-	-NA-
2.	Nu	mber, Width, Type & Arrangement of	Exits		
	_	Number of staircases	9070		
		Upper Floors	02nos.	02nos.	MR
		Basements	-NA-	-NA-	-NA-
	b.	Width of staircases	THE R.	THE COLUMN	
		Upper Floor	1.5m	A & B-Blk-2.20m	MR
		Basements	-NA-	-NA-	-NA-
	c.	Protection of exits	4000000		
		Fire check door	-NA-	-NA-	-NA-
		Pressurization	-NA-	-NA-	-NA-
	d.	. No. of continuous staircases to terrace	-NA-	-NA-	-NA-
1111	e.		-NA-	-NA-	-NA-
-	f.	. Door Size	1m	1.2m	MR
3.	(Compartmentation			
		Fire check door	-NA-	-NA-	-NA-
		 Sealing of electrical shafts 	-NA-	-NA-	-NA-
1		Fire Rating of shaft door	-NA-	-NA-	-NA-
1		Water Curtain Fire Democra	-NA-	-NA-	-NA-
		Fire Dampers	-NA-	-NA-	-NA-
4.		Smoke Management System	,		
		Basements	-NA-	-NA-	-NA-
		Upper floors	-NA-	-NA-	-NA-
5.		Fire Extinguishers			
-		Total numbers	04nos.	Provided	MR
-1-5	3	• Types	ABC/CO2	ABC/CO2	MR
		IS marking	ISI marked	Yes	MR
6.		First-Aid Hose Reels	NIA		R. II
		Total numbers on each floor Length of hose reel hose	-NA-	-NA-	-NA-
		Nozzle diameter	-NA-	-NA-	-NA-

1.	Automatic fire detection and alarming syste	m		
•	Type of detectors	-NA-	-NA-	-N
	Location of Main Panel	-NA-	-NA-	-N
	Location of Repeater Panel	-NA-	-NA-	-N
	Alternate source of power	-NA-	-NA-	-N
	Hooters' Location	-NA-	-NA-	-N.
8.	MOEFA	-NA-	-NA-	-N.
9.		-NA-	-NA-	-N.
10.	Public Address System	-NA-	-NA-	-147
10.	Automatic Sprinkler System Basement	374	374	1 27
	Ground & Upper Floors	-NA-	-NA-	-N
	Sprinkler above false ceiling	-NA-	-NA-	-NA
11.	Internal Hydrants	-NA-	-NA-	-NA
11.				
	Size of riser/down-comer Number of hydroute and G	-NA-	-NA-	-NA
	Number of hydrants per floor Hose Box	-NA-	-NA-	-NA
12.	Yard Hydrants	-NA-	-NA-	-NA
12.		1	to proceed the	
	 Total number of hydrants Hose Box 	-NA-	-NA-	-NA
13.	Pumping Arrangements	-NA-	-NA-	-NA
	Ground Level	100		
	1	to the second		
	Discharge of main PumpHead of Main pump	-NA-	-NA-	-NA-
	Number of main pumps	-NA-	-NA-	-NA-
	> Jockey Pump out put	-NA-	-NA-	-NA-
	 Jockey pump head Standby Pump out put 	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
	Standby Pump Head	-NA-	-NA-	-NA-
	Auto Starting/Manual Stopping	-NA-	-NA-	-NA-
	Pump House Access	-NA-	-NA-	-NA-
		-NA-	-NA-	
	Terrace level Discharge C	1 = 1 = 7 / 1 = -		-NA-
	Discharge of pumpHead of the pump	-NA-	-NA-	NA
	Power Supply	-NA-	-NA-	-NA-
	Auto Starting of pump	-NA-	-NA-	-NA-
14.	Captive Water Storage for fire fighting	-NA-	-NA-	-NA-
	• Underground tank asset			-1121-
	Diaw-Oil Connection	-NA-	-NA-	-NA-
	Fire service inlet Access to tank	-NA-	-NA-	-NA-
	Overhead Tank capacity	-NA-	-NA-	-NA-
15.	Exit Signage.	-NA-	-NA-	-NA-
16.	Provision of Lifts.	-NA-	-NA-	-NA-
			-NA-	-NA-
	Pressurization of Lift Shaft Pressurization of Lift lobby Communication	-NA-	N	
	Communication In 1:6 G	-NA-	-NA-	-NA-
	riteman's Grounding C	-NA-	-NA-	-NA-
	- Signage	-NA-	-NA-	-NA-
17.	Standby power supply	-NA-	-NA-	-NA-
18.	Refuge Area.	-NA-	-NA-	-NA-
1 :				-NA-

	Total Area Location	-NA-	-NA-	-NA-
·N	Fire Control Room	-NA-	-NA-	-NA-
NA A	Detector System Panel	1		
1	Flow Switch Panel	-NA-	-NA-	-NA-
	PA System Panel	-NA-	-NA-	-NA-
	Battery backup	-NA-	-NA-	-NA-
	Building Floor Plans	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
0.	Special Fire Protection System for Protection of special Risks, if any:	-NA-	-NA-	-NA-
	11 1 1			

Accordingly, the fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

Note:- C-Block comprised of ground floor found in damaged condition. The school management have submitted and an undertaking that they will not use the C-Block.

In view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F.6/DFS/MS/2022/School/WZ/626 dated 10.06.2022 is recommended for renewal of FSC for (A & B Block) under rule 37 of the Delhi Fire Service rules 2010.

Signature of the Inspecting Officer
Name Ajay Kumar Sharma
Designation ADO (Rohini)

Principal Direction

Principal Direction

Put up for little to four pour up for mind pound and synature Means.