

C/28

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI- 110001

No.F6/DFS/MS/School/NDZ/2025/ 427

Dated: 21/05/2025

To

The Principal,
MCD Primary School,
Deputy Ganj Co-Ed,
City SP Zone, New Delhi - 06.

Sub: - Regarding issuance of "Fire Safety Certificate" from fire safety point of view in r/o MCD Primary School, Deputy Ganj Co-Ed, City SP Zone, New Delhi - 06.

Sir,

This has reference to your letter outdoor diary No. 410 dated 09.04.2025 on the subject cited above. In this connection, this is to inform you that the school building was inspected by officer concerned from this department on 15.05.2025 in the presence of Mr. Juned (Attendant) and found that the school building is comprised of ground plus two upper floors. During the inspection, following shortcomings were observed:-

1. One more staircase shall be provided from 1st to 2nd floor.
2. First aid hose reel provided but not functional.
3. Fire pump provided but not functional.
4. Overhead water storage tank found empty.
5. Exit signages are not provided.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management.

Yours faithfully,

(Atul Garg)

Director

Delhi Fire Service

Tel: 011-23414000

Copy to:-

The Director of Education,
Govt. of NCT of Delhi, Old Secretariat, Delhi.

10-6/84
16/5
15/5