GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No. F.6/DFS/MS/School/2025/SZ/ 258

Dated: 19 03 2025

Delhi Fire Service

FIRE SAFETY CERTIFICATE

Certified that the MCD Primary School located at Village Amberhai, Sec-19, Dwarka, New Delhi- 110075, comprised of ground plus two upper floors, owned/occupied by MCD. The school building was inspected by the officer concerned of this department on dated 06.03.2025 in the presence of Ms. Urmil Sherawat (Principal), and found that the building/ premises (ground plus two upper floors) is fit for occupancy class B "Educational Building" with effect from 19 63 2025 for a period of three years in accordance with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010, printed below.

Issued on 19 63 2025 at New Delhi.

Copy to: -

1. Director of Education, MCD, Dr. S.P. Mukherjee Civic Centre, New Delhi- 110002.

2. The Principal, MCD Primary School located at Village Amberhai, Sec 19, Dwarka, New Delhi- 110075.

Conditions for validity of fire safety certificate: -

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.

2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.

3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

4. The trained staff should be available round the clock.

5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.

6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name & address of the building: MCD Primary School at Village Amberhai, New Delhi-110075.

Type of Occupancy Educational

Building comprised of Ground plus two upper floors

Type of Case New Details of Previous NOC N/A Fire Safety directives letter No N/A 7. Date of inspection 07.02.2025

8. Name of Inspecting Officer A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side Mrs. Urmil Sehrawat

10. Year of Construction 2018-19

11. Applicant's letter No. Online email Id amberhaischool197@gmail.com dated 20.12.2024

S. No.		num Standards on fire prevention re safety U/R 33	Requirements	Provided at site	Remarks MR/NMR		
1.	Access to building						
	•	Road width	Accessible 06 m	06 m	MR		
	•	Gate width	4.5 m	Directly accessible from road	MR		
	• 4	Width of internal road	N/A	N/A	N/A		
2.	Number, Width, Type & Arrangement of Exits						
	a. Nu	mber of staircases					
	•	Upper Floors	02 No's	02 No's	MR		
		Basements	N/A	N/A	N/A		
	b. Wi	dth of staircases			557/96		
		Upper Floor	1.50 each	1.50 & 1.80 m	MR		
		Basements	N/A	N/A	N/A		
	c. Pro	tection of exits					
		Fire check door	N/A	N/A	N/A		
		Pressurization	N/A	N/A	N/A		
	1,500 500	o. of continuous staircases to	01 No's	Provided	MR		
		rrace	1.50 m	2.10 m	MR		
		idth of Corridor oor Size	1.20 m	Provided	MR		
3.	Comp	partmentation					
		Fire check door	N/A	N/A	N/A		
		Sealing of electrical shafts	N/A	N/A	N/A		
	•	Fire Rating of shaft door	N/A	N/A	N/A		
	•	Water Curtain	N/A	N/A	N/A		
	•	Fire Dampers	N/A	N/A	N/A		
4.	Smoke Management System						
		Basements	N/A	N/A	N/A		
	•	Upper floors	Required	Natural ventilation	MR		
5.	Fire Extinguishers						
		Total numbers on each floor	10 no.'s	Provided	MR		
		Types	ABC/CO ₂ type	Provided	MR		
		IS marking	ISI marked	ISI marked	MR		
6.	First-	First-Aid Hose Reels					
		Total numbers on each floor	01 no's	01	MR		
		Length of hose reel hose	30 m	30 m	MR		
		Nozzle diameter	5 mm	5 mm	MR		
VG				Gy.			

7.	Automatic fire detection and alarming	g system		
-02		N/A	N/A	N/A
	 Type of detectors Location of Main Panel 	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A N/A	N/A	N/A
	Hooters' Location	N/A	N/A	N/A
•	W Francisco Parameter State Control Co	Required	Provided	MR
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	12 - 500-000		
10.	Automatic Sprinkler System	N/A	N/A	N/A
	Basement	N/A	N/A	N/A
	 Ground Floor Sprinkler above false ceiling	N/A	N/A	N/A
1.	Internal Hydrants	N/A	N/A	N/A
t	Size of riser/down-comer Charles to per floor	N/A	N/A	N/A
	Number of hydrants per floor Hose Box	N/A	N/A	N/A
2.	Yard Hydrants	N/A	N/A	N/A
	Total number of hydrants	N/A N/A	N/A	N/A
	Hose Box	1,775		
3.	Pumping Arrangements			
14	Ground Level		N/A	N/A
20	Discharge of main Pump	N/A	N/A	N/A
	Head of Main pump	N/A		N/A
	Number of main pumps	N/A	N/A	N/A
	Jockey Pump out put	N/A	N/A	N/A
	Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	(PASTA PASTA
	Standby Pump HeadAuto Starting/Manual	N/A	N/A	N/A
	 Auto Starting/Manual Stopping 	N/A	N/A	N/A
	> Pump House Access	N/A	N/A	N/A
-	Terrace level) (D
	Discharge of pump	450 LPM	450 LPM	MR
	Head of the pump	40 m	40 m Provided	MR MR
	> Power Supply	Required Required	Provided	MR
	➤ Auto Starting of pump	Required	Tiovided	
	Captive Water Storage for fire fighting			
	Underground tank capacity	N/A	N/A	N/A
	> Draw-off connection	N/A	N/A	N/A
	Fire service inletAccess to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A	N/A	N/A
	16: , 5:	10,000 ltrs	10,000 ltrs	MR
E	Exit Signage.	Required	Provided	MR
	rovision of Lifts.	<	No	Lift
P			544	N/A
P	Pressurization of Lift Shaft	N/A	N/A	IN/A
P	Pressurization of Lift Shaft Pressurization of Lift lobby		N/A N/A	
P	 Pressurization of Lift lobby Communication In lift Car 	N/A N/A N/A	N/A	N/A
P	Pressurization of Lift lobby	N/A		

17.	Standby power supply	N/A	N/A	N/A		
18.	Refuge Area.	***************************************				
_	> Total Area	N/A	N/A	N/A		
	> Location	N/A	N/A	N/A		
19.	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
	 PA System Panel Battery backup Building Floor Plans 	N/A	N/A	N/A		
		N/A	N/A	N/A		
		. N/A	N/A	N/A		
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were test checked and found not functional at the time of inspection.

Keeping in view of the above compliance of the minimum standards of fire prevention and fire safety measures under Rule 35 of the Delhi Fire Service Rules 2010, it's recommended to grant Fire Safety Certificate.

Note: - Earlier this department issued FSC vide letter No. F.6/DFS/MS/SZ/2022/1124 dated 10.10.2022 (placed at C-21) for old block of the school which is having two blocks comprised of ground floor and ground plus one upper floor.

Accordingly, DFS is put up for approval & signature please.

Signature of the Inspecting Officer

Name- R.K. Yadav

Designation- ADO (JKP)

DO (South West)

13131 VS

cro

13 31 2025

Director My Son M

Mr) My