



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001**



No.F.6/DFS/MS/School/2025/NDZ/ 497

Dated: 09/06/2025

To,

The Principal,
MCD Primary School
Chand Mohalla, Gandhi Nagar,
Delhi-110031.

Subject:-Regarding issuance of Fire Safety Certificate in r/o MCD Primary School located at Chand Mohalla, Gandhi Nagar, Delhi-110031.

Sir,

This is in reference to your letter no. nil dated 08/04/2025 on the subject cited above. In this connection, it is to inform you that officer concerned of this department has visited the school on dated 20/05/2025 in presence of In-charge of the school and observed that the shortcomings as communicated earlier vide letter No. F.6/DFS/MS/School/2023/NDZ/328 dated 26/06/2023 (copy enclosed) have not been complied yet.

In view of the above, Fire Safety Certificate cannot be considered at this stage. You are requested to rectify the shortcomings communicated vide above mentioned letter under intimation to this office for further action.

Yours faithfully

(VIRENDRA SINGH)
CHIEF FIRE OFFICER

Encl. As above

Copy to:-

The Director of Education (MCD)
15th Floor, E-Block, Dr. S.P. Mukahrjee Civic Center, JLN Marg, New Delhi-110002



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001

No. F.6/DFS/MS/School/2023/NDZ/328

Dated 20/06/2023

To,

The Ex. Engineer (Elect.)-II
EDMC Office of the Executive Engineer (Elect.)-II/SSZ
MCD 2nd Floor, Technical Laboratory, Near NH-24
Gazipur, Delhi-110096

Subject: - Regarding Issuance of Fire Safety Certificate in r/o MCD Primary School at Chand Mohila, Gandhi Nagar, Delhi-110031.

Sir,

This is in reference to your letter No. EE(Elect.)-II/SHN(S)/2023-24/D-18 dated 17/04/2023 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection of the above mentioned School from fire safety point of view on dated 25/05/2023 in presence of Mrs. Menu Puri, In-charge of the School. The building comprised of ground plus two upper floors. Following shortcomings were observed during the time of inspection.

1. One staircase of width 1.30 meter is provided against requirement of two staircase of width 1.50 meter.
2. Overhead water storage tank capacity 5000 liters is provided against requirement of 10,000 liters.
3. Exits signage not provided.

In view of the above, the building cannot be considered for issuance of Fire Safety Certificate at this stage. Therefore, you are requested to provide the above mentioned fire safety arrangements under intimation to this office for further course of action.

Yours faithfully

(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE

Copy to:-

1. The Director of Education, MCD
15th Floor, E- Block, Dr. S.P. Mukherjee Civic Center, JLN Marg,
New Delhi-110002
2. MCD Primary School
Chand Mohila Gandhi Nagar, Delhi-110031.