



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001**

c/16



No.F.6/DFS/MS/School/2025/NDZ/ 393

Dated: 14/05/2025

To,
The Principal,
MCD Primary School
Janta Mazdoor Colony Jafrabad Extn. -II,
Delhi-110053

Subject:-Regarding Issuance of Fire Certificate in r/o MCD Primary School at Janta Mazdoor Colony, Jafrabad Extn. -II, Delhi-110053.

Sir,

This is in reference to your Email:- edmcpsjmc2@gmail.com dated 11/12/2024 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has visited the school on dated 03/05/2025 in presence of Mr. Anil Kapoor, Principal and observed that the shortcomings as communicated earlier vide letter No. F.6/DFS/MS/School/2021/NDZ/160 dated 26/03/2021 (copy enclosed) have not been complied yet.

In view of the above, Fire Safety Certificate cannot be considered at this stage. You are requested to rectify the shortcomings communicated vide above mentioned letter under intimation to this office for further action.

Encl:- As above

Yours faithfully

(ATEL GARG)
DIRECTOR

DELHI FIRE SERVICE

Copy to:-

The Director of Education (MCD)
15th Floor, E-Block, Dr. S.P. Mukahrjee Civic Center, JLN Marg, New Delhi-110002

clw C14

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No.F6/DFS/MS/School/2021/NDZ/ 160

Dated:- 26/03/2021

To,

The Principal,
E.D. M. C. Primary School,
Janta Mazdoor Colony Jafrabad Ext. -II,
Delhi-110053

Subject:- Regarding issue of Fire Safety Certificate.

Sir,

With reference to your letter No. JMC Ext-II/School/118/19/01-21 dated 19/01/2021 on the subject cited above, it is informed that officer concerned of this department inspected the school from fire safety point of view in presence of Mrs. Shakil Fatima, Principal of the school on dated 16/03/2021. The school building comprises of ground plus two upper floors. During the course of inspection following observations were made:-

1. The firefighting system which has been provided in the school building was not functional at the time of inspection.
2. The discharge capacity & head of the fire pump could not ascertained in absence of documents/technician.

In view of the above, the school building cannot be considered for issuance of Fire Safety Certificate at this stage. Therefore, you are requested to rectify the above mentioned fire safety arrangements under intimation to this office and also, provide discharge capacity and head of the fire pump at the earliest for further necessary action.

Yours Faithfully,


24/3/21

(Dr. S. K. Tomar)
Dy. Chief Fire Officer

Copy to:-

The Director of Education, E.D.M.C.,
419, Udyog Sadan,
Patparganj Industrial Area,
Delhi -110092