

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2025/SZ/ 521

Dated: - 22/04/2025

FIRE SAFETY CERTIFICATE

Certified that the MCD Primary School at Nawada Main-II, Uttam Nagar, New Delhi110059, comprised of ground plus two upper floors, owned occupied by MCD, was issued FSC by this
department vide letter No. F.6/DFS/MS/School/2022/SZ/167 dated 14.02.2022. The school building
was re-inspected by the officer concerned of this department on dated 08.04.2025 in the presence of
Sh. Mahavir Chaudhary, and found that School building have deemed complied the fire prevention and
fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the
building/premises (ground plus two upper floors only) is fit for occupancy class "Educational"
w.e.f. 22 of 2015 for a period of three years in accordance with Rule 36 unless renewed under
Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38
of the Delhi Fire Service Rules, 2010 printed as below.

Issued on 22 04 2025 at New Delhi by.

Delhi Fire Service

Copy to: -

1. Director of Education, MCD, Dr. S.P. Mukherjee Civic Centre, New Delhi- 110002.

2. The Principal, MCD Primary School located at Nawada Main-II, Uttam Nagar, New Delhi-59.

Conditions for the validity of fire safety certificate: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name & address of the building: M.C.D. Primary School, Nawada Main- II, New Delhi-110059.

Building is comprised of : Ground plus two upper floors.

3. Type of Occupancy : Educational
4. Type of Case : Renewal

5. Details of Previous NOC : F.6/DFS/MS/School/2022/SZ/167 dated 14.02.2022

6. Fire Safety directives letter No : N/A

7. Date of inspection : 08.04.2025

8. Name of Inspecting Officer : A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side : Sh. Mahavir Chaudhary

10. Year of Construction : 2017

11. Applicant's letter No. : Online email Id sdmcnawadamain2@gmail.com dated 11.03.2025

S. No.		um Standards on fire prevention e safety U/R 33	Requirement as per FSC dt. 14.02.2022	Provided at site	Remarks MR/NMI		
1.	Access to building						
	•	Road width Gate width Width of internal road	Accessible 06 m 4.5 m NA	Provided Provided NA	M/R MR NA		
2.	Number, Width, Type & Arrangement of Exits						
	a. Nun	per of staircases					
	•	Upper Floors	02 No's	Provided	M/R		
	•	Basements	N/A	N/A	N/A		
	b. Wid	th of staircases	3 - 3 - 5 - 5 - 5 - 5 - 5 - 5 - 5 - 5 -				
	•	Upper Floor Basements	1.50 m	Provided	M/R		
	*	Basements	N/A	N/A	N/A		
	c. Prote	ection of exits	7.307(72)				
- 0	•	Fire check door	N/A	N/A	N/A		
	•	Pressurization	N/A	N/A	N/A		
	d. No.	of continuous staircases to	01	Provided	M/R		
	terra		1.50 m	2.10 m	M/R		
_		th of Corridor r Size	1.0 m	1.15 m (Double door)	M/R		
3.	Compartmentation						
	•	Fire check door	N/A	N/A	N/A		
	•	Sealing of electrical shafts	N/A	N/A	N/A		
	•	Fire Rating of shaft door	N/A	N/A	N/A		
	•	Water Curtain	N/A	N/A	N/A		
		Fire Dampers	N/A	N/A	N/A		
4.	Smoke Management System						
		Basements	N/A	N/A	N/A		
	• 1	Upper floors	Required	Natural Ventilation	M/R		
5.	Fire Extinguishers						
	•	Total numbers	07 no's	Provided	M/R		
		Types	ABC/CO ₂ type	Provided	M/R		
	• 1	\$ marking	ISI marked	ISI marked	M/R		

N24

		I.					
6.	First-Aid Hose Reels						
	 Total numbers on each floor 	Two	Provided	M/R M/R			
	 Length of hose reel hose 	30 m	Provided	M/R			
	Nozzle diameter	05 mm	Provided	M/K			
7.	Automatic fire detection and alarming system N/A N/A N/A						
	Type of detectors	N/A N/A	N/A	N/A N/A			
	 Location of Main Panel Location of Repeater Panel 	N/A	N/A	N/A			
	Alternate source of power	N/A	N/A	N/A			
	Hooters' Location	N/A	N/A	N/A			
3.	MOEFA	N/A	N/A	N/A			
).	Public Address System	N/A	N/A	N/A			
2717	Automatic Sprinkler System						
0.	100 miles (100 miles (N/A	N/A	N/A			
	Basement Ground Floor	N/A	N/A	N/A			
	Sprinkler above false ceiling	N/A	N/A	N/A			
1.	Internal Hydrants						
1.	CONTRACTOR OF THE	N/A	N/A	N/A			
	Size of riser/down-comer	N/A	N/A	N/A			
	Number of hydrants per floor Hose Box	N/A	N/A	N/A			
2.	Yard Hydrants N/A N/A						
	Total number of hydrants	N/A N/A	N/A	N/A N/A			
	Hose Box	N/A	11/14				
3.	Pumping Arrangements						
	Ground Level		NY/4	N/A			
	 Discharge of main Pump 	N/A	N/A	N/A			
	Head of Main pump	N/A	N/A				
	Number of main pumps	N/A	N/A	N/A			
	Jockey Pump out put	N/A	N/A	N/A			
	Jockey pump head	N/A	N/A	N/A			
	➤ Standby Pump out put	N/A	N/A	N/A			
	➤ Standby Pump Head	N/A	N/A	N/A			
	➤ Auto Starting/Manual Stopping	N/A	N/A	N/A			
	1	N/A	N/A	N/A			
	> Pump House Access		B **3				
	Terrace level	450 LPM	Provided	M/R			
	> Discharge of pump	40 m	Provided	M/R			
	> Head of the pump	Required	Provided	M/R			
	Power SupplyAuto Starting of pump	Required	Provided	M/R			
	Captive Water Storage for fire fighting						
	Underground tank capacity	N/A	N/A	N/A			
	> Draw-off connection	N/A	N/A	N/A			
	➤ Fire service inlet	N/A	Provided	N/A			
	> Access to tank	N/A	N/A	N/A			
¥3	Overhead Tank capacity	10,000 ltrs.	Provided	M/R			
17	Exit Signage.	Required	Provided	M/R			
	Provision of Lifts.	4	(No	Lift)			
	Pressurization of Lift Shaft	N/A	N/A	N/A			
	Pressurization of Lift lobby	N/A	N/A	- 100 - 100 M (SEA)			
	Communication In lift Car	N/A	N/A	N/A			
,	Fireman's Grounding Switch	N/A	N/A	N/A			
/	Lift Signage	N/A	N/A	N/A			
			4.3/4.k	N/A			

1	7	The state of the s	1 3/4	NVA	N/A	
	Stand	y power supply	N/A	N/A	N/F	
_	Refuge	Area.				
1	-	Total Area	N/A	N/A	N/A	
	>	Location	N/A	N/A	N/A	
_	Fire Control Room					
-		Detector System Panel	N/A	N/A	N/A	
		Flow Switch Panel	N/A	N/A	N/A	
		PA System Panel	N/A	N/A	N/A	
	•			N/A	N/A	
		Battery backup	N/A			
	•	Battery backup Building Floor Plans	N/A N/A	N/A	N/A	

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2022/SZ/167 dated 14.02.2022, renewal under rule 37, of the Delhi Fire Service Rules 2010 is recommended.

Signature of Inspecting Officer

Name: - R.K. Yadav Designation: - ADO (JKP)

DO (South West)

11/4/25

1 /1 /1 /2025

Director

Moysy

FT hetter is purup for Ngupha

RECTORIUM)