



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001**

No.F.6/DFS/MS/School/2025/NDZ/ 439

Dated: 23/05/2025

To,

The Principal, MCD Primary School, B-Block, Seelampur, Delhi-110053.

Subject:-Regarding renewal of Fire Certificate in r/o MCD Primary School, B-Block, Seelampur, Delhi-110053.

Sir,

This is in reference to your outdoor dairy no. 14512 dated 17/03/2025 on the subject cited above. In this connection, it is to inform you that officer concerned of this department has visited the school on 10/05/2025 in presence of Principal and observed that the shortcomings as communicated earlier vide letter No. F.6/DFS/MS/School/2022/NDZ/422 dated 19/07/2022 (copy enclosed) have not been complied yet.

In view of the above Fire Safety Certificate cannot be considered at this stage. The occupancy of the building/premises in absence of requisite for safety arrangement shall be at the risk and liability of the

owner/occupier.

Encl:- As above

Copy to:-

The Director of Education (MCD) 15th Floor, E-Block, Dr. S.P. Mukahrjee Civic Center, JLN Marg, New Delhi-110002





GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. F.6/DFS/MS/School/2022/NDZ/ 422

Dated 19/7/22

To,

The Principal, MCD Pimary School, B-Block, Seelampur, Delhi- 110053.

Sub:- Regarding Issuance Fire Safety Certificate r/o MCD Primary School located at B-Block, Seelampur, Delhi- 110053.

Sir,

With reference to your letter No. EDMC/EE(E) -I/SHN/2021-22/D-40 dated 02/05/2022 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection of the above mentioned School from fire safety point of view in presence of Mrs. Anju Nagpal, Principal. The following points/shortcomings were noticed in the building which is comprised of ground plus two upper floors.

- 1. One staircase of width 1.25 meter is provided against requirement of two staircase of width 1.50 meter.
- 2. First-Aid hose reel provided but not functional.
- 3. The discharge capacity & head of the fire pump could not ascertained in absence of documents.

In view of the above, the building cannot be considered for issuance of Fire Safety Certificate at this stage. Therefore, you are requested to provide the above mentioned fire safety arrangements under intimation to this office for further course of action.

Yours faithfull

Director

Delhi Fire Service

Copy to:-

1. The Director of Education, MCD
15th Floor, E- Block, Dr. S.P. Mukherjee Civic Center, JLN Marg,
New Delhi-110002