

2/18

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No.F6/DFS/MS/School/2025/NDZ/ 537

Dated: 20/06/2025

To

The Principal
M.C.D. Nigam Pratibha School-1,
3rd Pusta, Sonia Vihar, Delhi-110090.

Sub.:- Regarding renewal of Fire Safety Certificate in r/o M.C.D. Nigam Pratibha School-1, 3rd Pusta, Sonia Vihar, Delhi-110090.

Sir,

Please refer to your letter No. D-899/DDOS/SVI/SH(N)2025/30-05-2025 dated 30/05/2025 on the subject cited above. In this connection it is to inform you that the school premises was visited by the officer concerned of this department on 10/06/2025 in the presence of Mr. Gagan Deep (Principal) and observed that the shortcomings issued by this department vide letter No. F6/DFS/MS/School/2022/NDZ/256 dated 27/05/2022. (Copy Enclosed) still not complied.

In view of above, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Enclosed: As above

Yours faithfully,


(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE.

a/c

Copy to:-

1. The Dy. Director of Education, MCD Udyog Sadan, Plot No. 419, FIE, Patparganj, Delhi-92.

cl15

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001**

No. F6/DFS/MS/School/2022/NDZI/256

Dated 27/05/2022

To,
The Principal,
EDMC Primary School,
Sonia Vihar, Delhi-110094.

Sub:- Regarding Issuance Fire Safety Certificate in R/o EDMC Primary School at Sonia Vihar, Delhi-94

Sir,

With reference to your letter No. EDMC/EE(E)-I/SHN/2021-22/D-40 dated-02/05/2022 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection of the above mentioned school from fire safety point of view on dated 18/05/22 in presence of Mr. Vijay Kumar Gupta (Principal). The following points / shortcomings were noticed in the building which is comprised of ground plus three upper floors .

1. Access /approach road width is less than 6 meters.
2. First Aid Hose Reels not functional.
3. A fire pump having 450 LPM output at 40 meters head not functional.

In view of above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore you are suggested to rectify the above mentioned shortcomings under the intimation to this department for further course of action.

Yours faithfully

(Atul Garg)
Director

Copy to:-

1. The Director of Education, EDMC
Udyog Sadan, Plot No. 419, FIE,
Patparganj, Delhi 92
2. The Ex. Eng. (Elect,)-II,
Shahdara (North)Zone,
EDMC, Office of Executive Engineer (Elect)-II,
MCD Zonal Office Buildings, Keshav Chowk,
G.T. Road, Near Shyam Lal College.