



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

आपदा निवारण
अमृत महोत्सव

No. F6/DFS/MS/SCHOOL/NDZ/2025/ 396

Dated: 14/05/2025

To,

The Principal,
MCD Primary School
O – Block, Sunder Nagri,
Delhi – 110093.

Subject: - Regarding Grant of Fire Safety Certificate in r/o MCD Primary School located at O – Block, Sunder Nagri, Delhi – 110093.

Sir,

Please refer to your letter outdoor diary No. 918 dated 23/04/2025 on the subject cited above. In this connection, it is to inform you that the site was visited by officer concerned of this department on 07/05/2025 in the presence of Mrs. Shivani Kalra (Principal) and observed that the shortcoming has still not complied with as issued by this department vide letter no. F6/DFS/MS/School/2019/NDZ/2021/215 dated 16/04/2021 (copy enclosed).

In view of above, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Yours faithfully,

Enclosed: As above

(ATUL GARG)
DIRECTOR

o/c DELHI FIRE SERVICE

Copy to: -

1. The Director of Education, MCD, Udyog Sadan, Plot No. 419, FIE, Patparganj, Delhi - 110092.

C/26

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001**

No. 16/DAS/MS/School/ND2/2021/215

Dated 16/04/2021

To,

The Principal,
EDMC Primary School,
O-Block, Sunder Nagri,
Delhi 110093

Sub:- Regarding Issuance Fire Safety Certificate.

Sir,

This is in reference to your email ID edmcpsnno01@gmail.com dated 22/12/2020 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection of the above mentioned EDMC Primary School from fire safety point of view in presence of Mrs. Deepa Rani Gupta, Principal of the School. During the course of inspection it was observed that the following points / shortcomings were noticed in the building comprised of ground plus two upper floors.

1. Only 06 fire extinguisher provided in place of 14 fire extinguishers as required.
2. First-Aid hose reels (01 nos.) not provided at each floor as required.
3. A fire pump having 450 LPM output at 40 meters head not provided.
4. Exit Signage were not provided.
5. Overhead tank 10,000 ltr.cap.is not provided.

In view of above, the building can not be considered for issue of Fire Safety Certificate at this stage. Therefore you are suggested to rectify the above mentioned shortcomings under the intimation to this department for further course of action.

Yours faithfully


13/4/21

(Dr. S.K. Tomar)
Dy.Chief Fire Officer



Copy to:-

The Director of Education, EDMC
Udyog Sadan, Plot No. 419, FIE,
Patparganj, Delhi 92