



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

7/6
आज़ादी का
अमृत महोत्सव

No. F6/DFS/MS/School/SZ/2025/ 434

Dated: 22/05/25

To

The Principal
MCD Primary School No. 2 (Girls),
Tughlakabad Extn.,
New Delhi-19 (School ID no. 1958099).

Sub: -Regarding issuance of Fire Safety Certificate in r/o MCD Primary School No. 2 (Girls) located at Tughlakabad Extn, New Delhi-19 (School ID no. 1958099).

Sir,

With reference to letter bearing outdoor diary no. 14308 dated 11.03.2025 on the subject cited above, it is informed that the school building has been visited by the Assistant Divisional Officer (M. Road) from this department on 16.05.2025 in the presence of Mr. Durgesh (Chowkidar) and it was observed that the shortcomings issued to the building vide letter no. F6/DFS/MS/School/SZ/2019/7062 dated 27.11.2019 (Photocopy overleaf) has not been rectified till date. Hence FSC to the building cannot be considered at this stage.

In view of above shortcomings, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(Atul Garg)

Director

Delhi Fire Service

21/5/25. C

Copy to:-

The Directorate of Education, Center Zone: Lajpat Nagar, New Delhi-110024.

c/17

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE NEW DELHI-110001

No. F.6/DFS/MS/School/SZ/2019/

7062

Dated: 27.1.19

To,

The Principal,
SDMC Primary School No.2 (Girls),
Tughlakabad, Extension, New Delhi-110019.

Subject: - Issuance of Fire Safety Certificate.

Sir,

This is in reference to your letter no.-Nil, dated-12/09/2019 received through outdoor diary No.20186 dated 12/09/2019 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection on 21/09/2019 in the presence of Mrs. Meena Gupta (Principal). During the inspection it was observed that the school building is comprised of G + 3. The following shortcomings have been observed. -

1. First Aid hose reel not provided at each floor.
2. Terrace pump for firefighting capacity of 450 LPM with 40m head are not provided in auto mode.
3. Overhead tank with the capacity of 10,000 liters not provided at terrace.
4. Exit signage is required at each floor..

In view of above, the school building cannot be considered for grant of fire safety certificate. Therefore you are suggested to rectify the above mentioned shortcomings under the intimation to this department for further course of action.

Yours faithfully


(Anil Garg)
Director
Delhi Fire Service
A2 olc

Copy to:-

1. Directorate of Education, South MCD, Civic Centre, Minto Road, New Delhi-110002