No. F6/DFS/MS/School/SZ/2025/1277

Dated: 31/10/2025

FIRE SAFETY CERTIFICATE

Certified that the MCPS Rangpuri Boys School, Rangpuri, New Delhi-110037, building comprised of Ground plus one upper floor, owned / occupied by Delhi Municipal Corporation, was earlier issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/School/2022/SZ/1007 dated 14/09/2022. Now, the said premises was re-inspected by ADO/BCP of this department on 17/10/2025 in presence of Ms. Neeta Anil (Principal) and found that the said school building have deemed complied with the fire prevention and fire safety requirements in accordance with Directorate of Education Circular No.F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011 issued by the Director of Education, Govt. of NCT of Delhi and that the school building is fit for occupancy class "Educational Building" (Group - B) with effect from 31/10/2025 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of Delhi Fire Service Rules 2010.

Issued on 3110 2025 at New Delhi by.

(A.K.Malik)

Dy. Chief Fire Officer

Delhi Fire Service

OLC

O

Copy to: -

- 1. The Director of Education, MCD, Civic Centre, Minto Road, New Delhi-110002.
- 2. The Principal, MCPS Rangpuri Boys School, Rangpuri, New Delhi-110037.

Conditions for the validity of Fire Safety Certificate

- 1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- All the employees shall be acquainted with the use and maintenance of all fire equipment's and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the firefighting equipment's shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- 6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

-				**			
	-		PECTION REPOR				
01.	N	ame & address of the building	MCPS Rang	puri Boys School, I	langpu	ıri, Ne	
00	L		Delhi-110037				
02.	Ground plus one upper floor						
03.	T	ype of occupancy		Educational Building (Group-B) Renewal			
04.		ype of case	Renewal				
05.	D	etails of previous FSC	F6/DFS/MS/S	School/2022/SZ/100	7 dated	d	
0.6	_		14/09/2022				
06.	F	re safety directives letter no.	F.16/Estate/C	C/Fire Safety/2011/	3298 to	o 3398	
07	D		dated 01/03/2	011			
07. 08.		ate of inspection	17.10.2025.				
09.	N	ame of the inspecting officers	The Control of the Co				
09.		ame of the designation	of Ms. Neeta A	nil (Principal)			
10.		ficer from the building side					
11.	_	ear of construction	2003			_	
11.		oplicant's letter no.		Outdoor dairy no. 6128dated 18/09/2025			
S.No		inimum standard of fire	Old NOC	Provided at Rem			
2.110	þı	evention and fire safety U/R 33	Requiremen	t site	MR	VNMI	
)1.	A.	100gg 40 D213'					
1.	A	cess to Building: Road width	T v ma	1 (0)		\ m	
=	B	Gate width	Accessible	6.0 mtrs.		MR	
	C	Width of internal road	N/A	4.0 mtrs		N/A	
2.		mber, Width, Type and Ar	N/A	N/A		N/A	
	A	Number of staircases	rangement of Exi	ts:			
		a Upper floor	2 nos.	Provided 03 No	25	MI	
ŀ		C Basement	N/A	N/A	JS.	N/A	
	B	Width of staircases	1071	IVA		14/2	
21		a Upper floor	1.50 m / 0.75 m	1.80m, 1.30m & 1.	.30m	MI	
Ī		C Basement	N/A	N/A		N/A	
Ī	C	Protection of exits				- "-	
		a Fire check door	N/A	N/A		N/A	
		b Pressurization	N/A	N/A		N/A	
	D	No. of continuous	01 nos.	Provided		MR	
		staircases to terrace					
15	E	Width of corridor	1.5 mtr.	Provided		MR	
	F	Door size	1.0 mtr.	Provided	c	MR	
	Co	mpartmentation:					
	A	Fire check door	N/A	N/A	1	N/A	
	В	Sealing of electrical shafts	N/A	N/A	- I	N/A	
	C	Fire rating of shaft door	N/A	N/A	1	N/A	
	D	Water curtain	N/A	N/A	1	N/A	
]	E	Fire dampers	N/A	N/A	1	N/A	
. !	Sm	oke Management System:				14	
	A	Basement	N/A	N/A	1	N/A	
	B	Upper floor	N/A	N/A	1	N/A	
	G:	Extinguisher:					
	_	Total numbers	11 nos.	Provided		MR	
	4		ABC/CO ₂	ABC/CO ₂		MR	
	3	Types	ISI Marked	Provided		MR	
(ISI marking			I.		

2	15
2	112

06.	Fin	rst-Aid-Hose Reel:	10/112					
	A	Total numbers of each floor	N/A	N/A	N/A			
	В	Length of hose reel hose	N/A	N/A	N/A			
	C	Nozzle diameter	N/A	N/A	N/A			
07.	Au	tomatic Fire Detection and Alarmi	ng System:					
	A	Type of detectors	N/A	N/A	N/A			
	В	Location of main panel	N/A	N/A	N/A			
	C	Location of repeater panel	N/A	N/A	N/A			
	D	Alternate source of power	N/A	N/A	N/A			
	E	Hooters	N/A	N/A	N/A			
08.		OEFA:	N/A	N/A	N/A			
09	_	blic Address System:	N/A	N/A	N/A			
10.	and contract water to be a decreased to the contract of the co							
	A	Basement	N/A	N/A	N/A			
41	В	Upper floor	N/A	N/A	N/A			
	C	Sprinkler above false ceiling	N/A	N/A	N/A			
11.	_	ernal Hydrants:	No.					
	A	Size of riser/down-comer	N/A	N/A	N/A			
	В	Number of hydrants per floor	N/A	N/A	N/A			
Carcari	C	Hose box	N/A	N/A	N/A			
12.	-	rd Hydrants:		-348				
	A	Total number of hydrants	N/A	N/A	N/A			
	В	Hose box	N/A	N/A	N/A			
13.		mping Arrangements:						
1		round level	The court of					
	A	Discharge of main pump	N/A	N/A	N/A			
	В	Head of main pump	N/A	N/A	N/A			
	C	Number of main pumps	N/A	N/A	N/A			
	D E	Jockey pump out put	N/A	N/A	N/A			
	F	Jockey pump head	N/A	N/A	N/A			
	100,000	Standby pump out put	N/A	N/A	N/A			
x.	G	Standby pump head	N/A	N/A	N/A			
	H	Auto starting /manual stopping	N/A	N/A	N/A			
2	I	Pump house access	N/A	N/A	N/A			
2	1. SSA1096	rrace Level	27/4	27/4	27/			
	A	Discharge of pump	N/A	N/A	N/A			
	B	Head of the pump	N/A	N/A	N/A			
1.1	D	Power supply	N/A	N/A N/A	N/A N/A			
	124 1	Auto starting of pump	N/A	N/A	IV/A			
14.	Captive Water Storage for Fire Fighting:							
	A	Underground tank capacity	N/A	N/A	N/A			
	В	Draw-off connection	N/A	N/A	N/A			
	C	Fire service inlet	N/A	N/A	N/A			
	D	Access to tank	N/A	N/A	N/A			
	E	Overhead tank capacity	N/A	N/A	N/A			
15.	Exi	t Signage:	Required	Provided	MR			

W

16.						
	A	Pressurization of lift shaft	N/A	N/A	N/A	
	В	Pressurization of lift lobby	N/A	N/A	N/A	
	C	Communication in lift car	N/A	N/A	N/A	
	D	Firemen's grounding switch	N/A	N/A	N/A	
	E	Lift signage	N/A	N/A	N/A	
17.	V 1000	andby Power Supply:	NA	N/A	N/A	
18.	Defense Amon					
	A	Total area	N/A	N/A	N/A	
	B	Location	N/A	N/A	N/A	
19.	Fire Control Room:					
17.	A	Detector system panel	N/A	N/A	N/A N/A	
		Flow switch panel	N/A	N/A	A R	
	В	Control of Strain Marie Strain Strain Strain	N/A	N/A	N/A	
	C	PA system panel	N/A	N/A	N/A	
	D	Battery backup	N/A	N/A	N/A	
	E	Building floor plans	Description of the	N/A	N/A	
20.	Sp	ecial Fire Protection systems for otection of special Risks, if any: The fire protection system was rand	NA	11 150	nd was	

The fire protection system was randomly checked and tested ar

Keeping in view of the deemed compliance of minimum standards on fire functional at the time of inspection. prevention and fire safety measures as required under the rules, the Fire Safety Certificate issued vide letter no. F6/DFS/MS/School/2022/SZ/1007 dated 14/09/2022, renewal under

rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Signature of the Inspecting Officer Name: - Yashwant Singh Meena

Designation: - ADO/BCP