

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/GH/SW/2025/545

Dated: 21 11 2025

FIRE SAFETY CERTIFICATE

Certified that the M/s Metro View Guest House located at 17A/3, WEA, Karol Bagh, New Delhi -05, building is comprised of Basement + Ground + 03 upper floors: Basement - Storage, Ground floor - Reception + Dining Hall + Kitchen (inhouse), 1st, 2nd & 3rd floor- 08 Guest rooms at each floor and it was granted Fire Safety Certificate (FSC) by this department vide letter no. F6/DFS/MS/GH/SZ/2022/454 dated 03.10.2022 for total 24 guest rooms at 1st to 3rd floor. The premises was re-inspected by officer concerned of this department on 11.11.2025 in presence of Mr. Suresh Dhaka (Manager) and found that the Guest House has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the premises is fit for occupancy of Group 'A (Residential) sub division A-1, total 24 guest rooms (1st, 2nd & 3rd floor- 08 Guest rooms at each floor) with effect from ... 21. 11.2025. and valid upto 31.03.2028 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire service Rules, 2010 printed below.

Issued on 21112025 at New Delhi by

(A. K, Malik)

Dy. Chief Fire Officer (SZ)

01

Reference: elt.mcdonline application no. 2025110314555.

Copy to-

1. The Commissioner, MCD, Dr. S.P.M. Civic Centre, Minto Road, New Delhi-110002:- To ensure the occupancy as detailed above.

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 7. The means of escape shall be kept unobstructed/unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.

_	10	INS	PECTION REPOR	RT				
1		Name & address of the building	M/s Metro	View Guest H	the state of the s			
2	2	Building is comprised of	Basement + G Basement - S Ground - I (inhouse) 1"floor - 08 gs 2"floor - 08 gs	Ground + 03 upper torage Reception + Dining uest rooms uest rooms	Boors			
3	T	ype of occupancy	3"floor - 08 g					
4	-	ype of case		Residential Sub Division- A-1 Renewal F6/DFS/MS/GH/SZ/2022/454 dated 03.10.2022				
5	_	etails of previous FSC						
6	_	ire safety directive letter no.		H/SZ/2022/454 Galle	d 05.10.2022			
7	-	The same	Nil					
	+-	ate of inspection	11.11.2025					
8	-	ame of the inspecting officers		Rajesh Kumar Shukla, ADO (L.N) Mr. Suresh Dhaka (Manager)				
9	Fr	ame of the designation of officer om the building side	Mr. Suresh Dha					
10	Ye	ear of construction	2009					
11	A	oplicant's letter no.	elt_mcdonline a	pplication no. 2025	110314555			
S. No		inimum standard of Fire evention and Fire Safety U/R 33	Requirement as per Rule 35 (6)	Provide at site	Remarks MR/NMR			
1	_	cess to Building	160	10-	MR			
	A	Road width Gate width	6.0 m NA	6.0 m NA	NA NA			
	C	Width of internal roads	NA NA	NA NA	NA NA			
2	-	mber, Width, Type & Arrangem		1242				
	A							
		a) Upper floor	01 no.	l no.	MR (old case			
		b) Basements	01 no.	2 nos.	MR			
	В	Width of the staircase:	1					
		a) Upper floors	1.25 m	1.28 m	MR (old case)			
	C	b) Basements Protection of exits	1.25 m	1.22 m & 0.85 m	MR (old case			
	·	a) Fire check door	Required	Provided	MR			
		b) Pressurization	NA NA	NA	NA NA			
	D	No. of continuous staircase to terrace:	1 no.	1 no.	MR			
ŀ	E	Width of the corridor	1.25 m	1.25 m to 3.0 m	MR			
Ì	F	Door size	1.0 m	0.86 m	MR (old case)			
3	Con	partmentation:						
	A	Fire check doors	Required	Provided	MR			
	В	Sealing of horizontal & vertical opening	Required	Provided	MR			
ŀ	C	Fire rating of shaft doors	NA	NA	NA			
t	D	Water curtain	NA	NA	NA			
	E	Fire dampers	NA	NA	NA			
4		oke Management System:	Paguin d	P. L. C				
+	A B	Basements Upper floors	Required Required	Exhaust fans Exhaust fans	MR			
_		Extinguishers	quire	DAHGUST IGHS	MR			
-	A	Total numbers	12 nos.	12	land and			
	^		TH ADDRESS	12 nos.	MR			
-	R	Types	('(') AD/' '					
	B C	Types ISI marking	CO ₂ , ABC Required	CO ₂ , ABC	MR			

N/19

6	6 First Aid Hose Reel							
	A		1 no.	1 no.	MR			
	В	g o. nose reer	30 m		MR			
Ļ	C	- Totale diameter	5 mm	5 mm	MR			
7	7.31.viii, UBBL 2016).							
	A		CO detector		MR			
	В	a station of main faile	At ground	Provided	MR			
	C	paner	NA		NA			
	D	The source	NA		NA			
	Е	MOEFA	Audible in entire building Required	Provided 1	MR			
8					MR			
9		ublic Address System	Required	Provided	MR			
10		utomatic Sprinkler System Basement	T		***			
	A		NA (Area less than 200 m ²)	Provided	NA			
	В	- FF.,	NA	NA	NA			
	C	T Talog Colling	NA .	NA	NA			
11	_	ternal hydrants						
	A	Size of the riser/down comer	NA	NA	NA			
	В	CHICK SCHOOL CONTRACTOR FOR A STATE OF THE	NA	NA	NA			
	C	Hose box	NA	NA	NA			
12	_	ard Hydrants	Teer	1	N1 4			
	A	Total no. of hydrants	NA	NA	NA			
	В	Hose box	NA	NA	NA			
13		imping arrangements						
	A	Ground Level	LNA	T N/A	NA			
	. 8	a) Discharge & head of main pump	NA	NA	NA			
		b) Number of main pump	NA	NA	NA			
		c) Discharge & head of jockey pump	NA	NA	NA			
		d) Discharge & head of Standby	NA	NA	NA			
		e) Auto starting/ manual stopping	NA	NA	NA			
	-		1,1,1	5.2.5				
	В	Terrace Level	450 LPM	450 LPM x 2	MR			
		a) Discharge of terrace	430 LFWI	nos.	l.v.i.c			
	-	pump	40 m	40 m	MR			
		b) Head of terrace pump		Provided	MR			
		c) Alternate power supply	Required	Provided	MR			
		d) Auto starting of pump	Required	Flovided	IVIIC			
14	Ca	ptive Water Storage for Fire Figh	iting	NA	NA			
	A	Underground tank capacity	NA ·	12 50	NA			
	В	Draw off connection	NA	NA	NA			
d	C	Fire Service Inlet	NA	NA	NA NA			
	E	Access to tank	NA	NA	To a company			
	D	Overhead tank capacity	5,000 ltrs	10,000 ltrs	MR			
_	350		Required	Provided	MR			
5	Exi	t Signage			ingle o			
6	Pro	vision of lift	NA	NA	NA			
	A	Pressurization of lift shaft	NA NA	NA	NA			
T	В	Pressurization of lift lobby	moderal	Provided	MR			
-	C	Communication in lift car	Required	Provided	MR			
- 1	_	Fireman switch	Required	Provided	MR			
-	n			1 1/F(31/1/1P(1)				
		Lift signage	Required Required	Provided	MR			

M/s Metro View Guest House located at 17A/3, WEA, Karol Bagh, New Delhi -05.

Refuge Area						
A	location	NA	NA	NA		
В	Total area			NA		
Fire Control Room						
A	Fire Detection System panel	NA	NA	NA		
В		NA	NA	NA		
C		NA	NA	NA		
D			NA	NA		
E		NA	NA	NA		
A Special Fire Protection system for Protection of Special Risk, if any:						
	B Fir A B C D	B Total area Fire Control Room A Fire Detection System panel B Flow switch panel C P A system panel D Battery backup E Building floor plan Special Fire Protection for special ris	B Total area NA Fire Control Room A Fire Detection System panel NA B Flow switch panel NA C P A system panel NA D Battery backup NA E Building floor plan NA Special Fire Protection for special risk if any	B Total area NA NA Fire Control Room A Fire Detection System panel NA NA B Flow switch panel NA NA C P A system panel NA NA D Battery backup NA NA E Building floor plan NA NA Special Fire Protection for special risk if any		

LEGENDS:-Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided but Not Functional (PNF), Not Provided (NP).

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

The shortcomings issued to the Guest House by this department vide letter no. F6/DFS/MS/GH/NDZ/2025/385 dated 11.09.2025 has been rectified by the Guest House

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. F6/DFS/MS/GH/SZ/2022/454 dated 03.10.2022 is recommended to be renewed under Rule 37 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer
Name Rajesh Kumar Shukla
Designation ADO (L.N.)

5

17/11/25
RAJINDER AFWAL

PAR. MALIK

Elmostal Winch

Dy CFo to Som

Dy. (50 (921)

. K

A.K.

Ass (LN)