HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001 Dated: 26 03 2005 GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI

No. F6/DFS/MS/2025/WZ/ 144

FIRE SAFETY CERTIFICATE

Certified that the Mother Dairy Fruit & Vegetable located at Phase-1, Mangolpuri Ind. Area, Delhi-110083, comprised of admin block-(Basement, Ground + 03 upper floors) Worker Amenity Building, Service block, Godown, Engineering Store, Central Store-(Ground floor) has already been issued FSC by this department vide letter No. F.6/DFS/MS/2020/86 dated 30.01.2020. The premises was re-inspected by the officer concerned of this department on 10.03.2025 in the presence of Mr. Punit and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class Industrial/storage with effect from 21 03 2025 of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 26 63 7025 at New Delhi by

h; 011-23414000

Copy to: -

1. M/s Mother Dairy Fruit & Vegetable located at Phase-1, Mangolpuri Ind. Area, Delhi-110083.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.

2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

5. This certificate cannot be treated in any case for regularizations of unauthorized construction.

6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on

8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Fire+Safety+Acts+and+

http://www.delhi.gov.in/wps/wcm/connect/doit fire/FIRE/Home/Forms Rules/

			INSPE	CTION REPOR	r	i i		
Na	Name & address of the building		Mothe	Dairy Fruit 0. v	7			
	- CO		Mother Dairy Fruit & Vegetable Phase-1, Mangolpuri Ind. A. Delhi-110083.					
2. Ty	pe of Occupa	ncy	Busine	SS/Assembly/C4		Solpan Ind. A		
. Ty	Type of Case			Business/Assembly/Storage Renewal				
	1		Admin block-(Recoment G					
	3		Ameni	Admin block-(Basement, Ground + 03 upper floors) World Amenity Building, Service block, Godown Francisco				
	CD	Nos	Amenity Building, Service block, Godown, Engineering Sto					
. Details of Previous NOC			F.6/DFS/MS/2020/86 dated 30.01.2020.					
	Fire Safety directives letter No			F.6/DFS/MS/BP/2019/2780 dated 09.05.2019				
. Date of inspection . Name of Inspecting Officer			10.03.2025 Sh. Ajay Kumar Sharma (ADO Rohini)					
								. Na
	om the buildi							
. Ye	ar of Constru	action	1989					
	Applicant's letter No.		OD No 12403 dated 14 02 2025					
Mi	inimum Star	ndards on fire preve	ention	main DDY AVD C				
an	d fire safety	U/R 33	MILION	Requirement	Provided at site	Remarks MR/NMR		
	ccess to build			Requirement		MINIMIN		
	• Dood width			Accessible	A!1.1	100		
					Accessible	MR		
-	• Gate width			Accessible	6.0m	MR		
		of internal road		-NA-	-NA-	-NA-		
N	Number, Width, Type & Arrangement			Exits				
a.	a. Number of staircases					-		
	 Upper Floors 			02nos. in admin bl	k 02nos.	MR		
9	• Base	Basements		02nos.	02nos.	MR		
b.	. Width of staircases							
8	• Upp	er Floor		1.25m & 2m	1.25m & 2m	MR		
11	Basements			1.25m	1.25m	MR		
c.						1		
li F	100 GOOD WAR	check door		Required	Provided	MR		
11				-NA-	-NA-	-NA-		
d		ressurization	terrace	02nos.	Provided	MR		
1		tinuous staircases to	cirace	-NA-	-NA-	-NA-		
e. f.	The state of the s	UTTIOF		1.5m	1.5m	MR		
-						1		
				Required	Provided	MR		
1 1		check door		Required	Provided	MR		
1		Ing of electrical shafts		Required	Provided	MR		
	Fire Rating of shaft door Water Curtain		-NA-	-NA-	-NA-			
	• Fire Dampers		-NA-	-NA-	-NA-			
4.	4. Smoke Management System			-58 <u>9</u>				
	a) Baser	nents		30 a/c per hour	Provided	MR		
E	b) Uppe	r floors		12 a/c per hour	Provided	MR		
3.	Fire Extinguishers			•		- 3-2		
	• Total numbers		18nos.	Provided	MR			
	Types			ABC/CO2	ABC/CO2	MR		
6.	First-Aid T	narking		ISI marked	Yes	MR		
	• Tota	Hose Reels			Duaridad	MR		
_	• Len	na numbers on each floor		01nos.	Provided Provided	MR		
1		or nose reel hose		30mm	riovided	IVIIC		

T	• Nozzla di				
1	1NOZZIE diameter	5m	Provided	M.	
1	Automatic fire detection and alarming syst	em			
-	a) Type of detectors	Required	Provided	MR	
_	b) Location of Main Panel	Ground floor	Provided	MR	
	c) Location of Repeater Panel	Ground floor	Provided	MR	
	d) Alternate source of power	Required	Provided	MR	
	e) Hooters' Location	Each floor	Provided	MR	
	MOEFA		Provided	MR	
1	Public Address System	Required		-NA-	
).	Automatic Sprinkler System	-NA-	-NA-	-NA-	
	Basement	D . 1	D 11.1	MR	
1		Required	Provided		
	Ground & Upper Floors	Required	Provided	MR	
_	Sprinkler above false ceiling	-NA-	-NA-	-NA-	
1.	Internal Hydrants				
	Size of riser/down-comer	Required	Provided	MR	
	 Number of hydrants per floor 	01nos.	Provided	MR	
	Hose Box	01nos.	Provided	MR	
12.	Yard Hydrants				
	Total number of hydrants	02nos.	Provided	MR	
	Hose Box	02nos.	Provided	MR	
13.	Pumping Arrangements		All II		
	Ground Level				
1	Discharge of main Pump	2280lpm	Provided	MR	
	Head of Main pump	60m	Provided	MR	
	Number of main pumps	01nos.	Provided	MR	
	Jockey Pump out put	180lpm	Provided	MR	
	Jockey pump head	60m	Provided	MR	
	Standby Pump out put	2280lpm	Provided	MR	
	Standby Pump Head	60m	Provided	MR	
	Auto Starting/Manual Stopping	Required	Provided	MR	
	> Pump House Access	Required	Provided	MR	
	Terrace level	0001			
	Discharge of pump	900lpm	900lpm	MR	
	➤ Head of the pump	40m	40m	MR	
	> Power Supply	Required Required	Provided Provided	MR	
	Auto Starting of pump	Required	riovided	MR	
14					
_	Underground tank capacity			MR	
	> Draw-off connection	Required	Provided	MR	
	> Fire service inlet	Required	Provided	MR	
	➤ Access to tank	Required 20,000ltr Required	Provided Provided Provided	MR MR	
	Overhead Tank capacity				
-		Required	Flovided	MR	
1:	Provision of Lifts.	-NA-	-NA-		
1	Prossurization of Lift Shaft	-NA-	-NA-	-NA-	
	Description of Lift lobby	-NA-	-NA-	-NA-	
	migation In lift Car	-NA-	-NA-	-NA-	
	Fireman's Grounding Switch	-NA-	-NA-	-NA-	
	• Lift Signage			-NA-	

//	Zandby power supply	Required	Provided	MR		
12	afuge Al	a				
万	> Total Area	-NA-	-NA-	-NA-		
1	Location	-NA-	-NA-	-NA-		
	Fire Control Room	ol Room				
19.	Detector System Panel	-NA-	-NA-	-NA-		
1 +	Flow Switch Panel	-NA-	-NA-	-NA-		
·	PA System Panel	-NA-	-NA-	-NA-		
H	Battery backup	-NA-	-NA-	-NA-		
F	Building Floor Plans	-NA-	-NA-	-NA-		
	Special Fire Protection System for Protection of special Risks, if any:	-NA-	-NA-	-NA-		

Accordingly, the fire protection systems provided in the building were tested/ checked randomly and

found in working condition at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in NBC Part-4, and removal of shortcomings issued vide letter no. 3232 dated 28.12.2022, the FSC issued vide letter no. F.6/DFS/MS/2020/86 dated 30.01.2020, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended

> Signature of the Insp Ajay Kumar Sharma Name Designation ADO(Rohini)

D.B Mukherjee DO (NW)

12/03/ws

Ly for kindpersol; and Separation from