

GOVRERMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI – 110001



No. F6/DFS/MS/2025/SZ/ 480

Date: 12.09.2025

FIRE SAFETY CERTIFICATE

Certified that the M.R. Charitable Trust Temple located at Plot No. HAF - 7, Sec. -12, Dwarka, New Delhi, comprised of basement, ground floor plus 01 upper floor, owned/occupied by M/s. M R Charitable trust, was earlier fire safety certificate issued by this department vide letter no. F6/DFS/MS/2018/SZ/2241 dated 04/10/2018. Now, the premises was re-inspected by the officer concerned of this department on 29.08.2025 in the presence Sh. Deepansh Kalra and found that premises have deemed complied with fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service 2010, and that the premises / building if fit for occupancy class group- D Assembly "Building" with effect from 12/09/1025 for a period of three years, subject of the conditions printed overleaf.

Issued on 12 6 9 2025 at New Delhi by

Chief Fire Officer

Copy to:

- The Joint Director (L&C), Bldg. Section, Vikas Sadan, INA, New Delhi.
- Secretary M.R. charitable Trust, B-4/200, Safdarjung Enclave, New Delhi.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. The compliance with regards to electrical installation, structural stability, set back area, occupancy and any deviation in construction etc. shall be verified from authority concerned.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.
- 9. Any flammable material for interior decoration is prohibited.
- 10. Basement shall be used strictly as per UBBL-2016 / as per approved plans.

INSPECTION REPORT 1. Name & address of the building :M.R. Charitable Trust Temple at Plot No. HAF - 7, Sec- 12, Dwarka, New Delhi 2. Type of occupancy : Group D, Sub Div -D-3 3. Type of case:-: Renewal Ground + 01 Upper floors 4. Details of previous FSC :F6/DFS/MS/2018/SZ/2241 DT. 04/10/2018 5. Fire safety directives No. : N/A 6. Date of inspection:-29/08/2025 7. Name of the inspecting officer : Sh. Rajinder Atwal (DO/SW), 8. Name & designation of officer From the building side : Sh. Deepansh Kalra 9. Year of construction : before 1986 Applicant's letter No : Nil dated : 12/08/2025 Minimum Standards on fire Requirement/ Provided at Remarks Prevention and fire safety U/R Existing fire MR/NMR site safety 33 arrangements 1. Approach to Building 1) Road width 30 mtr. Provided MR 2) Gate width 6 mtr. Located at MR main road 3)Width of internal road N/A N/A N/A Number, Width Type & Arrangement of Exits 2. A. Number of staircases 1. Upper floors 02 No. 02 No. MR 2. Basements 02 No. 02 No. MR B. Width of staircase 1. Upper floors 1.50 mtr. Provided MR each 2. Basements 1.50 Provided MR mtr.each C. Protection of exits 1. Fire check door N/A N/A N/A 2. Pressurization N/A N/A N/A D. No. of continuous 01 no. Provided MR staircase to terrace E. Width of corridor N/A N/A N/A N/A F. Door size N/A N/A Compartmentation 3. N/A 1) Fire check door N/A N/A 2) Sealing of electrical shafts N/A N/A N/A 3) Fire rating of shaft door N/A N/A N/A 4) Water curtain N/A N/A N/A 5) Fire Dampers N/A N/A N/A Smoke Management System 4. 1) Basements 12 ACPH Exhaust fans MR

2) Upper floors

5.

Fire Extinguishers

provided

Naturally Ventilated

MR

12 ACPH

N'S

	1) Total numbers	08 Nos.	Provided	MR 🐗			
	2) Types	ABC & CO2	Provided	MR			
	3) ISI marking	Required	Provided	MR			
6.	First-Aid Hose Reel						
	1)Total number of each floor	01	Provided	MR			
	2) Length of hose reel hose	30 m	Provided	MR			
	3) Nozzle diameter	5 mm	Provided	MR			
7.	Automatic Fire Detection & Alar	ming System	TTOVIGCO	IVIIX			
	1) Type of detectors (Beam)	N/A	N/A	N/A			
	2) Location of main panel	N/A	N/A	N/A			
	3) Location of repeater panel	N/A	N/A	N/A			
	4) Alternate source of power	N/A	N/A	N/A			
	5) Hooter's Location gr. floor	N/A	N/A	N/A			
8.	MOEFA	Required	Provided	MR			
9.	Public Address System	Required	Provided	MR			
10.	Automatic Sprinkler System		Tiovided	1			
- 3 T-10/	1) Basement	N/A	N/A	N/A			
	2) Upper floors	N/A	N/A	N/A			
	3) Sprinkler above false ceiling	N/A ·	N/A	N/A			
11.	Internal Hydrants	1100	1.07	1.00			
	1) Size of riser/down-comer	100 MM	Provided	MR			
	2) Number of hydrants per floor		Provided	MR			
	3) Hose box each floor	Required	Provided	MR			
12.	Yard Hydrants						
	1) Total number of hydrants	N/A	N/A	N/A			
	2) Hose box	N/A	N/A	N/A			
13.	Pumping Arrangement						
	1) Ground level						
	a) Discharge of main pump	N/A	N/A	N/A			
	b) Head of main pump	N/A	N/A	N/A			
	c) Number of main pump	N/A	N/A	N/A			
	d) Jockey pump out put	N/A	N/A	N/A			
	e) Jockey pump head	N/A	N/A	N/A			
	f) Stand by pump output	N/A	N/A	N/A			
	g) Stand by pump head	N/A	N/A	N/A			
	h) Auto starting/Manual stopping	N/A	N/A	N/A			
	2) Terrace level						
	a) Discharge of pump	900 LPM,180 LPM	Provided	MR			
	b) Head of pump	30m	Provided	MR			
	c) Power supply	Required	Provided	MR			
	d) Auto starting of pump	Required	Provided	MR			
14.	Captive Water Storage for Fire Fighting						
		N/A	N/A	N/A			

W

7	7
	Į.

	a) Draw-off assertion			
	- Connection	N/A	N/A	N/A
Ì	O OCI VICE INIO	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
*	d) Over head tank	15000 liter	Provided	MR
5.	Capacity Exit Signage.	1 1 1 1 1 1	4 41 5 1	
6.	Provision of Lifts.	Required	Provided	MR
	 a) Pressurization of lift shaft 	N/A	N/A	N/A
reside	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
47	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room			
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	Required *	Provided	MR
	e) Building floor plan	N/A	N/A	N/A
 Special Fire Protection System for Protection of special Risk, if any- 1. CO2 Fire Extinguisher Near Electric Panel 				MR

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of deemed compliance of minimum standard for fire prevention and fire safety measures as required under the rules, if approved, we may renew the FSC (fire safety certificate) issued vide letter no.F6/DFS/MS/2018/SZ/2241 dated 04/10/2018, under rule 35(6) of the Delhi Fire Service Rules 2010. Accordingly, FSC is recommended for approval & DFA is put up for kind perusal and signature please.

Signature of the Inspecting Officer

Name :- Rajinder Atwal Designation :- DO (CD)

Two M

8 19 2025

Principal Dinectal

cro to Sem

- 56 pg 125

1019120