

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No.F.6/DFS/MS/2025/NDZ/ 1077

Dated: 17/0 82025

FIRE SAFETY CERTIFICATE

Certified that the M.R. Modern Public School located at 3rd Pusta, Som Bazar, Sonia Vihar, Delhi-110094, building comprised of Ground plus two upper Floors but school is running on Ground plus one upper floor only owned / occupied by M.R. Modern Public School, was issued FSC vide letter No. F6/DFS/MS/2022/NDZ/School/867 Dated 08/08/22. The school building was re-inspected by the officer concerned of this department on 08/08/2025 in presence of Sh. Arun Kumar and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with Circular No. F16/Estate/CC/Fire Safety/2011/3298-3398 Dated 01/03/2011 issued by Director of Education and that the school building is fit for Ground plus one upper floor occupancy class "Educational" (Group-B) with effect from 7 / 08 /2025 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010.

Issued on 17/08/5 at New Delhi by.

(VIRENDRA SINGH) HIEF FIRE OFFICER

Copy to :-

1. The Manager, M.R. Modern Public School, 3rd Pusta, Som Bazar, Sonia Vihar, Delhi-110094.

2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi-110054.

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided their in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non-functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The from is available on WWW.dfs.Delhigovt.nic.in.



INSPECTION REPORT

1. Name & address of the building: M.R. Modern Public School, 3rd Pusta, Som

2. Building is comprised of Bazar, Sonia Vihar, Delhi-110094.

3. Type of Occupancy : G+2 (school running at G+1 upper floors only)

4. Type of Case : Educational : Renewal

5. Details of previous NOC : F6/DFS/MS/2022/NDZ/School/867 Dated 08/08/22

6. Fire Safety directives Letter No.: Circular No. 3298-3398 Dated 01/03/2011

8. Name of the Inspecting Officer: A.K. Jaiswal, D.O. (E.D.)

9. Name and designation of Officer

from the building side : Sh. Arun Kumar 10. Year of Construction

No	Minimum standards on fire prevention and fire safety U/R 33	: 2018 d through email Id-arungujjar6040@gmail.com dated 04/ ls on fire safety U/R 33 Cir. Requirements Site		08/2025 at Remarks MR/NMF	
1.	Access of building		Soft a resi		
	Road width	6 mtr			
	Gate width	N/A	6 mtr	MR	
	Width of internal road	N/A	N/A	N/A	
2.	Number, width, Type & Arrangement	to of onits	N/A	N/A	
	a. Number of staircases	S OI EXILS	10.11		
	Upper floors	01 nos.	04	March 199	
	Basements	N/A	01 nos.	MR	
	b. Width of staircases	N/A	N/A	N/A	
	Upper floors	1.50 m		1 1	
	Basements	N/A	1.54 m	MR	
	c. Protection of exits	IV/A	N/A	N/A	
	Fire check door	1			
	Pressurization	N/A	N/A	N/A	
	d. No of continuous staircase to	N/A	N/A	N/A	
	terrace	01 nos.	01 nos.	MR	
	e. Width Of Corridor	1.50 mtrs.	1.50 mtr	MR	
	f. Door Size	1.20 m	1.20 m	MR	
3.	Compartmentation	The state of the s	CERTIFICATION	1711	
	 Fire check door 	N/A	N/A		
	 Sealing of electrical shafts 	N/A	N/A	N/A	
. 1	Fire Rating of shaft door	N/A	N/A	N/A	
	Water Curtain	N/A	N/A	N/A	
	Fire Dampers	IVA	N/A	N/A	
١.	Smoke managements System	10			
	Basements	NI/A	11, 11	Y W	
Ī	Upper floors	N/A	N/A	N/A	
5.	Fire Extinguishers	N/A	N/A	N/A	
	Total numbers	04		11 PM	
	W.V. A	04 nos.	05 nos.	MR	
	• Types	ISI marked ABC/CO ₂	Provided	MR	
	IS marking	Required	Provided	MR	

MB

	First – Aid Hose Reels Total number		7.1					
ŀ	Total numbers on each flo	or	N/A		N/A		L	
	 Length of hose reel hose 		N/A		.44		N.	
	 Nozzle diameter 				N/A		N/	
• 7.	Automatic fire detection and the		IN/A		N/A		N/	
f	7. Automatic fire detection and alarming system Type of detector							
	 Location of Main Panel 		N/A		N/A			
			N/A		N/A	-	N/	
	 Location of Repeater Panel 		N/A		N/A	a T	N/A	
	 Alternate source of power 		N/A				N/A	
•	Hooters' Location				N/A	7-	N/A	
8.	MOEFA		N/A	1	N/A			
9.	Public Address Court		N/A			_ '	V/A	
10.	Automatic Sprinkler System		N/A		Provided		V/A	
	Basements	_			Provided	1	V/A	
	Upper Floor	_	V/A		N/A	-	_	
360	Sprinkler above false ceiling	!	V/A		N/A		I/A	
11.	Internal II	1	V/A	141	N/A		I/A	
	Internal Hydrants					- 1	/A	
	Size of riser/down- comer	I	I/A					
	Number of hydrants per floor	_	I/A		N/A	N	/A	
				100	N/A	N,	/A	
12.	Hose Box Vard II- 1	N	/A					
	Yard Hydrants		يستوح		N/A	N/	'A	
- 1	Total number of hydrants	N	/A	-	and the			
13.	Hose Box Pumping Arrangements	N	/A		N/A	N/	Ά	
	Ground Level	V In	TV L		N/A	N/	Α	
•	Discharge of main pump				- 7/			
4	Head of main pump	_	/A		N/A	1		
. >	Number of main pumps		/A		N/A	N/		
4	Jockey pump out put	-	/ A		V/A	N/		
4	Jockey pump head	N/			V/A	N/		
4	Standby Pump out put	N/		1	N/A	N/A		
4	Standby Pump Head	N/			N/A	N/A		
4	Auto Staring/Manual stopping	N/			V/A	N/A		
Pump House Access		N/A		N/A		N/A		
•	Terrace level	1.7	- MAII	1	I/A	N/A	1	
. >	Discharge of pump	N/	Δ	- 1	144			
4	Head of the pump	N/	1.571		/A	N/A		
Power cumby			N/A		N/A N/A		N/A	
A	Auto starting of pump	N//				N/A		
	aptive water Storage for fire fighting	14//	,	N	/A	N/A	Ğ.	
	Underground tank capacity	N/A		12.	,	1000		
	> Draw of connection	N/A			/A	N/A	9	
	Fire service inlet	N/A			/A	N/A		
	> Access to tank	N/A			/A /A	N/A		
	Overhead Tank capacity	N/A			/A	N/A N/A		
		N/A		N/		N/A	_	

16				Azadi Ka Amrit Mahotsa
16.	Provision of Lifts.			
	➤ Pressurization of Lift Shaft	N/A	N/A	N/A
	Tressurization of lift lobby	N/A	N/A	N/A
	Communication in lift Car	N/A	N/A	N/A
	Fireman's Grounding Switch	N/A	N/A	N/A
	➤ Lift Signage	N/A	N/A	N/A
17.	Standby power supply	N/A	N/A	N/A
18.	Refuge Area		23722	
	Total area	N/A	N/A	N/A
	➤ Location	N/A	N/A	N/A
19.	Fire control room	Kr L Serve		
	Detector system panel	N/A	N/A	N/A
	➤ Flow Switch Panel	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	➤ Battery backup	N/A	N/A	N/A
	➤ Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection Systems for Protection of special Risks, if any;	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found

functional at the time of inspection.

MS

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter No. F6/DFS/MS/2022/NDZ/School/867 dated 08/08/2022 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

> Signature of the Inspecting Officer Name: Ashok Kumar Jaiswal Designation: D.O. (East Division)

LIV Dy cro (NDX)