

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI - 110001

No. F6/DFS/MS/2025/ 236

Dated 22.05/2025

To,

The Assistant Engineer (E), HC-2,
PWD, HMED (C),
Lok Nayak Hospital, New Delhi.

Sub: Regarding issuance of fire safety at MRD block, Lok Nayak Hospital, New Delhi.

Sir,

This has reference to your letter no. fire/AE(E)/HC-II/PWD/2025-26/13 dated 21.04.2025, on the subject cited above, it is to inform that the site was inspected by the officers concerned of this department on 14/05/25 in the presence of Mr. Manish, AE and the following shortcomings were observed.

1. Fire check door serving to basement is not properly closed due to that complete Compartmentation cannot be achieved.
2. Door closers from fire check doors also found removed at some doors.
3. Openings horizontally/ vertically are not properly sealed.
4. Fire man lift switch found nonfunctional.

In view of above shortcomings, the application for issuance of FSC is rejected. The occupancy in the building without requisite fire safety arrangement shall be at risk and liability of owner /occupier of the building. The statutory /licensing authority may take necessary action as deemed fit.

Yours faithfully

(Atul Garg)
DIRECTOR

Delhi Fire Service

Copy to:

1. The Medical Superintendent, LNJP hospital, New Delhi.
2. The Assistant Engineer (E), Health maint. Elect. Division (C), PWD, LNJP, New Delhi.