

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001



No F 6 / DFS / MS / 2025/ School/WZ/ 1320

Dated:

FIRE SAFETY CERTIFICATE

Certified that the M.S. Memorial Public School located at E-106, Saini Vihar, Laxmi Park, Nangloi, Delhi-110041 comprised of Ground and Three upper floors was issued FSC by this department vide letter No F6/DFS/MS/School/WZ/2022/1140 dated 12.10.2022. The premises was re-inspected by the officer concerned of this department on 28.10.2025 in the presence of Sh. Rajiv Saini (Chairman), and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule D.O.E. Circular No. 3298-3398 dated 01/03/2011/ NBC (Part-IV) and that the building/ premise is fit for occupancy Group B Educational with effect from ...1.7.11. 2.2.5... for a period of three years, in accordance with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40, subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on 17 11 2025 at New Delhi, by

Dv. Chief Fire Officer

West Zone

Copy to: -

1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi- 110054.

2. The Principal, M.S. Memorial Public School located at E-106, Saini Vihar, Laxmi Park, Nangloi, Delhi-110041.

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

Name & address of the building: M.S. Memorial Public School located at E-106, Saini Vihar, Laxmi Park

Type of Occupancy

: Educational 3. Building Comprised of

: Ground + Three upper floors 4. Type of Case

5. Details of Previous NOC Renewal

F6/DFS/MS/School/WZ/2022/1140 Dated- 12/10/2022 6. Fire Safety directives letter No :

7. Date of inspection NBC Part-IV 8. Name of Inspecting Officer 28/10/2025

R.K.Sinha, ADO (Jawala Puri) 9. Name and designation of officers

From the building side : Sh. Rajiv Saini (Chairman)

	0. Year	of Construction	Sh. Rajiv Saini (Chai	irman)		
	l 1. Appl	icant's letter No.	2013	A ACREMICATION		
i.	Minimum Standards on fire		Diary No. 6779 dated 08/10/2025			
No	preven	tion and fire safety U/R 33	As per inspection rep dated 20/09/2022	port Provided at site	Remarks MR/NMR	
	Access to building					
		Road width	Accessible			
	•	Gate width	Accessible	Provided	MR	
	•	Width of internal road	NA Accessible	Provided	MR	
2.	Numbe	er, Width, Type & Arrangem	ent of Exits	NA	NA	
	a. Number of staircases					
		Upper Floors	01	02	MR (old case	
		Basements	NA NA	NA	NA	
	135.4	th of staircases	INA	INA	INA	
		Control Contro	1.5	16 016	MD (ald agg	
	•	Upper Floor	1.5 m	1.6 m & 1.5 m	MR (old case	
	• 1	Basements	NA '	NA	NA	
	c. Prot	ection of exits				
	•	Fire check door	NA	NA	NA	
	•	Pressurization	NA	NA	NA	
		of continuous staircases to ace	01	Provided	MR	
	e. Wi	dth of Corridor	1.5 m	Provided	MR	
	f. Do	or Size	1 m	Provided	MR	
3.	Comp	rtmentation				
		Fire check door	NA I	NA	NA	
			NA NA	NA	NA	
	•	Sealing of electrical shafts	NA NA	NA		
	•	Fire Rating of shaft door Water Curtain	NA NA	NA NA	NA NA	
	•	Fire Dampers	NA NA	NA NA	NA NA	
	• Cmake	Management System		IVA	INA	
4.	-		NA I	NA	NY.	
		Basements Unper floors	Required	Naturally Ventilated	NA MR	
	•	Upper floors		- variation ventuated	IVIK	
5.	Fire Extinguishers					
	•	Total numbers	9 Nos.	12 Nos.	MR	
	•	Types	ABC/ Co2 Type	Provided	MR	
	•	IS marking	Required	Provided	MR	
6.		Aid Hose Reels Total numbers on each floor	01 Nos.			
	•	Length of hose reel hose	30 m	Provided	MR	
	-	Nozzle diameter	5 mm	Provided	MR	
	•			Provided	MR	
7.	Autom	atic fire detection and alarmin	g system			
	·	Type of detectors	NA NA	NA		
		Location of Main Panel	NA		NA	
		Location of Repeater Panel	NA	NA	NA	
	•	Alternate source of power	NA	NA NA	NA	
-		l.	1	NA	NA .	

	• Hootone? I	NA		100		
3.	Hooters' Location MOEFA	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	NA	NA		
	Public Address System	NA	NA	NA NA		
0.	Automatic Sprinkler System NA NA NA NA					
- 1	a Davis					
Ì	Ground Floor	NA NA	NA NA	NA NA		
1	Contract to the second	NA NA	NA NA	NA NA		
11.	oprimiter above raise certing	NA	NA	NA		
1.	Internal Hydrants • Size of riser/down-comer	NA	NIA	NA NA		
	Number of hydrants per floor	NA NA	NA NA	NA NA		
	Hose Box	NA ·	NA NA	NA NA		
12.	Yard Hydrants					
	Total number of hydrants					
	Hose Box	NA NA	NA NA	NA NA		
13.	Pumping Arrangements	144	13/4			
	• Ground Level ➤ Discharge of main Pump	NA	NA	. NA		
	were speed to seems to their	NA NA	NA NA	NA		
	➤ Head of Main pump	(Sections)	1500	NIA		
	> Number of main pumps	NA	NA	NA		
	> Jockey Pump out put	NA	NA NA	NA NA		
	> Jockey pump head	NA	NA NA	NA NA		
	> Standby Pump out put	NA NA	NA NA	NA		
	Standby Pump HeadAuto Starting/Manual	· NA	NA NA	NA		
	Stopping		96/186/000			
	> Pump House Access	NA	NA	NA		
	Terrace level					
9	Discharge of pump	450 lpm	450 lpm	MR		
		40 m	Provided	MR		
	➤ Head of the pump		Provided	MR		
	> Power Supply	Required	Provided	MR		
10 00	> Auto Starting of pump	Required	Flovided	IVIIC		
14.	Captive Water Storage for fire fighting		NA	NA		
	 Underground tank capacity 	NA NA	NA NA	NA NA		
	> Draw-off connection	NA NA	NA NA	NA NA		
	> Fire service inlet	NA NA	NA NA	NA NA		
	> Access to tank	10,000 ltrs	Provided	MR		
1.5	Overhead Tank capacity Exit Signage.	Required	Provided	MR		
15.						
16.	Provision of Lifts.			84.4		
	Pressurization of Lift Shaft	NA	NA	NA		
	Pressurization of Lift lobby	NA	NA NA	NA NA		
	Communication In lift Car	NA	NA			
	Fireman's Grounding Switch	NA	NA	NA		
	Lift Signage	NA	NA	NA		
17.	Standby power supply	NA	NA	NA		
18.						
10.		NA	NA	NA		
	> Total Area	NA	NA	NA		
	► Location Fire Control Room					

	400		35		
\	6.		NA	NΛ	NA
		Detector System Panel	NA NA	NA	NA
N	•	Flow Switch Panel	NA NA	NA	NA
1	•	PA System Panel		NA	NA
F		Battery backup	NA		NA
-			NA	NA	NA
	•	Building Floor Plans	NA	NA	IVA
20.	Special Protect	Fire Protection System for ion of special Risks, if any:	AMERICAN AND THE STATE OF THE S		

The fire protection systems provided in the building were tested, checked and found some

observations at the time of inspection.

Keeping in view of deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, it is **recommended to renew** the fire safety certificate issued vide letter no F6/DFS/MS/School/WZ/2022/1140 dated 12/10/2022 under Rule 37 of the Delhi Fire Service Rules, 2010.

Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO (Jawala Puri).