GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001

ि आज़ादी व अमृत महोत्सव

No.F6/DFS/MS/School/2025/NDZ/ 379

Dated: | 3/05/2025

To,

The Principal,
M. S. W. Public School,
B-369, Gali No. 05, Babu Nagar,
Karawal Nagar,
Delhi – 110094.

Subject: - Inspection Report in r/o M. S. W. Public School located at B-369, Gali No. 05, Babu Nagar Karawal Nagar, Delhi – 110094.

Sir,

Please refer to your outdoor diary no. 896 dated 23/04/2025 on the subject cited above. In this connection, it is to inform you that the site was visited by officer concerned of this department on dated 05/05/2025 and observed that the shortcoming has still not complied with as issued by this department vide letter no. F6/DFS/MS/School/NDZ/2024/711 dated 16/10/2024 (copy enclosed).

In view of above, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Encl: As Above

Yours faithfully,

DIRECTOR DICDELHI FIRE SERVICE

Copy to: -

1. The Dy. Director of Education, Delhi Municipal Corporation, 419, Udyog Sadan, Patparganj Industrial Area, Delhi – 110092.



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELHI FIRE SERVICE: NEW DELIII- 110001

P1.5

No. F6/DFS/MS/School/NDZ/2024/ 7//

Dated: / 6/10/2024

To.

The Principal, M.S.W Public School B - 369, Gali No. 5, Babu Nagar, karawal Nagar, Delhi - 110094.

Subject: - Regarding grant of Fire Safety Certificate in r/o M.S.W Public School located at B -369, Gali No. 5, Babu Nagar, karawal Nagar, Delhi – 110094.

This has a reference to your Outdoor Dairy No. 6999 dated 25.09.2024, on the subject cited above. In this connection, it is to inform you that premises was inspected by the officer concerned of this department on 08/10/2024 in the presence of Mr. Rohan Malik (Manager) and observed that building comprised of Ground plus three upper floors.

- Following shortcomings were observed during time of inspection: 1. One Staircase of width 1.40 meters are provided against requirement of two width 1.50 meters each.
- Fire Extinguishers not provided.
- 3. First-Aid-Hose Reel at each floors not provided.
- 5. Over head water storage tank of 10,000 liters capacity is required exclusively for firefighting is not
- 6. Exit & floors Signage's not provided in strategic location in the building.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary Yours faithfully, action as deemed fit.

Copy to:-

- 1. The Dy. Director of Education, B Block, Yamuna Vihar, Delhi 110053.
- 2. The Manager, M.S.W Public School located at B 369, Gali No. 5, Babu Nagar, karawal Nagar, Delhi - 110094.