्री १३६ आज़ादीका अमृत महोत्सव

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No.F.6/DFS/MS/EH/2025/SZ/261

Dated. 27. 19.7. 12025

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style of M/s Musical Restaurant Pvt Ltd. located at Second floor, Shop No 201, DDA commercial complex, Hauz Khas, New Delhi-110016 comprised of Basement, Ground plus 02 Upper floor owned/occupied by Mr. Rajneesh Negi was issued Fire Safety Certificate department vide letter no. F6/DFS/MS/EH/SZ/2019/1403 dated this 09/07/2019. The restaurant premise was re-inspected by the officer concerned of this department on 27/06/2025 in the presence of Mr. Mohan Kumar (Manager) of the restaurant and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class D "Assembly Building" (Restaurant running at 2nd Floor only) and validity up to 31/03/2028 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on $\frac{07}{\sqrt{07}}/2025$ at New Delhi by

(ATUL GARG) DIRECTOR DELHI FIRE SERVICE

Copy to: -

- The Dy. Health Officer, Public Health Department, South Zone, Green Park, Delhi-110016 (Ref. MCD Portal ID 2025062110407 dated 21/06/2025)
- 2. The Joint C.P (Lic/Branch) 1st Floor, P S Defence Colony, New Delhi 110049

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."



1. Name & address of the building: Musical Restaurant Private Ltd. 201, 2nd floor, DDA commercial

Name & address of the building: Musical Restaurant Private Ltd. 201, 2nd floor, DDA commercial

complex, Aurobindo Place, Hauz Khas, New Delhi-110016 2. Type of Occupancy

: Assembly Building, Group-D, Restaurant 3. Comprised of

4. Type of Case : Ground plus two upper floor

: Renewal [Restaurant at 2nd Floor Only] 5. Details of Previous NOC

: F6/DFS/MS/EH/2022/SZ/170 dated 10/06/2022

6. Fire Safety directives letter No: Nil 7. Date of inspection

: 27/06/2025

8. Name of Inspecting Officer : Sh. Suman Kumar, ADO

9. Name and designation of

officers from the building side : Sh. Mohan Kumar

10. Year of Construction : Prior to 2009 [DDA shopping Complex] : MCD Portal ID 2025062110407 dated 21/06/2025 11. Applicant's letter No. Remarks S. No. Minimum Standards on fire prevention Provided at Requirement MR/NMR site and fire safety U/R 33 Rule 35(6) 1. Access to building MR 12m 9m Road width -NA--NA--NA-Gate width -NA--NA--NA-Width of internal road Number, Width, Type & Arrangement of Exits 2. a. Number of staircases MR 2 2 Upper Floors -NA--NA--NA-Basements b. Width of staircases MR 1.35m (each) 1.25m (each) Upper Floor -NA--NA--NA-Basements c. Protection of exits -NA--NA--NA-Fire check door -NA--NA--NA-Pressurization d. No. of continuous staircases to terrace e. MR One One MR 1.5m 1.5m Width of Corridor MR 2m & 1.7m 1m Door Size Compartmentation 3. -NA--NA--NA-Fire check door -NA--NA--NA-Sealing of electrical shafts -NA--NA--NA-Fire Rating of shaft door -NA--NA--NA-Water Curtain -NA--NA--NA-Fire Dampers Smoke Management System 30 ACPH 4. -NA--NA-Basements 12 ACPH **Exhaust Fan** MR Upper floors Fire Extinguishers 6 No's 5. 6-No's Total numbers MR ISI ABC-4 No's MR Types Marked CO₂-2 No's I\$ marking MR First-Aid Hose Reels Total numbers on each floor One One 6. MR Length of hose reel hose 30m 30m MR 5mm Nozzle diameter 5mm MR Automatic fire detection and alarming system Type of detectors 7. -NA--NA--NA-Location of Main Panel -NA--NA--NA-

M-27

आज़ादीका अमृत महोत्सा

	M-27		-NA-	-NA-
	Location of Repeater Panel	-NA-	-NA-	-NA-
	Alternate source of power	-NA- -NA-	-NA-	-NA-
	Hooters' Location	1000000	Provided	MR
3.	MOEFA	Required	-NA-	-NA-
).	Public Address System	-NA-	-NA-	
10.	Automatic Sprinkler System		I	-NA-
	Basement	-NA-	-NA-	-NA-
	Ground Floor	-NA-	-NA-	-NA-
	 Sprinkler above false ceiling 	-NA-	-NA-	-NA-
11.	Internal Hydrants	T 7222		MR
	Size of riser/down-comer	100mm	Provided Provided	MR
	 Number of hydrants per floor 	One	Provided	MR
	Hose Box	One	Flovided	IVAL
12.	Yard Hydrants	-NA-	-NA-	-NA-
	Total number of hydrants	-NA-	-NA-	-NA-
	Hose Box	-14/4-	-11/4-	
13.	Pumping Arrangements			
	Ground Level District Power	-NA-	-NA-	-NA-
	> Discharge of main Pump	-NA-	-NA-	-NA-
	➤ Head of Main pump	-NA-	-NA-	-NA-
	> Number of main pumps	-NA-	-NA-	-NA-
	> Jockey Pump out put	-NA-	-NA-	-NA-
	> Jockey pump head	-NA-	-NA-	-NA-
	Standby Pump out put	-NA-	-NA-	-NA-
	> Standby Pump Head	-NA-	-NA-	-NA-
	> Auto Starting/Manual Stopping	-11/1	-1411	1421
	Terrace level	450 I D) (450 T D) 4) AD
	> Discharge of pump	450 LPM 40m	450 LPM 40m	MR MR
	Head of the pumpPower Supply	Required	Provided	MR
	> Auto Starting of pump	Required	Provided	MR
14.	Captive Water Storage for fire fighting	1		
14.		-NA-	-NA-	-NA-
	 Underground tank capacity Draw-off connection 	-NA-	-NA-	-NA-
	Fire service inlet	-NA-	-NA-	-NA-
	Access to tank	-NA-	-NA-	-NA-
	 Overhead Tank capacity 	10,000 Lts.	Provided	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.		2	No. Vonebled
-224	Pressurization of Lift Shaft	-NA-	-NA-	-NA-
-	Pressurization of Lift lobby	-NA-	-NA-	-NA-
	Communication In lift Car	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
	Fireman's Grounding SwitchLift Signage	-NA-	-NA-	-NA-
17.	Standby power supply		activate.	SENOTE N
18.	Refuge Area.	Required	Provided	MR
18.				
	Total AreaLocation	-NA-	-NA-	-NA-
19.	Fire Control Room	-NA-	-NA-	-NA-
	Detector System Panel	-NA-	-NA-	-NA-
	Flow Switch Panel			100000000000000000000000000000000000000
	PA System Panel	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-

t





The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/EH/2022/SZ/170 dated 10/06/2022, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature.

20.

30/06/2025

Signature of Inspecting Officer Name: Sh. Sunan Kumar Designation: ADO

DO (8D) Much 396ps

Of THE SOS)

Dinetar May

Start May

My 1 Gm

F.T. letter is lot up to

Signature My

03/07/2125

Tirector My

V Hadead