GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No F.6/DFS /MS/2025/WZ/ S77

Dated 29 / 10 /2025

FIRE SAFETY CERTIFICATE

Certified that the N. N. Mall at Plot No-15, Manglam Place District Center, Sector- 03 Rohini, Delhi-110085, comprised of Double Basement, Ground & 05 upper floors only owned/ occupied by N.N. Mall was granted Fire Safety Certificate by this department vide letter no. F6/DFS/MS/2021/WZ/506 Dated: 14/10/2021. The premises was inspected by the officers concerned of this department on dated 09/10/2025 in the presence of Sh. Harender Singh (Mall Manager) and observed that all the fire prevention and fire safety arrangements as provided found in good working condition and the premises have deemed complied with the requirements under Rule 33 of the Delhi Fire Service Rules, 2010 and building premises is fit for occupancy class "Mixed Mercantile Building" with effect from 29.10.1205... for a period of three years, in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on .29/10/2025..... at New Delhi by.

(S.K Dua) 1875

Dy. Chief Fire Officer (WZ)

Delhi Fire Service

Copy to:-

1. Sh. Harender (Mall Manager), N. N. Mall at Plot No-15, Manglam Place District Center, Sec-03 Rohini, Delhi-110085.

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape shall be kept free from any type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipment and method of smooth and speedy safe evacuation of occupants in case of emergency

3. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seem during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities. This Fire Safety Certificate is valid only for permanent building structure as per plan.

5. This fire safety certificate may not be treated in any case of regularizations of unauthorized construction/unauthorized use of land or activities, if any.

6. Basement shall not be used for any other purpose except as specified in UBBL, subject to permission from concerned local authority.

7. The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on the official website of Delhi Fire Service i.e. www.dfs.delhigovt.nic.in.

8. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

9. Banquet Hall/ Eating House running in the said building shall obtain separate FSC/Renewal from this department.

INSPECTION REPORT

1. Name & address of the building

: N.N. Mall at Plot No-15, Manglam Place District Center,

Sec- 03 Rohini, Delhi-110085.

2. Type of Occupancy

: Mixed Mercantile

3. Composition of building

: Double Basement, Ground & 05upper floors only

4. Type of Case

: Renewal

5. Details of previous NOC

: F6/DFS/MS/2021/WZ/506 Dated: 14/10/2021

6. Fire Safety directives letter No

: F.6/DFS/MS/HQ/BP/2003/1925 Dated: 25/08/2003

7. Date of inspection

: 09/10/2025

8. Name of the Inspecting Officers

: C.L. Meena (ADO/Rohini) & A.K. Jaiswal (DO/NW)

9. Name and designation of officers

: Sh. Harender Singh (Mall Manager)

from the building side 10. Year of Construction

Applicant's letter No.

: Letter No. Nil & DFS Dairy No.5759 Dated: 10/09/2025

S. No	. Minimum Standards on fire prevention and fire safety U/R 33	BBL & NBC/Rule35(6) Requirement	Provided at site	Remarks MR/NMR
1	Access to building			- 1 m
-	Road width	09m	09m	MR
	Gate width	05m	Directly Accessible	MR
	 Width of internal road 	NA	NA	NA
2	Number, Width, Type & Arrangement	t of Exits		
}	a. Number of staircases			
	Upper Floors	02 nos.	02 nos.	MR
	Basements	04 nos.	05 nos.	MR
	b. Width of staircases			
	Upper Floors	1.50m	Provided	MR
	Basements	1.50m	Provided	MR
	c. Protection of exits			
	Fire check door	Required in basement	Provided	MR
	Pressurization	Required	Provided	MR
	d. No. of continuous staircases to terrace	05	05	MR
	e. Width of Corridor	NA	NA	NA
1	f. Door Size	1.0m	1.0m	MR
	Compartmentation.			
	Fire check door	Required in basement	Provided	MR
	 Sealing of electrical shafts 	Required	Provided	MR
	 Fire Rating of shaft door 	Required	Provided	MR
	Water Curtain	NA	NA	NA
	Fire Dampers	NA	NA	NA
5	Smoke Management System.			
	Basements	30 a/c per hour	Exhaust Fan	MR
	Upper floors	12 a/c per hour	Natural Ventilated	MR

1	Fire Extinguishers	NIE2		-		
	Total numbers	50nos	Provided			
	 Types 	Wco2/DCP type		MR		
	ISI marking		ABC/DCP/WCO2	MR		
+	First-Aid Hose Reels.	Yes	Yes	MR		
-						
	Total numbers on each floor	02 at each floor	Provided	MR		
	Length of hose reel hoseNozzle diameter	30mm	30mm	NA		
	Automatic fire detection	05mm	05mm	NA		
	Automatic fire detection and alarming Type of detectors					
	Location of Main Panel	Required	Provided	MR		
		GF	Provided	MR		
	 Location of Repeater Panel Alternate source of power 	Each floor	Provided	MR		
	Hooters' Location	Required	Provided	MR		
8		Required	Provided	MR		
9	MOEFA Public Add	Required	Provided	MR		
10	Public Address System.	Required	Provided	MR		
- 0	Automatic Sprinkler System.		Property and the second	1411		
	Basement	Required	Provided	MR		
	• Upper Floor	Required	Provided	MR		
	Sprinkler above false ceiling	Required		MR		
11	Internal Hydrants					
	 Size of riser/down-comer 	150mm	150mm	MD		
	Number of hydrants per floor	02 nos.	02 nos.	MR MR		
12	Hose Box Vond Hard	02 nos.	02 nos.	MR		
12	Yard Hydrants.	1		WII		
	Total number of hydrants	Required	Provided	MR		
	Hose Box	Required	Provided	MR		
13	Pumping Arrangements.	· ·		IVIK		
	Ground Level					
	Discharge of main Pump	2280 LPM	Provided	MR		
	Head of Main pump	60m	Provided	MR		
	Number of main pumps	02 nos.	Provided			
	Jockey Pump out put	180 LPM	Provided	MR MR		
	> Jockey pump head	60M				
	Standby Pump out put	2280 LPM	Provided Provided	MR		
	> Standby Pump Head		45/1622/0435/245	MR		
		80m Required	Provided Provided	MR		
	Auto Starting/ Manual stopping	25		MR		
	> Pump House Access	Required	Provided	MR		
	Terrace level					
	➤ Discharge of pump	02 nos. of 450	Provided	MR		
	> Head of the pump	LPM 40m	Provided	MR		
	ALL PERSONNELLES - CHALLES		Provided	MR		
	> Power Supply	Required	1 TOVIUCU	IVIII		

d *

7	Cantive	Water Storage for fire fighting.		Provided	MR
4		Jnderground tank capacity	2,00,000 LTR	Provided	- MR
			Required		MR
	**	Draw-off connection	Required	Provided	MR
	 Fire service inlet Access to tank 	Required	Provided		
			Provided	MR	
		30,000 LTR	#:	MR	
		Overhead Tank capacity	Required	Provided	. vi
5	Exit Si	gnage.		D wided	MR
6	Provisi	on of Lifts.	Required	Provided	N/A
2 80		Pressurization of Lift Shaft	N/A	N/A	Maria (1985)
		Pressurization of Lift lobby	Deguired	Provided	MR
	Communication In lift Car	Required	Provided	MR	
	•		Required		MR
	•	• Fireman's Grounding Switch	Required	Provided	
		Lift Signage	Required	Provided	MR
17	Stand	by power supply	Required		
			N/A	N/A	
18	Refug	e Area. Total Area	N/A	N/A	N/A
		Location	N/A	N/A	117
Λ	12			Provided	MR
19	Fire Control Room.	Detector System Panel	GF	N/A	N/A
		Flow Switch Panel	N/A	N/A	N/A
		PA System Panel	N/A	NA NA	NA
		Batter backup	NA Required	Provided	MR
	. 1	Building Floor Plans	NA	NA	NA
20	Speci	al Fire Protection Systems for ction of special Risks, if any:	INA	2004	

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition, at the time of inspection. The observations/ shortcomings issued and communicated vide this department letter of even no. F6/DFS/MS/WZ/2025/146 dated 03/04/2025 have been complied by the management.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in NBC Part-4, it is recommended for renewal of fire safety certificate issued vide this department letter of even no. F6/DFS/MS/2021/WZ/506 Dated: 14/10/2021.

Signature of the inspection Officer

Name :- C.L. Meena Designation:- ADO/Rohini Signature of the Inspecting Officer

Name:- A.K. Jaiswal Designation:- DO/NW