

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001

अमृत महोत्सव

No. F6/DFS/MS/SCHOOL/2025/NDZ/ 304

Dated: 0 | /0 2025

To,

The Principal,
Nalanda Cambridge School
Kh. No. 1146/787, Gali No. 13,
Nalanda Chowk, Vishnu Garden,
Main Road Mandawali Fazalpur,
Delhi – 110092.

Subject: - Inspection Report in r/o Nalanda Cambridge School located at Kh. No. 1146/787, Gali No. 13, Nalanda Chowk, Vishnu Garden, Main Road Mandawali Fazalpur, Delhi – 110092.

Sir,

Please refer to your outdoor diary no. 585 dated 15/04/2025 on the subject cited above. In this connection, it is to inform you that the site was visited by officer concerned of this department on dated 26/04/2025 and observed that the shortcoming has still not complied with as issued by this department vide letter no. F6/DFS/MS/School/NDZ/2025/115 dated 17/02/2025 (copy enclosed).

In view of above, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Yours faithfully,

Encl: As Above

DIRECTOR DELHI FIRE SERVICE

Copy to: -

1. The Dy. Director of Education, Delhi Municipal Corporation, 419, Udyog Sadan, Patparganj Industrial Area, Delhi – 110092.



## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

प्रिक् आज़ादी म अमृत महोत्सर

No. F6/DFS/MS/School/NDZ/2025/ 115

Dated: 17/02/2025

To,

The Principal,
Nalanda Cambridge School
Kh. No. 1146/787, Gali No. 13,
Nalanda Chowk, Vishnu Garden,
Main Road Mandawali Fazalpur,
Delhi – 110092.

Subject: - Regarding grant of Fire Safety Certificate in r/o Nalanda Cambridge School located at Kh. No. 1146/787, Gali No. 13, Nalanda Chowk, Vishnu Garden, Main Road Mandawali Fazalpur, Delhi – 110092.

Sir,

This has a reference to your Outdoor Diary No. 11740 dated 24/01/2025, on the subject cited above. In this connection, it is to inform you that premises was inspected by the officer concerned of this department on 08/02/2025 in the presence of Mrs. Sunita (In- Charge) and observed that building comprised of ground plus two upper floors.

## Following shortcomings were observed during time of inspection:

- 1. First-Aid-Hose Reel at each floors provided but not functional.
- 2. Internal Hydrant provided at ground floor only that is also not functional.
- 3. Fire pump of 450 LPM provided but not functional.
- 4. Over head water storage tank of capacity 10,000 liters not provided.
- 5. Exit & floors Signage's not provided in strategic location in the building.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

DIRECTOR

O C DELHI FIRE SERVICE

Copy to:-

1. The Joint Director of Education, MCD, Udyog Sadan, Plot No.419, FIE, Patargang, Delhi - 110092.