

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2025/ 286

Dated: 2.9/.04./2025

FIRE SAFETY CERTIFICATE

Certified that the Nancy Dx. located at 7779, Ram Nagar, A.K. Road, Pahar Ganj, New Delhi comprised of Ground + 04 Upper floors, Ground floor (Reception + 02 guest rooms) 1st floor to 3rd floor (04 guest rooms at each floor), 4th floor not in use as per affidavit dated 21.04.2025 total 14 guest rooms up to third floor only owned/occupied by Hotel Nancy Dx. was earlier granted FSC by this department vide letter No.F6/DFS/MS/GH/NDZ/2022/124 dated 02/03/2022. Now, the premises was re-inspected by the officer concerned of this department on 19/04/25 in the presence of Mr. Punit Kumar and found that the said guest house building has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (Reception + 02 guest rooms) 1st floor to 3rd floor (04 guest rooms at each floor) total 14 guest rooms up to third floor only with effect from 99 out 12025 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued - ot 25 - at New Delhi by.

Director Delhi Pire Service

Copy to:-

- 1. The Commissioner, North MCD, Civic Centre, New Delhi: to ensure the occupancy as detailed above.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. ID No. 2025040405546 dated 04.04.25.
- 3. The Manager, Nancy Dx. at 7779, Ram Nagar, A.K. Road, Pahar Ganj, New Delhi.

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. This FSC is valid from ground to third floor only
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. The compliance with regards to electrical installation, structural stability, set back area, occupancy and any deviation in construction etc. shall be verified from authority concerned.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.
- 9. Any flammable material for interior decoration is prohibited.

4-21

INSPECTION REPORT 1. Name & address of the building:-

Nancy Dx. located at 7779, Ram Nagar, A.K. Road, Pahar Ganj, New Delhi 2. Type of occupancy:-Residential, Sub Division-A-1

Gr. + 04 Upper floors (total 18 Guest rooms)

Ground floor (Reception + 02 guest rooms) 1st floor to 3rd floor (04 guest rooms at each floor), 4th & & terrace floor (lift room + airtel antenna) not in use above third

3. Type of case:floor as per affidavit dated 21.04.2025. 4. Details of previous FSC:-Renewal

F6/DFS/MS/GH/NDZ/2022/124 dated 02/03/2022. 5. Fire safety directives No.-

6. Date of inspection:-19.04.2025.

7. Name of the inspecting officer:-Sh. Suman Kumar (ADO)

8. Name & designation of officer From the building side:-

9. Year of construction:-Mr. Punit Kumar 10. Applicant's letter No:-2001

S.No.	Minimum Standards on fire		940405546 dated 04	
	Prevention and fire safety	Requirement	Provided at site	Old Case Remarks
	U/R 33	Existing fire	at Site	MR/NMR
		safety		MK/NMK
1.	Access to Building	arrangements		
	1) Road width			
	2) Gate width	N/A	06 mtr.	MR
		N/A	N/A	N/A
2.	3) Width of internal road	N/A	N/A	N/A
	Number, Width Type & Ar	rangement of E	xits	IVA
	- 1 Trainfoct of Staircases			
	 Upper floors Basements 	01 No.	01 No.	MR
	B. Width of staircase	N/A	On the street	N/A
	1. Upper floors			1,011
	· ·	0.80 mtr.	1.15 mtr.	MR
	2. Basements	N/A	N/A	N/A
	C. Protection of exits			IVA
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous	01	01	MR
	staircase to terrace			
-	E. Width of corridor	N/A	N/A	N/A
2	F. Door size	1 mtr.	1 mtr.	MR
3.	Compartmentation			
	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System			
	1) Basements	N/A	N/A	N/A
	2) Upper floors	12 ACPH	Natural Ventilation/exh aust fan	MR
5.	Fire Extinguishers		aust fall	

N. 32

		M.	52				
	2) Types		ABC	& CO	2 ABC	& CO	2
	3) ISI marking		Requir		Provid		14
6.	First-Aid Hose Reel		regun	-	TIOVIG	leu	M
	1) Total number of each	floor	01		01		-
	2) Length of hose reel h		30 m	-			M
	3) Nozzle diameter	-	5 mm		30 m		M
7.	Automatic Fire Detecti	or P	Alam.	- 0	5 mm		MI
	1) Type of detectors CO	on &	Alarmin	g Syst			
	Type		Require	D	Provide	d	MR
	2) Location of main pane	1	Cr. C				
	3) Location of repeater p	anal	Gr. floor		Provided		MR
	4) Alternate source of po	anel	Required		Provided		MR
	5) Hooter's Location	wer	Required		Provided		MR
8.	MOEFA		Gr. floor	the state of the s	Provided		MR
9.			Required		Provided		MR
10.	Public Address System		Required		Provided		MR
10.	Automatic Sprinkler Sys						
	1) Basement	_	N/A		N/A		N/A
	2) Upper floors	_	N/A		N/A		N/A
	3) Sprinkler above false ceiling	1	N/A		N/A		N/A
11.	Internal Hydrants						
-	1) Size of riser/down-come	1.	-1.				
	2) Number of hydrants per	er N	V/A	_	V/A		N/A
	floor	N	I/A	N	I/A		N/A
	3) Hose box	-	1/4				
12.	Yard Hydrants	N	/A	N	/A		N/A
_	1) Total number of hydrants	NT S	/A	1	/ 4		
	2) Hose box	N/		N/			N/A
3.	Pumping Arrangement	14/	11	N/	A	1	N/A
	1) Ground level	N/	'A	N/	'A		,
	a) Discharge of main	N/		N/.			/A
	pump		*	11/.	А	N.	/A
	b) Head of main pump	N/A	Α .	N/A	4	27	
	c) Number of main	N/A		N/A		N/	
	d) Jockey nume and			1		N/.	A
	d) Jockey pump out pute) Jockey pump head	N/A		N/A		N/A	4
-	f) Stand by pump output	N/A		N/A	(N/A	
	g) Stand by pump head	N/A		N/A		N/A	
	h) Auto starting/Manual	N/A N/A		N/A		N/A	
_	stopping	IVA		N/A		N/A	
-	2) Terrace level						
-	a) Discharge of pump	225	LPM	225 I	DM		
	b) Head of pump	30 m	tr.	30 m	tr T	MR	
-		Requ	ired	Provi		MR	
	c) Power supply					MR	
-	d) Auto starting of pump	Requ	ired	Provid	ded	MD	
	d) Auto starting of pump	Requ		Provid	ded	MR	
. (d) Auto starting of pump Captive Water Storage for Fire	Requ		Provid	ded	MR	
. (d) Auto starting of pump Captive Water Storage for Fir 1) Under ground tank	Requ	ıting				
. (d) Auto starting of pump Captive Water Storage for Fir 1) Under ground tank capacity	Requ e Figh N/A	ıting	Provid		MR N/A	
. (d) Auto starting of pump Captive Water Storage for Fir 1) Under ground tank capacity a) Draw-off connection	Requ e Figh	nting				

Day

MR MR MR MR MI

1		N-3.	>	
	c) Access to tank	N/A	N/A	
	d) Over head tank	2500 ltrs.	2500 Ltr.	N/A
	capacity	10.5	2300 Ltr.	MR
15.	Exit Signage.	Required	Provided	
16.	Provision of Lifts.	Tan-ou	Flovided	MR
	 a) Pressurization of lift shaft 	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift	Required	Provided	MR
	d) Fireman's switch	Required	Provided	MR
17.	e) Lift signage	Required	Provided	MR
18.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A N/A
	e) Building floor plan	N/A	N/A	N/A
0.	Special Fire Protection System Risk, if any:	n for Protection		NA NA

The fire protection systems provided in the guest house building were randomly tested, checked and found functional at the time of inspection.

. In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No. F6/DFS/MS/GH/NDZ/2022/124 dated 02/03/2022, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

Signature of the Inspecting Officer

Name: - Suman Kumar Designation: - ADO

Director