No. F6/DFS/MS/School/NDZ/2025/ 842

FIRE SAFETY CERTIFICATE

Certified that the Nand Lal Modern Public school located at A- Block, Sushila garden Fanne Khan More, Mandoli, Delhi - 110093 Comprised of ground plus one upper floors, owned / occupied by Nand Lal Modern Public school was issued FSC vide letter No. F6/DFS/MS/School/2021/NDZ/907 dated 29/10/2021. The School building have complied with the fire prevention and fire safety requirements in accordance with the Circular No.F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated01/03/2011 issued by the Director of Education and re-inspected by the officer concerned of this department on 26/06/2025 in presence of Mr. Sanjay Kumar Sharma (Manager) of the school and that the school building is fit for occupancy class "Educational Building" (Group-B) with effect from 02 /07/2025 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010 & also conditions printed bellow.

02 07 20 25 _ at New Delhi by. Issued on

Copy to:-

- 1. The Dy. Director of Education, D Block, Anand Vihar, Delhi 110092.
- 2. The Principal, Nand Lal Modern Public school located at A- Block, Sushila garden Fanne Khan More, Mandoli, Delhi - 110093.

Conditions for the validity of Fire Safety Certificate

- The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub 1. rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- All the means of escape shall be kept free of all the type of obstruction all the time. 2.
- All the employees shall be acquainted with the use and maintenance of all fire equipment's and method 3. of smooth and speedy safe evacuation of occupants in case of emergency.
- All the firefighting equipment's shall be maintained in perfect working condition all the time and any 4. lapse rendering non-functional of fire safety measures, management shall be responsible.
- The clarification with regards electrical installation, ventilation, structure stability set back areas, 5. occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction 6. unauthorized use of land if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of 7. Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

FILM HILE

		INSPE	CTION REPORT					
1.	Nam	e & address of the building	Nand Lal Modern Public school located at A-Block, Sushila garden Fanne Khan More, Mandoli, Delhi - 110093.					
2.	Build	ding is comprised of	Ground plus one	upper floor only	ur pad V			
3.		e of occupancy	Educational					
4.		e of case	Renewal					
5.	-	ils of previous FSC	20/10/2021	F6/DFS/MS/School/2021/NDZ/907 dated 29/10/2021				
6.	Fire	safety directives letter no.	F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011					
07.	Date	of inspection	26/06/2025					
08.		ne of the inspecting officers	Veshwant Singh Meena ADO (L.N)					
09.	Nan	ne of the designation of officer in the building side	Mr. Sanjay Kumar Sharma (Manager)					
10		r of construction	2006 & 2011					
10.	A-10.5- 10.5	licant's letter no.	Email dated 19/0)6/2025	Remarks			
11. S.No	I	Minimum standard of fire evention and fire safety U/R	Circular Requirement	Provided at site	MR/NMR			
01.	Access to Building:			7 mtrs. MR				
To	A Road width		6.0 mtrs.	N/A	N/A			
	В	Gate width	N/A N/A	N/A N/A				
1.0			noment of Exits:		The Co			
02.	Nu	mber, Width, Type and Arra	ingement of Zame	and place of the con-	nt 5			
	A	Number of staircases	01 nos.	02 nos.	MR			
1		a Upper floor	N/A	N/A	N/A			
		C Basement	17/22	Astro-Lib	n tested			
	В	Width of staircases a Upper floor	1.50 mtrs.	1.0 mtrs & 0.80 mtrs	MR N/A			
		C Basement	N/A	N/A	IV/A			
		C Basement Protection of exits		NT/A	N/A			
	C	a Fire check door	N/A	N/A	N/A			
	.	b Pressurization	N/A	N/A	MR			
	D	No. of continuous	01 nos.	01 nos.				
	-	staircases to terrace Width of corridor	1.50 mtrs.	1.50 mtrs	MR MR			
	F	Door size	1.0 mtr	1.0 mtr.	IVIK			
03.	Compartmentation:		N/A	N/A	N/A			
	A	Fire check door	N/A N/A	N/A	N/A			
	В	Sealing of electrical shafts	N/A	. N/A	N/A			
	C	Fire rating of shaft door	N/A	N/A	N/A			
	D	Water curtain	N/A	N/A	N/A			
	E	Fire dampers	11/11					
04.	Sn	noke Management System:	N/A	N/A	N/A			
	A	Basement	N/A	N/A	N/A			
	В	Upper floor	11111					



05.		e Extinguisher:	04 nos.	04 nos.	MR			
8	A	Total numbers	ABC/CO ₂	ABC/CO ₂	MR			
1.4	В	Types	ISI Marked	ISI Marked	MR			
	C	ISI marking	ISI Warked		-3/2			
06.		st-Aid-Hose Reel:	N/A	N/A	N/A			
h	A	Total numbers of each floor	N/A	N/A	N/A			
-	В	Length of hose reel hose	N/A	N/A	N/A			
	C	Nozzle diameter	200 S 100 S		1111			
07.	Automatic Fire Detection and Alarming A Type of detectors		N/A	N/A	N/A			
	A	Location of main panel	N/A	N/A	N/A			
	B	Location of repeater panel	N/A	N/A	N/A			
	D	Alternate source of power	N/A	N/A	N/A			
	E	Hooters	N/A	N/A	N/A			
08.		OEFA:	N/A	N/A	N/A			
09	L BERTHAN	blic Address System:	N/A	N/A	N/A			
10.	Automatic Sprinkler System:							
10.	A	Basement	N/A	N/A	N/A			
	В	Upper floor	N/A	N/A	N/A			
	C	Sprinkler above false ceiling	N/A	N/A	N/A			
11.	Internal Hydrants:							
	A	Size of riser/down-comer	N/A	N/A	N/A			
	В	Number of hydrants per floor	N/A	N/A	N/A			
	C	Hose box	N/A	N/A	N/A			
12.	Ya	Yard Hydrants:						
	A	Total number of hydrants	N/A	N/A	N/A			
	В	Hose box	N/A	N/A	N/A			
13.	Pu	mping Arrangements:		IVA	19/4			
1	Ground level							
	A	Discharge of main pump	N/A	N/A	NI/A			
	В	Head of main pump	N/A	N/A	N/A			
	C	Number of main pumps	N/A	N/A N/A	N/A			
	D	Jockey pump out put	N/A	N/A	N/A			
	E	Jockey pump head	N/A	The state of the s	N/A			
	F	Standby pump out put	N/A	N/A	N/A			
	G	Standby pump head	N/A	N/A	N/A			
	H	Auto starting /manual stopping	N/A	N/A	N/A			
	I	Pump house access		N/A	N/A			
2	Terrace Level N/A N/A N/A							
	A Discharge of nump							
	B	Head of the pump	N/A	N/A	N/A			
	C	Power supply	N/A	N/A	N/A			
	D	Auto starting of pump	N/A	N/A	N/A			
		ratio starting of pump	N/A	N/A	N/A			

1 4	Guern Public school, Block Suskit						
14.	Captive Water Storage for Fire Fighting: Captive Water Storage for Fire Fighting: Captive Water Storage for Fire Fire Fighting: Captive Water Storage for Fire Fire Fire Fire Fire Fire Fire Fir						
	A Underground tank capacity N/A N/A						
-	B	Draw-off connection	N/A	N/A			
	C	Fire service inlet	N/A	N/A	N/A		
	D	Access to tank	N/A		N/A		
ŀ	E	Overl	N/A	N/A	N/A		
15.		Overhead tank capacity	N/A	N/A	N/A		
16.	EX	it Signage:		N/A	N/A		
10.	Provision of Lifts:		N/A	N/A	N/A		
	A	Pressurization of lift shaft	1 1777				
	B	Pressurization of lift lobby	N/A	N/A	N/A		
	C	Communication in lift car	N/A	N/A	N/A		
	D	Firemen's ground:	N/A	N/A	N/A		
ŀ	E	Firemen's grounding switch	N/A	N/A	N/A		
17.	==4	Lift signage	N/A	N/A	N/A		
18.	DIE	andby Power Supply:	NA	N/A	N/A		
28.5	Refuge Area:						
-	A	Total area	N/A	N/A	N/A		
	В	Location	N/A	N/A	N/A		
19.	Fire Control Room:						
	A	Detector system panel	N/A	N/A	N/A		
	В	Flow switch panel	N/A	N/A	N/A		
	C	PA system panel	N/A	N/A	N/A		
	D	Battery backup	N/A	N/A	N/A		
	E	Building floor plans	N/A	N/A	N/A		
		ecial Fire Protection systems for stection of special Risks, if any:	NA	N/A	N/A		

The fire protection system was randomly checked and tested and was found functional at the time of inspection.

Keeping in view of the deemed compliance of minimum standards on fire prevention and fire safety measures as required under the Rules the Fire Safety Certificate issued vide letter no. F6/DFS/MS/School/2021/NDZ/907 dated 29/10/2021 under the Circular no F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011 is recommended to be renewed.

> Signature of the Inspecting Officer Name: - Yashwant Singh Meena

Designation: - ADO (L.N)