

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001



No. F6/DFS/MS/2025/School/ 962

Dated: 08 /08 /2025

FIRE SAFETY CERTIFICATE

Certified that the Nav Bharti Senior Secondary School located at Shree Nagar Colony, Sindhora Kalan, Near Shakti Nagar Railway Under Pass, Delhi-110052 comprised of Ground & 02 upper floors owned/ occupied by Nav Bharti Senior Secondary School was issued Fire Safety Certificated vide this office letter no. F6/DFS/MS/School/2022/877 dated 10/08/2022. The premise was inspected by the officer concerned of this department on 29/07/2025 in the presence of Mrs. Vinita Bhartiya (Vice Principal) and observed that all the fire prevention and fire safety arrangements as provided in the premise found in good working condition. The premise have therefore deemed complied with the requirements under rule 33 of the Delhi Fire Service Rules, 2010 and the building premise is fit for occupancy class "Group B Educational (School)" with effect from . or by 2025.... for a period of three years, in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under rule 40, subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010,

Issued on .0.8. 08 2.025...... at New Delhi by.

irendra Singh Chief Fire Officer Delhi Fire Service

Copy to: -

- 1. The Deputy Director of Education, Zone-VII, District North Lucknow Road, Timarpur, Delhi - 110054.
- 2. The Manager, Nav Bharti Senior Secondary School located at Shree Nagar Colony, Sindhora Kalan, Near Shakti Nagar Railway Under Pass, Delhi-110052.

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.

3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

4. All the staff members must know the correct method of operation of firefighting system.

5. The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service 2010. The form available http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

INSPECTION REPORT

1. Name & address of the building

: Nav Bharti Senior Secondary School at Shree Nagar Colony, Sindhora Kalan

Near Shakti Nagar Underpass, Delhi-110052.

2. · Type of Occupancy

: Educational (School)

3. Composition of building

: Ground & 02 upper floors

4. Type of Case

: Renewal

5. Details of previous NOC

: F6/DFS/MS/School/2022/877 dated 10/08/2022

6. Fire Safety directives letter No

: Nil

7. Date of inspection

: 29/07/2025

8. Name of the Inspecting Officers

: ADO (RN)

9. Name and designation of officers

from the building side

: Mrs. Vinita Bhartiya (Vice Principal)

10. Year of Construction

: 1985

11. Applicant's letter No.

: Letter No. Nil dated 18/07/2025

	Minimum Standards on fire prevention and fire safety U/R 33	NBC Part –IV Requirements	Provided at site	Remarks MR/NMR				
1	Access to building							
	Road width	06m	06m	MR				
	Gate width	05m	05m	MR				
	Width of internal road	NA	NA	NA				
2	Number, Width, Type & Arrangement of Exits							
	a. Number of staircases	02	02	MD				
	Upper Floors		55/2500	MR				
	Basements	NA	NA	NA				
	b. Width of staircases							
	Upper Floors	1.50m	1.40m, 1.57m & 1.88m	MR				
	Basements	NA	NA	NA				
	c. Protection of exits							
	Fire check door	NA	NA	NA				
	Pressurization	NA	NA	NA				
	d. No. of continuous staircases to terrace e. Width of Corridor f. Door Size	02	Required	MR				
		NA	NA	NA				
	1. 500 5120	01m	01m	MR				
	Compartmentation.							
	Fire check door	NA	NA	NA				
	Sealing of electrical shafts	NA	NA	NA				
	 Fire Rating of shaft door 	NA	NA	NA				
	Water Curtain	NA	NA	NA				
	• Fire Dampers	NA	NA	NA				
	Smoke Management System.							
	Basements	NA	NA	NA				
	Upper floors	Required	Natural Ventilated	MR				
	Fire Extinguishers							
-	Total numbers Types	16nos	16nos	MR				
		ABC/Co2	ABC16	MR				
	ISI marking	ISI Marked	Yes	MR				

6	First-Aid Hose Reels.	· M12				
	Total numbers on each floor	02 at each floor	02			
	 Length of hose reel hose 	Secretary and the second secretary second se		M		
	Nozzle diameter	30m	30m	N		
7	== 2.4.000.00 3.00 f l.	5mm -	5mm	N		
an J	Automatic fire detection and alarming system. • Type of detectors NA NA					
	Location of Main Panel	NA NA	NA NA	N		
		NA NA	NA NA	N		
	Location of Repeater Panel			1		
	Alternate source of power	NA	NA	N		
	Hooters' Location	NA	NA	N		
8	MOEFA	Required	Provided	М		
9	Public Address System.	NA	NA	N.		
10	Automatic Sprinkler System.					
	Basement	NA	NA	N/		
	Upper Floor	NA	NA	N/		
	Sprinkler above false ceiling	NA	NA	N/		
11	Internal Hydrants					
10000000	Size of riser/down-comer	NA NA	NA	N/A		
	Number of hydrants per floor	NA NA	NA	NA NA		
	Hose Box	NA	NA	NA NA		
12	Yard Hydrants.					
	Total number of hydrants	NA	NA	NA		
	Hose Box	NA	NA	NA		
13	Pumping Arrangements.					
	Ground Level		8			
	> Discharge of main Pump	N/A	N/A	N/A		
	> Head of Main pump	N/A	N/A	N/A		
	> Number of main pumps	N/A	N/A	N/A		
	> Jockey Pump out put	N/A	N/A	N/A		
	> Jockey pump head	N/A	N/A	N/A		
	> Standby Pump out put	N/A	N/A	N/A		
	> Standby Pump Head					
	 ➤ Auto Starting/ Manual stopping ➤ Pump House Access 	N/A N/A	N/A N/A	N/A N/A		
	Terrace level	IVA	17/11	IN/A		
	➤ Discharge of pump	450 LTR	450 LTR	MR		
	➤ Head of the pump	40m	40m	MR		
1	➤ Power Supply	Required	Provided	MR		
	➤ Auto Starting of pump	Required	Provided	MR		
14	Captive Water Storage for fire fighting.		W. D. DESCRIPTION (1994)			
	Underground tank capacity	NA	NA	NA		
	> Draw-off connection	NA	NA	NA		
	> Fire service inlet	NA	NA	NA		
	> Access to tank	NA	NA	NA		
	Overhead Tank capacity	10,000 LTR	Provided	MR		
		The state of the s		IVII		

16	Provision of Lifts.						
	Pressurization of Lift Shaft	N/A	N/A	N/A			
	 Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch 	N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
	• Lift Signage	N/A	N/A	N/A			
17	Standby power supply	N/A	N/A	N/A			
18	Refuge Area.						
	Total Area	N/A	N/A	- Control of			
	Location	N/A	N/A	N/A			
19	Fire Control Room						
	Detector System Panel	N/A	N/A	N/A			
	Flow Switch Panel	N/A	N/A	N/A			
	PA System Panel	N/A	N/A	N/A			
	Batter backup	N/A	N/A	N/A			
	Building Floor Plans	N/A	N/A	N/A			
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A			

The fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in NBC Part-IV, it is recommended for renewal of fire safety certificate issued vide this department letter of even no. F6/DFS/MS/School/2022/877 dated 10/08/2022.

Signature of the Inspecting Officer Name :-C.L. Meena

Designation:- ADO/RN

D.B. Mukharjee (DO/NW)