



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001



No. F.6/DFS/MS/School/2025/SZ/1844

Dated: 27 / 11 / 2025

To

Sh. Ravi Pratap (Manager),
Nehru Academy, RZ-55 & 56.
Vashisht Park, Opp. Janak Cinema,
West Sagarpur, New Delhi-110046

**Sub: Regarding issuance of Fire Safety Certificate in r/o Nehru Academy, RZ-55 & 56,
Vashisht Park, West Sagarpur, New Delhi-110046**


Sir,

This has reference to your letter No. NA/2025/820 dated 08/10/2025 received in this department vide outdoor diary no. 6786 dated 08/10/2025, on the subject cited above. In this connection, it is to inform you that the said premise was inspected by the officer concerned of this department on 11/11/2025 in the presence of Ms. Sashi Rani Sharma (Principal) to verify the compliance of shortcomings issued vide letter No. F.6/DFS/MS/School/2019/SZ/6094 dated 14/10/2019 (copy enclosed) and observed that the shortcomings are not yet complied.

In view of above, application for issuance of fire safety certificate is rejected. You are requested to rectify the shortcomings under intimation to this department for further action.

Yours faithfully,

Encls: As above.


(A.K. Malik)
Dy. Chief Fire Officer (SZ)
Delhi Fire Service
21/11/25

Copy to: -

1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No: F.6/DFS/MS/School/2019/SZ / 6094
To,

Dated: 14/10/19

The Manager,
Nehru Academy,
D-1 & 2, Vasistha Park,
Opp. Janak Cinema, Sagarpur, New Delhi-110046

Sub: - Regarding issuance of Fire Safety Certificate in r/o Nehru Academy, D-1 & 2, Vasistha Park, Opp. Janak Cinema, Sagarpur, New Delhi-110046.

Sir,

This has reference to your Letter No. NA/2019/528 dated 30.07.2019 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 05.09.2019 to see the requisite fire safety measures. Smt. Shobha Rani Sharma (Chairperson) was present at the time of inspection.

During the course of inspection it was observed that school building comprised of basement, ground plus three upper floors. The upper floors are served by two staircases from Ground floor to second floor having width 112 cms & 72 cms and third floor served by single staircase having width 112 cms. The basement is served by single staircase having width 110 cms. The electrical wiring was seen concealed and the electric supply was passing through MCB's. The following shortcoming was observed:-

1. The upper floors are served by two staircases from Ground floor to second floor having width 112 cms & 72 cms and third floor served by single staircase having width 112 cms. The basement is served by single staircase having width 110 cms against required two staircases having width 150 cms each from basement to terrace.
 2. Door width is 85 to 90 cms against required 120 cms.
 3. Fire check door not provided.
 4. Basement ventilation provided but not functional.
 5. Hose reel system provided but not functional.
 6. Automatic sprinkler system not provided in the basement.
 7. Fire pump having capacity 900 LPM not provided.
 8. Overhead water storage tank of 15,000 ltrs capacity not provided for hose reel system & automatic sprinkler system.
 9. Exit signs are not provided.
 10. Also submit sanctioned drawings/As built drawings duly signed by the Principal/Authorized signatory.
- If student capacity is more than 45 in any class room then double door having width 120 cms is required.

You are advised to rectify the above-mentioned shortcomings for taking further action as necessary for grant of Fire Safety Certificate.

Yours Faithfully,

(ATUL GARG)
CHIEF FIRE OFFICER

Copy to:-

Director of Education,
Govt. of NCT of Delhi, Old Secretariat,
New Delhi - 110054

(With a request to take further action as school does not have fire NOC)