## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, NEW DELHI - 110001

No: F6/DFS/MS/Hosp/WZ/2024/ 4 8-8

Dated: 30/07 /2024

Director

## FIRE SAFETY CERTIFICATE

Certified that the New Hospital Block in Acharya Shree Bhikshu Govt. Hospital located at Moti Nagar, New Delhi - 110015, comprised of Basement + Ground + 07 Upper Floors. The premises was re- inspected by the officer concerned of this department on 16/07/2024 in the presence of Sh. Ramesh Chand Gupta A.E and found that the Fire prevention and fire safety arrangements provided in the premises, found in good working condition. The premises have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and that the premises is fit for occupancy class Group C (Institutional) with effect from 30072024..... for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 30 07 2024 at New Delhi.

Copy to:-

1. The Medical Superintendent, Acharya Bhikshu Hospital, located at Moti Nagar, New

2. The Executive Engineer, Health Maintenance Division, (South West) M-123, DGER Complex, Opposite D.P.S., Sector-3, Dwarka, New Delhi - 110078.

## Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. The basement shall be used as per building bye laws.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- 9. Left out ventilation system in basement & upper floors, Fire check doors shall be provided in Refuge area within 03 months from the date of issuance of Fire Safety Certificate with the risk and responsibility of the hospital management, otherwise FSC shall be automatically cancelled/null & void.
- 10. In lift lobbies normal glazing glasses are provided instead of 2 hours fire rated wire mesh glass, which violate the fire safety norms & It shall be replaced by wire mesh glasses (2hrs fire rated) before the next date of renewal for the safety of occupants.

22

7/18

	IN	CDE	CTION DEPONE			
1.			CTION REPORT	-4		
1.	Name & address of the building	New Hospital Block in Acharya Shree Bhikshu Govt. Hospital, Located at Moti Nagar, New Delhi- 110015.				
2.	Type of Occupancy	Institutional (Hospital)				
3.	Type of Case	New				
4.	Details of previous NOC	New	Case		An year	
5.	Fire Safety directives letter No	F.6/I	DFS/MS/BP/2016/303	dated 25/11/2016		
6.	Date of inspection	16/0	16/07/2024			
7.	Name of the Inspecting Officers	Sara	bjeet Singh ADO (MN	Ŋ		
	Name and designation of officers from the building side					
9.	Year of Construction	2024				
	). Applicant's letter No.		o)/ स्वा. अनु. म.(द.प)/ एम-		d 08/07/2024	
*	The said hospital is comprised of	Base	ment + Ground + 07	upper floors.		
S. No.	Minimum Standards on fire prevention and fire safety U/R		BBL /NBC Requirement	Provided at site	Remarks MR/NMR	
1	Access to building			Provided	MR	
	Road width		9 mts	Provided	MR	
	Gate width		6 mts	Provided	MR	
	Width of internal road		06 mts	Flovided	17114	
2	Number, Width, Type & Arran	gemen	t of Exits			
	a. Number of staircases		02	Provided	MR	
	Upper Floors     Basements		02	Provided	MR	
	b. Width of staircases		02		- Property of	
	• Upper Floors		2 mts	Provided	MR	
Pf	Basements		2 mts	Provided	MR	
	c. Protection of exits			T DESCRIPTION OF		
	Fire check door		Required	Provided	MR	
	Pressurization		Required	Provided	MR	
	e. No. of continuous staircases to te	rrace	02	Provided	MR	
	f. Width of Corridor		2.4 mts	Provided	MR	
	g. Door Size		2 mts	Provided	MR	
3	Compartmentation.	JL., D		1	Conditional MR	
	Fire check door		Required	Not Provided in refuge area	for 03 months	
	Sealing of electrical shafts		Required	Not Provided	Conditional MR for 03 months	
	Fire Rating of shaft door		Required	Provided	MR	
	Water Curtain		NR	NR	NR	
	Fire Dampers		Required	Provided	MR	
4	Smoke Management System.				Conditional MI	
4	Basements		Required	Provided but some areas are left out	for 03 months	
	Upper floors		Required	Provided but some areas are left out	Conditional Mi for 03 months	
5	Fire Extinguishers		100	Provided	MR	
	<ul> <li>Total numbers</li> </ul>		100 nos.	Provided	MR	
	• Types		CO <sub>2</sub> ,DCP, ABC type	Provided	MR	
	IS marking		ISI marked	Provided		

84

. 1	١	٠
w١	1	1
	٠,	-

	<ul> <li>Total numbers on each floor</li> </ul>	- 02	02 each floor	M		
	Length of hose reel hose	30 m required		M		
¥	Nozzle diameter	5 mm required	1,5,5,5	M		
7						
	Type of detectors	Smoke	Provided	MI		
	Location of Main Panel	Ground floor	Provided	MF		
1	Location of Repeater Panel	Required	Provided	MR		
I	Alternate source of power	Required	Provided	MR		
	Hooters' Location	Required	Provided	MR		
8	MOEFA	Required	Provided	MR		
9	Public Address System.	Required	Provided	MR		
10	Automatic Sprinkler System.					
	Basement	Required	Provided	MR		
	Upper Floor	Required	Provided	MR		
	Sprinkler above false ceiling	Required	Provided	MR		
11	Internal Hydrants		- Wood door to the State of the			
- 11	Size of riser/down-comer	150 mm	Provided	MR		
	Number of hydrants per floor	02	Provided	MR		
	Hose Box	02	Provided	MR		
12	Yard Hydrants.			- Period Control		
	Total number of hydrants	05	Provided	MR		
tar (	Hose Box	05	Provided	MR		
3	Pumping Arrangements.		and the second second			
	Ground Level		the state of the state of			
	Discharge of main Pump	2280 LPM	Provided	MR		
	➤ Head of Main pump	80 MH	Provided	MR		
_	> Number of main pumps	01	Provided	MR		
	➤ Jockey Pump out put	180 LPM	Provided	MR		
	> Jockey pump head	80 MH	Provided	MR		
	Standby Pump out put	2280 LPM	Provided	MR		
	Standby Pump Head	80 MH	Provided	MR		
- 1	> Auto Starting/ Manual stopping	Required	Provided	MR		
	> Pump House Access	Required	Provided	MR		
-   •	Terrace level		Marie II.			
	➢ Discharge of pump	NR	NR	NR		
	➤ Head of the pump	NR	NR	NR		
	➤ Power Supply	NR	NR	NR		
	➤ Auto Starting of pump	NR	NR	NR		
Ca	ptive Water Storage for fire fighting.		2000 000			
	Underground tank capacity		Provided (Common	MR		
	> Draw-off connection	Paguired	with old building) Provided	MR		
34,	> Fire service inlet	Required Required	Provided	MR		
	Access to tank					
	Overhead Tank capacity	Required	Provided Provided	MR MR		
	* * * * * * * * * * * * * * * * * * * *	20, 000 litres Required	Provided	MR		
Exit	Signage.	required	Tovidod	MIX		

10	110, 1510n of Lifts.					
	Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch	Required Required Required	Provided Provided Provided	MR MR MR		
	Lift Signage	Required	Provided	MR		
17		Required	Provided	MR		
18	Standby power supply Refuge Area.	Required	Provided	MR		
	> Total Area	Required	Provided	MR		
3/30 1131	> Location	Required	Provided at 7th floor	MR		
19	Fire Control Room					
	Detector System Panel	Required	Provided	MR		
	Flow Switch Panel	Required	Provided	MR		
	PA System Panel	Required	Provided	MR		
	Batter backup	Required	Provided	MR		
	Building Floor Plans	Required	Provided	MR		
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required	Provided	MR		

107/2024

Note: - Leftout ventilation system in basement & upper floors, Fire check doors shall be provided in refuge area & sealing of plumbing shaft/ electrical shafts etc. shall be done within 03 months from the date of issuance of Fire Safety Certificate with the risk and responsibility of the hospital management, otherwise FSC shall be automatically cancelled/null & void.

\* In lift lobbies, normal glazing glasses are provided instead of 2 hours fire rated wire mesh glass, which violate the fire safety norms. It shall be replaced by wire mesh glasses (2hrs fire rated) before the next date of renewal for the safety of occupants.

The fire fighting system is connected with the existing U.G water tank capacity 2,00,000ltr & fire pumps as per sanctioned plan.

The fire protection system provided in the building were checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention & fire safety requirement under the rules and approval/acceptance of above note, it is recommended to grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010.

Qy cro /win

Signature of the Inspecting Officer

Name: - Sarabjeet Singh Designation: - ADO (MN)

Designation: - A

1 03 3 m

cro

24 Plany

mont my

THE THE PARTY OF T