

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

आजादी व अमृत महोत्सव

No.F6/DFS/MS/School/SZ/2025/ 706

Dated: 26 05 2025

FIRE SAFETY CERTIFICATE

Certified that the New Life Convent School located at Gali No. 26F, Khajoor Wala Road, Molarband Extn., New Delhi-44, comprised of Ground + 01 upper floors, was granted Fire Safety Certificate (FSC) by this department vide letter no. F6/DFS/MS/School/2013/669 dated 15.02.2013. The school building was re-inspected by Assistant Divisional Officer (M. Road) from this department on 21.05.2025 in the presence of principal and found that the school has deemed complied with the fire prevention and fire safety requirements in accordance with the circular no. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Directorate of Education and the building (Ground floor + 01 upper floor) is fit for occupancy of Group B "Educational Building" with effect from 26.05.2025.... for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire Service Rules, 2010 printed below.

Issued on 26/05/2025 at New Delhi by

Delhi Fire Service

Copy to:-

1. The Dy. Director of Education, GNCT of New Delhi DISST. South Block-C, Defence Colony, New Delhi-24.

 The Principal New Life Convent School located at Gali No. 26F, Khajoor Wala Road, Molarband Extn., New Delhi-44.

Conditions for the validity of Fire Safety Certificate

1. All the means of escape shall be kept free of all the type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.

- The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.

6. Basement shall be used as per BBL.

- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.
- 8. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry.

1/0 n/10

1	No	3000000	PECTION REPORT	The state of Col	No. 26F.		
		me & address of the building	New Life Convent School located at Gali No. 26F, Khajoor Wala Road, Molarband Extn., New Delhi- 44.				
2	Bui	ilding is comprised of	Ground + 01 upper floor				
3	Ту	oe of occupancy	Group B –Educational Building				
1	Ту	pe of case	Penevual				
5	Det	tails of previous FSC	EC/DEC/AS/School/2013/669 dated 15.02.2013				
6		e safety direction letter no.	F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011				
7	Dat	te of inspection	21.05.2025				
8		me of the inspecting officers	Rajesh Kumar Shukla, ADO (M. Road)				
9	Na	me of the designation of icer from the building side	Principal				
10	_	ar of construction	2012				
11	_	plicant's letter no.	Outdoor diary no. nil dated 19.05.2025				
S.No	Mi	nimum standard of fire evention and fire safety U/R	Requirement as per Rules 35 (6)	Provided at site	Remarks MR/NMF		
1		cess to Building:	r III-li a	Accessible to fire	MR		
	A	Road width	Accessibility	engines	.4175.21		
	7	And the second of the second o		NA	NA		
	В	Gate width	NA	NA	NA		
	C	Width of internal road	NA				
2	Nu	mber, Width, Type and Arra	ngement of Exter	in the last			
	A	Number of staircases	02	02 nos.	MR		
		a Upper floor	02 nos.	NA	NA		
		b Basement	NA				
	В	Width of staircases a Upper floor	1 staircase of 1.5 mtrs or if main staircase width is < 1.5 mtrs an additional staircase of 0.75 mtrrs width is required.	1.50 mtrs & 1.25 mtrs	MR		
	1	201	NA NA	NA	NA		
		b Basement Protection of exits	NA NA	NA	NA		
	C	a Fire check door	NA	NA	NA		
		b Pressurization	NA	NA	NA \		
	D	No. of continuous staircases to terrace	01 no.	01 no.	MR NA		
	E	Width of corridor	NA	NA			
	F	Door size	1.0 m for class room	1.0 m for class room	MR		
3	Co	mpartmentation:		NA	NA		
	A	Fire check door	NA	NA NA	NA		
	B	Sealing of electrical shafts	NA	NA NA	NA		
	C	Fire rating of shaft door	NA NA	NA	NA		
	D	Water curtain	NA NA	NA	NA		
	E	Fire dampers	INA	1 - 11 -			
4	-	noke Management System:	NA	NA	NA		
	A	Basement	NA NA	NA NA	NA		
	В	Upper floor	IAV	1-11-	1		
5.	Fir	e Extinguisher:		104	340		
	A	Total numbers	04 nos.	04 nos.	MR		
	В	Types	CO ₂ & ABC	CO ₂ & ABC	MR		
		ISI marking	Required	Provided	MR		



		st-Aid-Hose Reel:					
	A	Total numbers of each floor	NA	NA	NA		
	В	Length of hose reel hose	NA	NA	NA		
	C	Nozzle diameter	NA	NA	NA		
7	Automatic Fire Detection and Alarming System:						
	A	Type of detectors	NA	NA	NA		
	В	Location of main panel	NA	NA	NA		
	C	Location of repeater panel	NA	NA	NA		
	D	Alternate source of power	NA	NA	NA		
	E	Hooters	NA	NA	NA		
8		DEFA:	NA	NA	NA		
9	1100000	blic Address System:	NA	NA	NA		
10	Automatic Sprinkler System:						
-	A	Basement Basement	NA	NA	NA		
	B	Upper floor	NA	NA	NA		
	C	The state of the s	NA NA	NA NA	NA NA		
-		Sprinkler above false ceiling	INA	INA	INA		
11	-	ernal Hydrants:	Tara	NA	NA		
	A	Size of riser/down-comer	NA NA	NA NA	NA NA		
	B	Number of hydrants per floor	NA NA		NA NA		
	C	Hose box	NA	NA	INA		
12	-	rd Hydrants:	LNIA	NIA	NA		
	A	Total number of hydrants	NA	NA	400.4100		
	В	Hose box	NA	NA	NA		
13	Pumping Arrangements:						
A	_	Fround level	LSVA	Lara	1374		
	a)	Discharge of main pump	NA	NA	NA		
	b)	Head of main pump	NA	NA	NA		
	c)	Number of main pumps	NA	NA	NA		
	d)	Jockey pump out put	NA	NA	NA		
	e)	Jockey pump head	NA	NA	NA		
أنخال	n	Standby pump out put	NA	NA	NA		
	g)	Standby pump head	NA	NA	NA		
1	h)	Auto starting /manual	NA	NA	NA		
1	i)	stopping Pump house access	NA	NA	NA		
В	Terrace Level						
	a)	Discharge of pump	NA	NA	NA		
	b)	Head of the pump	NA	NA	NA		
	c)	Power supply	NA	NA	NA		
	d)	Auto starting of pump	NA	NA	NA		
14	Captive Water Storage for Fire Fighting:						
	A	Underground tank capacity	NA	NA	NA		
	В	Draw-off connection	NA	NA	NA		
	C	Fire service inlet	NA	NA	NA		
	D	Access to tank	NA	NA	NA		
15	E	Overhead tank capacity	NA Required	NA Provided	NA		
15 16	Exit Signage: Required Provided MR Provision of Lifts:						
10	A	Pressurization of lift shaft	NA	NA	NIA		
	B	Pressurization of lift lobby	NA	NA NA	NA NA		
	C	Communication in lift car	NA	NA	NA		
	D	Firemen's grounding switch	NA	NA	NA		
	E	Lift signage	NA	NA	NA		
17		ndby Power Supply: Convent School located at Gali No. 26F	NA	NA	NA		

New Life Convent School located at Gali No. 26F, Khajoor Wala Road, Molarband Extn., New Delhi-44.

18	New Life Convent School located at Galt No. 26F, Khajoor Wala Road, Molarband Extn., New Delhi-14. Refuge Area:					
	A	Total area	NA	NA.	NA	
	B	Location	NA	NA	NA	
19	Fire Control Rooms					
	٨	Detector system panel	NA	NA	NA	
	B	Plow switch panel	NA.	NA	NA	
	C	PA system panel	NA	NA	NA	
	D	Battery backup	NA	NA	NA	
	E	Building floor plans	NA	NA	NA	
20	Special Fire Protection systems for protection of special Risks, if any:		NA	NA	NA	

Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided but Not Functional (PNF), Not Provided (NP),

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

The shortcomings issued to the school by this department vide letter no. F6/DFS/MS/School/2017/SZ/2039 dated 07.08.2017 has been rectified by the school

management.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required in Directorate of Education Circular no. 3298 to 3398 dated fire safety measures as required in Directorate of Education Circular no. 3298 to 3398 dated 10.03.2011, the FSC issued vide letter no. F6/DFS/MS/School/2013/669 dated 15.02.2013 is recommended to be renewed.

Signature of the Inspecting Officer
Name Rajesh Kumar Shukla
Designation ADO (M. Road)

DO (\$D)

Mulernisho

Derceter 18