066

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2025/36/

Dated: 21/05/2025

## **FIRE SAFETY CERTIFICATE**

Certified that the M/s New Tamanna Guest House located at 2320, Katra Alam Beg, Ballimaran, Delhi comprised of Ground & 04 upper floors, Ground floor (Reception + 01 hall for 10 beds), 1st to 3rd floor (05 guest rooms at each floor), total 15 guest rooms owned/occupied by M/s New Tamanna Guest House was granted FSC by this department vide letter No. F6/DFS/MS/GH/NDZ/2021/493 dated 02/11/2021. The premises was inspected by the officer concerned of this department on 13/05/2025 in the presence of Mr. Moin Khan and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010. The owner has submitted an affidavit on 14/11/2019 regarding not to use any floor above third floor for any other purpose except mumty of staircase and water tank. Accordingly, the premises is fit for occupancy class Residential, Sub Division-A-1 for total 15 guest rooms and 01 hall for 10 beds, (ground floor- 01 hall for 10 beds, 1st floor to 3rd floor, 5 guest rooms at each floor) up to 3<sup>rd</sup> floor only with effect from 21 05 2025 for period of three years, in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 21/05/2625 at New Delhi by.

Delhi Fire Service

## Copy to:-

- 1. The Commissioner, MCD, Civic Centre, New Delhi: with a request to ensure the occupancy as detailed above & deviation if any.
- 2. Online id no. 2025042707332 dated 27/04/2025.
- 3. M/s New Tamanna Guest House located at 2320, Katra Alam Beg, Ballimaran, Delhi.

## Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the MCD Portal along with a copy of this Certificate, six months prior to its expiry".
- This Fire Safety Certificate is valid for ground & 03 upper floors only. In case of any violation, this FSC will be treated as null & void.

	31/4	M22				
	INSP	ECTION REPO	ORT			
1.	Name & address of the building	M/s New T	amanna Guest Ho	use at 2320,		
	12	Katra Alam Beg, Ballimaran, Delhi				
2.	Type of occupancy:- Residential, Sub Division-A-1					
		Ground+04 up	per floors			
		Ground floor (	Reception + 01 hall for	r 10 beds), 1st to		
		3 <sup>rd</sup> floor (04 gr	uest rooms at each floo	or), total 12 guest		
2	Tree of	Rooms & 4th floor not in use Renewal No. F6/DFS/MS/GH/NDZ/2021/493 dated 02/11/2021.				
	Type of case:-					
4.	Details of previous FSC:-					
	77					
5.	Fire safety directives No	N/A				
	6. Date of inspection:- 13/05/2025					
7.	Name of the inspecting officer:	<ul> <li>ADO/RN</li> </ul>				
8.	Name & designation of officer					
	From the building side:-	Mr. Moin K	han			
9.	Year of construction:-	2001	0.000			
10	). Applicant's letter No:-	ID No-20250	42707332 dated 27	/04/2025		
S.No.	Minimum Standards on fire	Requirement/	Provided at site	Remarks		
	Prevention and fire safety	Existing fire	(PSS)	MR/NMR		
	U/R 33	safety		In the second		
		arrangements				
1.	Access to Building		07	MR		
	1) Road width	N/A(Spl.	07 mtr.	MIK		
		Area)	P. R. H. J. J.	N/A		
	2) Gate width	N/A	N/A			
	3)Width of internal road	N/A	N/A	N/A		
2	Number, Width Type & Arr		its			
2.	A. Number of staircases					
1	THE RESERVE THE PROPERTY OF TH	01 Nos.	01 Nos.	MR		
	1. Upper floors	N/A	N/A	N/A		
	2. Basements	11/22				
	B. Width of staircase	0.80 mtr.	1.25 mtr.	MR		
-	1. Upper floors	N/A	N/A	N/A		
	2. Basements	TV/X				
	C. Protection of exits	N/A	N/A	N/A		
	1. Fire check door	N/A	N/A	N/A		
	2. Pressurization	01	01	MR		
	D. No. of continuous	01	01	andes		
	staircase to terrace	N/A	N/A	N/A		
_	E. Width of corridor		0.95 mtr.	MR		
	F. Door size	0.90 mtr.	0.93 mu.	Trace		
3.	Compartmentation	Tarri	NI/A	N/A		
	1) Fire check door	N/A	N/A	N/A N/A		
	2) Sealing of electrical shafts	N/A	N/A	LANCE COLORS		
	3) Fire rating of shaft door	N/A	N/A	N/A		
	4) Water curtain	N/A	N/A	N/A		
	5) Fire Dampers	N/A	N/A	N/A		
4.	Smoke Management System			Tarra		
	1) Basements	N/A	N/A	N/A		
	2) Upper floors	Required	Natural	MR		
-	Fire Extinguishers	n = 1 14				
5.	1) Total numbers	07 Nos.	07 Nos.	MR		
	2) Types	ABC & CO2	ABC & CO2	MR		
	2) ISI marking	Required	Provided	MR		
	3) ISI marking	Required				
6.	First-Aid Hose Reel	01	01	MR		
1	1) Total number of eachfloor	30 mtr.	30 mtr.	MR		
	2) Length of hose reel hose 3) Nozzle diameter	05 mm	05 mm	MR		
100	A NOTTIE GIAMPIEL		1 42 11111			

Provided

Provided

Provided

Provided

N/A

N/A

05 mm

Required

Reception

Required

Every floor

N/A

N/A

Automatic Fire Detection & Alarming System

3) Nozzle diameter

1) Type of detectors CO<sub>2</sub>

2) Location of main panel

5) Hooter's Location

**MOEFA** 

3) Location of repeater panel

4) Alternate source of power

7.

8.

MR

MR

N/A

MR

MR

N/A

	N/2	3		1
	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			1
	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	N/A	N/A	N/A
	ceiling	IV/A	1,111	1
11.			-	
11.	Internal Hydrants	21/4	N/A	N/A
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	I IVA
	floor		NT/A	N/A
	3) Hose box	N/A	N/A	IVA
12.	Yard Hydrants		15774	N/A
	1) Total number of hydrants	N/A	N/A	
	2) Hose box	N/A	N/A	N/A
3.	Pumping Arrangement	M M		1
	1) Ground level	N/A	N/A	N/A
	a) Discharge of main	N/A	N/A	N/A
	pump			-
	b) Head of main pump	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
	d) Jockey pump out put	N/A N/A	N/A	N/A
	e) Jockey pump head		N/A	N/A
	f) Stand by pump output	N/A	N/A N/A	N/A
	g) Stand by pump head	N/A		N/A
	h) Auto starting/Manual	N/A	N/A	IN/A
	stopping		107	-
	2) Terrace level		to July	11
	a) Discharge of pump	225 LPM	225 LPM	MR
ger.	b) Head of pump	30 mtr.	30 mtr.	MR
	c) Power supply	Required	Provided	MR
	d) Auto starting of pump	Required	Provided	MR
	u) Auto starting or pump		F 00	
14	Captive Water Storage for Fi	re Fighting		
14.	1) Under ground tank	N/A	N/A	N/A
10	capacity			
	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
		N/A	N/A	N/A
	c) Access to tank	2500 ltr.	2500 ltr.	MR
	d) Over head tank	2500 III.	2500 10.	
	capacity	Required	Provided	MR
15.	Exit Signage.	Kequirea	Tiovided	1,1,1
16.	Provision of Lifts.			1
	a) Pressurization of lift	N/A	N/A	N/A
1 8	shaft		1.4	
	b) Pressurization of lift	N/A	N/A	N/A
	lobby	iri da		1
vet.	c) Communication in	N/A	N/A	N/A
	lift car		79	
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
177	Stand by Power Supply	Required	Provided	MR
17.	The state of the s	N/A	N/A	N/A
18.	Refuge Area	W. Callaces.		
	Total area location	N/A	N/A	N/A
	Fire Control Room	N/A	N/A	N/A
19.		N/A	N/A	N/A
19.	a) Detector eyetem	4 1/4 2	****	
19.	a) Detector system			
19.	panel	N/A	N/A	N/A
19.	panel b) Flow switch panel	N/A	N/A	N/A
19.	panel	N/A N/A N/A	N/A N/A N/A	N/A N/A N/A

N/24

2.00				
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risk, if any:			N/A

The fire protection systems provided in the building were tested/ checked and found in working order at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to renew Fire Safety Certificate issued vide this department letter of even no. F6/DFS/MS/GH/NDZ/2021/493 dated 02/11/2021 under rule 37 of the Delhi Fire Service Rules 2010. Is recommended for approval up to third floor.

Signature of the Inspecting Officer
Name: - C.L. Meena
signation: Asst. Div. Officer (RN)

Designation: Asst. Div. Officer (RN) Dinector Director