



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001



No. F.6/DFS/MS/Instnl/2026/SZ/ 623

Dated: 16/04/2026

To

The Superintendent,
Bal Niketan / Balika Greh,
After Care Home for Women,
Department of Women & Child Development,
Govt. of NCT of Delhi,
Nirmal Chhaya Complex,
Jail Road, New Delhi-110064

Sub: Regarding Fire Safety Inspection and Issuance of Fire Safety Certificate in r/o Balika Greh and Bal Niketan situated at Nirmal Chhaya Complex, New Delhi-110064


Sir,

This has reference to your office letter F.No.11/ACHW/BN/BG/PWD(E)/FSC/25-26/822 dated 19.02.2026 received in this department vide outdoor diary No. 11195 dated 20.02.2026, on the subject cited above. In this connection, the Nirmal Chhaya Complex was visited by the officer concerned of this department on 06.04.2026 to verify the compliance of shortcomings issued by this department vide letter No. F.6/DFS/MS/Institutional/2019/SZ/4185 dated 12/07/2019 (copy enclosed) in your presence and observed that the shortcomings are not yet complied. Furthermore, the building blocks of G+1 upper floor only does not fall under the purview of sub-rule (2 & 7) of Rule 27 of DFS Rules, 2010 and already communicated vide letter No. F.6/DFS/MS/SZ/2024/124 dated 22.01.2024 and therefore, reference to this department for these blocks is not required unless any addition/alteration is carried out.

In view of above, application for issuance of fire safety certificate cannot be considered at this stage and rejected. You are requested to rectify the shortcomings already communicated under intimation to this department for further consideration in the matter.

Encl: As above.

Yours faithfully,


(A.K. Malik)
Chief Fire Officer (SZ)
Delhi Fire Service

Copy to: -

1. The Executive Engineer (Bldg.), Municipal Corporation of Delhi, 9th Floor, Dr. SPM Civic Centre, Minto Road, New Delhi-110002

C-13
C119

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No: F.6/DFS/MS/Institutional/2019/SZ /4185

Dated:

12/07/19

To,

The Superintendent,
Nirmal Chhaya Complex,
DWCD, Jail Road, New Delhi-110064

Sub: - Regarding issuance of Fire Safety Certificate in r/o Nirmal Chhaya Complex, DWCD, Jail Road, New Delhi-110064.

Sir,

This has reference to your Letter No. F.1/Misc./SSH/WCD/fire & safety/2018/621-623 dated 28.01.2019 on the subject cited above. In this connection, it is to inform you that the inspection of above said building has been carried out by officer concerned of this department on 17.05.2019 to see the compliance of the requisite fire safety measures. Smt. Poonam (Superintendent) was present at the time of inspection.

During the course of inspection it was observed that the building is comprised of Short Stay & Widow Home having three blocks (G+I), Children Home (G+III), After Care Home (G+III) & Nari Niketan (G+I). The upper floors of Children Home are served by two staircases having width 140 & 145 cms. and the upper floors of After care home are served by two staircases having width 142 & 140 cms. The building is approachable to the fire fighting vehicles. The electrical wiring was seen concealed and the electric supply was passing through MCB's. The following shortcomings were observed:-

1. The upper floors of Children Home are served by two staircases having width 140 & 145 cms and the upper floors of After care home are served by two staircases having width 142 & 140 cms against required two staircases of 200 cms each from ground floor to terrace.
2. Hose reel system provided but not functional in Children Home & After care home.
3. Automatic fire detection and alarming system not provided in Children Home & After care home.
4. MOEFA not provided in Children Home & After care home.
5. PA System not provided in Children Home & After care home.
6. Internal hydrant system not provided in Children Home & After care home.
7. Yard hydrant not provided in Children Home & After care home.
8. Fire pump of 2280 LPM (Main pump), 2280 LPM (DG set) & 180 LPM (jockey pump) are not provided.
9. Fire pump of 450 LPM capacity (terrace pump) is provided but not functional in Children Home & After care home.
10. Under ground water storage tank of 50,000 ltrs capacity each not provided for Children Home & After Care home.
11. Overhead water storage tank of 10000 ltrs capacity not provided in Children Home & After care home.

Hence you are advised to rectify the shortcomings under intimation to this department at the earliest for further necessary action for issuance of Fire Safety Certificate.

Yours Faithfully

(ATUL GARG)

CHIEF FIRE OFFICER

Copy to:-

The Executive Engineer (Bldg.),
HQ-II, SDMC, 8th Floor, Dr. S.P.M Civic Centre,
E-Wing, J.L. Nehru Marg, New Delhi-110002