



## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/School/2025/SZ/ 729

Dated: 05/06 /2025

## FIRE SAFETY CERTIFICATE

Certified that the Building of N. K. Bagrodia Public School located at Sector-4, Dwarka, New Delhi-110078, comprised of Basement, Ground + 04 upper floors, owned/occupied by N.K. Bagrodia Education Society, was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/School/2022/SZ/274 dated 14/03/2022. The premises was re-inspected by the officer concerned of this department on dated 20/05/2025 in the presence of Sh. Anil Kr. Goel and observed that said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that the premise/building is fit for occupancy class "Educational Group B" (School) with effect from 05/06/2025 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the DFS Rules, 2010.

Issued on <u>05/06/2025</u> at New Delhi by

(Virendra Singh)
Chief Fire Officer
Delhi Fire Service

Copy to: -

- 1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.
- 2. The Principal, N. K. Bagrodia Public School at Sector-4, Dwarka, New Delhi-110078

## **Conditions for the validity of Fire Safety Certificate:**

1. The basement shall not be used for school activities as per undertaking dated 21.05.2025. This FSC shall be withdrawn, if basement is found to be used for school activities.

2. All the means of escape/entry/exit shall be kept free from any obstruction.

3. All the fire safety arrangement provided therein shall be maintained in good working conditions at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.

4. All the staff members must know the correct method of operation of fire-fighting system.

5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.

6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, prior to its expiry.

7. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>

N-24

		ON REPORT			
1.	Name & address of the building	N. K. Bagrodia Public School located at Sector-4, Dwarka, New Delhi-110078			
2.	Type of Occupancy	Educational (Group-B)			
3.	Building Comprised of	Basement, Ground + 04 upper floors.			
4.	Type of Case	Renewal			
5.	Details of previous NOC No.	F6/DFS/MS/School/2022/SZ/274 Dt. 14/03/2022			
6.	Fire Safety directives Letter No.	F6/DFS/MSBP/2014/237 dated 25.07.2018			
7.	Date of inspection	20/05/2025			
8.	Name of the Inspecting Officer	ADO (DWK)			
9.	Name and designation of Officer	Sh. Anil Kr. Goel			
٧.	from the building side	Sil. Allii Ki. Goei			
10.	Year of Construction	2003 & 2017			
11.	Applicant's letter No.	NKBPS/DWK/DFS/2025/165 dated 06.05.2025			
			lo. 1380 dated 06/05/20 Provided at site	Remarks	
S.	Minimum standards on fire	Old NOC Requirement		MR/NMR	
No. 1.	prevention and fire safety U/R 33 Access of building	Requirement			
1.	Road width	12 mtr	30 mtr	MR	
	Road width     Gate width	4.5mtr	4.72 mtr	MR	
	Width of internal road	06 mtr	Provided	MR	
2.	Number, width, Type & Arrangement	s of exits			
	a. Number of staircases			1 . m	
	Upper floors	03 Nos	06 Nos	MR MR	
	Basements	02 Nos	02 Nos	IVIK	
	b. Width of staircases		1.60 1.05 m 1.41 m	MR	
	Upper floors	1.5 mtr	1.60m, 1.05m, 1.41m, 1.701m, 1.16 & 095m (Spiral Iron staircase)	(Old case	
	Basements	1.5m & 1.18m	1.73m & 1.18m	MR	
	c. Protection of exits			1 MD	
	Fire check door	Required	Provided in Bt.	MR N/A	
	<ul> <li>Pressurization</li> </ul>	N/A	N/A		
	d. No of continuous staircase to terrace	Required	04 Nos	MR	
	e. Width of Corridor	1.5 mtr	1.75m & 1.85m	MR	
	f. Door Size	1.0 mtr	1.08 mtr	MR	
3.	Compartmentation			1 10	
	Fire check door	Required	Provided in Bt.	MR	
	<ul> <li>Sealing of electrical shafts</li> </ul>	N/A	N/A	N/A	
	<ul> <li>Fire Rating of shaft door</li> </ul>	N/A	N/A	N/A	
	Water Curtain	N/A	N/A	N/A	
	Fire Dampers	N/A	N/A	N/A	
4.	Smoke Managements System				
	Basements	30 ACPH	Provided	MR	
	Upper floors	12 ACPH	Natural Ventilation	MR	
5.	Fire Extinguishers				
	Total numbers	16 Nos	Provided	MR	
	Types	ABC & CO <sub>2</sub>	Provided	MR	
	ISI marking	ISI Marked	Provided	MR	
6.	First-Aid Hose Reels	177			
٠.	Total numbers on each floor	02 Nos	03 Nos	MR	
		30 m	Provided	MR	
	Length of hose reel hose		Provided	MR	
	<ul> <li>Nozzle diameter</li> </ul>	5 mm	Provided	IVIIC	

	No. of the Control of	vetem		
7.	Automatic fire detection and alarming s	ystem N/A	N/A	N/A
	Type of detector	N/A	N/A	N/A
	Location of Main Panel     Constant Panel	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooters' Location	Required	Provided	MR
8.	MOEFA  Public Address System	Required	Provided	MR
9. 0.	Public Address System Automatic Sprinkler System	Required	1101100	1
U.	Basements	Required	Provided	MR
	-	N/A	N/A	N/A
	Upper Floor     Contains a language for a selling	N/A	N/A	N/A
1.	Sprinkler above false ceiling  Internal Hydrants	1071	1071	1 1/1/
1.	Size of riser/down-comer	100 mm	Provided	MR
	Number of hydrants per floor	02 Nos	03 Nos	MR
		Required	Provided	MR
2.	Hose Box  Yard Hydrants	required	11011404	14114
_	Total number of hydrants	Required	One	MR
	Hose Box	Required	Provided	MR
3.	Pumping Arrangements	Requires	110 1100	
<i>J</i> .	Ground Level			
		N/A	N/A	N/A
	<ul> <li>Discharge of main pump</li> <li>Head of main pump</li> </ul>	N/A N/A	N/A	N/A
	> Number of main pumps	N/A	N/A	N/A
	> Jockey pump out put	N/A	N/A	N/A
	Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	<ul> <li>➤ Standby Pump Head</li> <li>➤ Auto Staring/Manual stopping</li> </ul>	N/A	N/A	N/A
	➤ Auto Staring/Manual stopping ➤ Pump House Access	N/A N/A	N/A N/A	N/A N/A
	Terrace level	N/A	IN/A	IN/A
	> Discharge of pump	1620 LPM	1620 LPM	MR
	Head of the pump	40 mtr	40 mtr	MR
	> Power supply	Required	Provided	MR
	> Auto starting of pump	Required	Provided	MR
14.	Captive water storage for firefighting	Roquirea	Tiovided	IVIIC
	Underground tank capacity	N/A	N/A	N/A
	> Draw of connection	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	> Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	25,000 Ltr	Provided	MR
15.	Exit Signage	Required	Provided	MR
16.	Provision of Lifts	-101	Tiovided	IVIK
	> Pressurization of Lift Shaft	N/A	N/A	N/A
	➤ Pressurization of lift lobby	N/A	N/A	
	➤ Communication in lift Car	N/A	N/A	N/A
	➤ Fireman's Grounding Switch	N/A	N/A	N/A
	➤ Lift Signage	N/A		N/A
17.	Standby Power Supply	N/A	N/A	N/A
18.	Refuge Area	IVA	Provided	N/A
10.	> Total area	N/A	N/A	
				N/A

19.	Fire Control Room			
	> Detector system panel	N/A	N/A	N/A
	➤ Flow Switch Panel	N/A	N/A	N/A
	> PA System Panel	Required	Provided	MR
	➤ Battery backup	Required	Provided	MR
	➤ Building Floor Plans	Required	Provided	MR
20.	Special Fire Protection Systems for Protection of Special Risks, if any;	Required	CO <sub>2</sub> type fire extinguisher provided near electric panel	MR

Note: The school management has submitted documents pertaining DDA approval for subletting Ground Floor to Bank and an undertaking dated 21/05/2025 regarding not to use basement in future for school activity. We may consider it, if agreed please.

The fire protection systems provided in the building were checked, tested at random and found functional at the time of inspection. The shortcomings issued & communicated vide letter No. F.6/DFS/MS/School/2025/SZ/198 dated 07/04/2025 found rectified.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety required under the rules, the fire safety certificate issued vide letter No. F6/DFS/MS/School/2022/SZ/274 dated 14/03/2022, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, reply letter is put up for perusal/approval and signature please.

Signature of the Inspecting Officer
Name: Santosh Kumar

Designation: ADO (DWK)

DO (SW)

22/5/25

CFO/ Muy

T26/5/1/2015

Director - an MIR

DO KW)

Sir, FT water is promp for your bing. M

Sir, FT water is promp for your bing. M

Sir, FT water is promp for your bing. M

Sir, FT water is promp for your bing. M

Sir, FT water is promp for your bing. M