

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No. F.6/DFS/MS/School/2025/SZ/ 336

Dated: 03 04 2025

FIRE SAFETY CERTIFICATE

Certified that the Nutan Bal Vidyalaya at J-Block, West Sagar Pur, New Delhi-110046, comprised of ground plus two upper floors, having total 25 rooms (Including Class rooms, Offices, Store, Library & Staff room etc.), owned/occupied by Nutan Bal Vidyalaya was issued FSC by this department vide letter No. F.6/DFS/MS/School/2022/SZ/292 dated 17.03.2022. The school building was re-inspected by the officer concerned of this department on dated 21.03.2025 in the presence of Smt. Lata Gupta (Head Mistress) and found that School building have deemed complied the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises (ground plus two upper floors) is fit for occupancy class "Educational" w.e.f. 03 04 2025 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

Issued on 03 04 2025 at New Delhi by.

Delhi Fir

Copy to: -

1. The Head Mistress, Nutan Bal Vidyalaya at J-Block, West Sagar Pur, New Delhi-110046.

Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Conditions for the validity of fire safety certificate: -

1. All the fire safety arrangements provided therein shall be maintained in good working

2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of

occupants in case of emergency.

3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

4. The trained staff should be available round the clock.

5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning

6. The certificate may not be treated in any case for the regularization of the unauthorized

7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available www.dfs.delhigovt.nic.in.

8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior

to its expiry.



INSPECTION REPORT

1. Name & address of the building :

Nutan Bal Vidyalaya, J-Block, West Sagar Pur, New Delhi-110046

2. Building comprised of

Ground plus two upper floors.

3. Type of Occupancy

Educational

4. Type of Case

Renewal

5. Details of Previous NOC

F.6/DFS/MS/School/2022/SZ/292 dated 17.03.2022

6. Fire Safety directives letter No

N/A

7. Date of inspection

21.03.2025

8. Name of Inspecting Officer 9. Name and designation of officers A.D.O. R.K. Yadav

From the building side

: Smt. Lata Gupta (Head Mistress) : 2003

10. Year of Construction

S. No.	11. Applicant's letter No. : Minimum Standards on fire	Requirement	Provided at site	Remarks MR/NMR		
	prevention and fire safety U/R 33					
1.	Access to building		1 100	M/R		
	Road width	Accessible 06 m	Provided Directly accessible from road	MR		
	Gate width	4.5 m N/A	N/A	N/A		
	Width of internal road	N/A				
2.	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases		02 No's	M/R		
	Upper Floors	02 No's	N/A	N/A		
	Basements	N/A	1771			
	b. Width of staircases	1.50 & .75 m	1.18 m & .80 m	M/R		
1	Upper Floor	1.50 & .75 III N/A	N/A	N/A		
	Basements	N/A				
	c. Protection of exits	N/A	N/A	N/A		
	Fire check door	N/A N/A	N/A	N/A		
	Pressurization	N/A				
	d. No. of continuous staircases to	N/A	N/A	N/A		
	terrace	18.500 VO	2.0 m	M/R		
	e. Width of Corridor	1.50 m	1.12 m (double door) few rooms	M/R		
	f. Door Size	1.0 m	with single doors			
3.	Compartmentation		5	27/4		
	1.05 TMM (March 10.05)	N/A	N/A	N/A		
	Fire check door Fire check door Fire check door	N/A	N/A	N/A		
	Sealing of electrical shafts Sealing of electrical shafts The sealing of electrical shafts The sealing of electrical shafts	N/A	N/A	N/A		
	• Fire Rating of shaft door		N/A	N/A		
	Water Curtain	N/A N/A	N/A	N/A		
	Fire Dampers	IV/A				
4.	Smoke Management System		N/A	N/A		
	Basements	N/A	Not a first a first	M/R		
	Upper floors	Required	Natural ventilation	III I		
5.	Fire Extinguishers					
	Total numbers	10 no's	Provided	M/R		
	Types	ABC/CO ₂ type	Provided	M/R		
	IS marking	ISI marked	Provided	M/R		
i.	First-Aid Hose Reels					
	Total numbers on each floor	01 no.	Provided	M/R		
	Length of hose reel hose	30 M	Provided	M/R		
	Nozzle diameter	5 mm	Provided	M/R		

to

7.	Automatic fire detection and alarming	system		-
		N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	 Alternate source of power 	N/A	N/A	N/A
	Hooters' Location	N/A	N/A	N/A
Į.	MOEFA	N/A	N/A	N/A
	Public Address System	N/A	N/A	N/A
	Automatic Sprinkler System			
0.		N/A	N/A	N/A
	Basement	N/A	N/A	N/A
	Ground Floor Sprinkler above false ceiling	N/A	N/A	: /A
		1,,,,		
1.	Internal Hydrants			1 2712
	Size of riser/down-comer	N/A	N/A	N/A
	Number of hydrants per floor	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
2.	Yard Hydrants			
	Total number of hydrants	N/A	· N/A	N/A
	Hose Box	N/A	N/A	N/A
•		Control of		+
3.	Pumping Arrangements			
	Ground Level		27/4	N/A
	Discharge of main Pump	N/A	N/A	HADAMAGE -
	Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	11/A
	> Jockey Pump out put	N/A	N/A	N/A
	> Jockey pump head	N/A	N/A	N/A
	> Standby Pump out put	N/A	N/A	N/A
	> Standby Pump Head	N/A	N/A	N/A
	> Auto Starting/Manual Stopping	N/A	N/A	N/A
	> Pump House Access	N/A	N/A	N/A
	Terrace level			
	Discharge of pump	450 LPM	Provided	M/R
	> Head of the pump	30 m	Provided	M/R
	> Power Supply	Required	Provided	M/R
	➤ Auto Starting of pump	Required	Provided	M/R
14.	Captive Water Storage for fire fighting			
	Underground tank capacity	N/A	N/A	N/A
15	> Draw-off connection	N/A	N/A	N/A
	> Fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
	Overhead Tank capacity Entite:	10,000 ltrs	Provided	MR
15.	Exit Signage.	Required	Provided	M/R
16.	Provision of Lifts.		No L	ift
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby Communication In lift Car	N/A	N/A	N/A
	Fireman's Grounding Switch	N/A	N/A	N/A N/A
	Lift Signage	N/A N/A	N/A	N/A
N.	5 89	IN/A	N/A	N/A

7	Standb	y power supply	N/A	N/A	N/A		
	Refuge	ge Area.					
		Total Area	N/A	N/A	N/A		
	>	Location	N/A	N/A	N/A		
).	Fire Control Room						
	Detector System Panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans	N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
0.	Special Protect	Fire Protection System for on of special Risks, if any:	N/A	15 25 7			

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Note: - As per undertaking given by school management (placed at C-19) that there is one store room at third floor which is not used for educational purpose.

In view of the deemed compliance of the minimum standards of fire prevention and fire measures as required under the rules the FSC issued vide letter No. safety F.6/DFS/MS/School/2022/SZ/292 dated 17.03.2022, renewal under rule, 37 of the Delhi Fire Service Rules, 2010 is recommended.

> Signature of Inspecting Officer Name: - R.K. Yadav

Designation: - ADO (JKP)

D.O. (South West)

put up for signi plas