



FORM 'H': FORM FOR ISSSUNG FIRE SAFETY CERTIFICATE

[See sub-rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE **NEW DELHI- 110 001**

No. F6/DFS/MS/School/2025/NDZ/ 1213

Dated: 30/09/2025

FIRE SAFETY CERTIFICATE

Certified that the Nutan Vidya Mandir School at A.G.C.R. Enclave, Delhi-110092, comprised of basement, ground plus one upper floor, owned/occupied by Nutan Vidya Mandir School has already issued Fire Safety Certificate vide letter No. F.6/DFS/MS/School/2022/NDZ/842 dated 02/08/2022. The premises was re-inspected by the officer concerned of this department on 09/09/2025 in the presence of Mrs. Rashmi Pillai, Principal and observed that all the fire prevent in and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated-01/03/11 issued by the Director of Education and found that the building/premises is fit for occupancy class 'Educational Building (Group-B)' with effect from .39/.0.9/2020 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010 & also conditions printed below.

Issued on at New Delhi by

(VIRENDRA SINGH) CHIEF FIRE OFFICER

To,

1. The Principal, Nutan Vidya Mandir School at A.G.C.R. Enclave, Delhi-110092

2. The Director of Education, The Dy. Director of Education, D-Block, Anand Vihar, Delhi-110092

Conditions for the validity of Fire Safety Certificate

1. All the means of escape shall be kept free of all type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipment shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.

4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.

5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.

6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry.

8. Basement shall be used as per BBL/NBC Part IV.

Name & address of the building

: Nutan Vidya Mandir School,

AGCR Enclave, Delhi-110092

2. Building is comprised of

: Basement, Ground plus one upper floor only

3. Type of Occupancy

: Educational

4. Type of Case

: Renewal

5. Details of Previous NOC letter

: F.6/DFS/MS/School/2022/NDZ/842 dt 02/08/2022

6. Fire Safety direction letter No

: F16/Estate/CC/FireSafety/2011/3298to3398 dt-01/03/11

E

1:

12

7. Date of Inspection

: 09/09/2025

8. Name of the Inspecting officers

: ADO Deepak Kumar

9. Name and designation of Officer

from the building side

: Mrs. Rashmi Pillai, Principal

10. Year of Construction

: 1988

11. Applicant's letter No

: email nvm.agcr@gmail.com dated 27/08/2025

Sr.	Minimum Standards on fire	DoE Circular Provided at Site Requirement		Remarks MR/NMR				
No.	prevention and fire safety U/R33 Requirement Access to building							
01	Access to building	09 mtr.	MR					
	Road width	06 mtrs	N/A	N/A				
	Gate width	N/A	N/A	N/A				
	 Width of internal road 	N/A	N/A					
02	Number, Width, Type and Arrangement of Exits							
	a. Number of Staircases			MR				
	Upper Floor	01 nos.	02 nos.	MR				
	Basement	01 nos.	02 nos.	IVITS				
	B. Width of Staircases		1.40 mtr & 1.50 mtr	MR				
	 Upper Floor 	1.50 mtr	1.40 mtr & 1.50 mtr	MR				
	 Basement 	1.50 mtr	1.40 mil & 1.50 mil					
	c. Protection of exits	N/A	N/A	N/A				
	 Fire check door 	N/A	N/A	N/A				
	Pressurization	01 nos.	01 nos.	MR				
	d. No. of continuous staircases	011105.	011100.	1,100,000				
	to terrace e. Width of Corridor	1.50 mtr.	02 mtr.	MR				
	f. Door Size	01 mtr.	01 mtr.	MR				
03	Compartmentation.							
	Fire check door	N/A	N/A	N/A				
	Sealing of electrical shafts	N/A	N/A	N/A				
	Fire rating of shaft door	N/A	N/A	N/A				
	Water curtain	N/A	N/A	N/A				
	Fire Dampers	N/A	N/A	N/A				
04	Smoke Management System.							
	Basement	N/A	N/A	N/A				
	Upper floor	N/A	N/A	N/A				

05.	Fire Extinguishers						
	Total numbers	06 nos.	06 nos.	MR			
	Types	ABC /CO ₂	ABC /CO ₂	MR			
	IS marking	ISI marked	ISI marked	MR			
06	First-aid-Hose Reels.						
	Total numbers on each floor	01 No.	01 No.	MR			
	 Length of hose reel hose 	30 mtr.	30 mtr.	MR			
	Nozzle diameter	05 mm	05 mm	MR			
07	Automatic fire detection and alarming system.						
	Type of detectors	N/A	N/A	N/A			
	 Location of main panel 	N/A	N/A	N/A			
	 Location of repeater panel 	N/A	N/A	N/A			
	 Alternate source of power 	N/A	N/A	N/A			
	 Hooter's location 	N/A	N/A	N/A			
80	MOEFA	N/A	N/A	N/A			
09	Public address System.	N/A	N/A	N/A			
10	Automatic Sprinkler System.						
	Basement	Required	Provided	MR			
	upper floor	N/A	N/A	N/A			
	sprinkler above false ceiling	N/A	N/A	N/A			
11	Internal Hydrants						
	size of riser/down-comer	N/A	N/A	N/A			
	Number of hydrants per floor	N/A	N/A	N/A			
		N/A	N/A	N/A			
	Hose Box Yard Hydrants.						
12		N/A	N/A	N/A			
	Total number of hydrants	N/A	N/A	N/A			
	Hose Box						
13	Pumping Arrangements.						
	Ground Level	N/A	N/A	N/A N/A			
	Discharge of main Pump	N/A	N/A N/A	N/A			
	Head of Main Pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	- I was out DUI	N/A	N/A	N/A			
	lockey pump head	N/A	N/A	N/A			
	Standby pump out put	N/A N/A	N/A	N/A			
	Standby pump Head	N/A	N/A	N/A			
	Ctarting /Vallua	IN/A	50815. T	-			
	Langing	N/A	N/A	N/A			
	Pump House Access						
	Torrace Level	450 lpm .	450 lpm	MR			
7.17	Discharge of pullip	40 M	40 mtr	MR			
	Head of the Pullip	Required	Provided	MR			
	> Power supply	Required	Provided	MR			

		1 1/4	N/A	N/A			
4	Captive Water Storage for Fire Fighting.	N/A	N/A	N/A			
	 Underground tank capacity 	N/A N/A	N/A	N/A			
	Draw-off connection		N/A	N/A			
	Fire service inlet	N/A	N/A	N/A			
	Access to tank	N/A	6,000 Ltr	MR			
	Overhead Tank capacity	5,000 Ltr.	Provided	MR			
5	Exit Signage.	Required	110				
16	Provision of Lifts.		1-1	1			
		N/A	N/A	N/A			
	 Pressurization of Lift Shaft 		N/A	N/A			
	Pressurization of Lift lobby	N/A	N/A	N/A			
	a series in lift car	N/A	N/A	N/A			
	Communication in the car Secunding switch	N/A	N/A	N/A			
	Firemen's grounding switch	N/A	N/A	N/A			
	Lift Signage	N/A	IN/A				
17							
18	Refuge Area.	NI/A	N/A	N/A			
	Total area	N/A	N/A	N/A			
	Location	N/A					
10	Ti O attal Poom						
19		N/A	N/A	N/A			
	Detector system panel	N/A	N/A	N/A			
	Flow switch panel	N/A	N/A				
	PA system panel	N/A	N/A	N/A			
	Battery backup	N/A	N/A	N/A			
	Building Floor Plans	N/A	N/A	N/A			
20	Fire Drotection systems for	10,7					

The fire protection systems provided in the building were tested/checked and found

Keeping in view the deemed compliance of the minimum standards on fire functional at the time of inspection. prevention and fire safety required under the rules the FSC issued vide letter No. F.6/DFS/MS/School/2022/NDZ/842 dt 02/08/2022 renewal under rule 35 of the Delhi Fire Service Rule, 2010 is recommended.

> Signature of the Inspecting Officer :- Deepak Kumar Name

Designation

:- A.D.O (Shd)