

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. F.6/DFS/MS/School/2025/NDZ/63

Dated: 08/05/2025

FIRE SAFETY CERTIFICATE

Certified that the M/s Nutan Shiksha Sadan is running on ground plus one upper floor only, building comprised of ground plus two upper floors & ground plus one upper floor (two separate blocks) at 203/2, Moti Ram Road, Shahdara, Delhi-110032, owned/occupied by Nutan Shiksha Sadan was issued FSC vide letter No. F.6/DFS/MS/School/2022/NDZ/80 dated 01/02/2022. The school building was re-inspected by the officer concerned of this department on dated07/04/2025 in the presence of Mrs. Jagjeet Kaur (H.O.S) of school and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with rule 33 of Delhi Fire Service Rules 2010 and that the building is fit for ground to first floor onlyoccupancy class "Educational" (Group-B) with effect from 08 / 0572025 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rules, 2010.

Issued on 08 05 2025 at New Delhi by

To:-

The Principal, Nutan Shiksha Sadan, 203/2, Moti Ram Road, Shahdara, Delhi-110032

Copy to:-

The Dy. Director of Education B-Block YamunaVihar, Delhi-110053

Conditions for the validity of Fire Safety Certificate

- 1. FSC is valid for ground & first floor only. 2nd floor which is sealed may not be used for any purpose failing which FSC should be treaded null and void.
- 2. All the means of escape shall be kept free of all type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipment's and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the fire fighting equipment shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 5. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 6. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.
- 7. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry.
- 8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of

INSPECTION REPORT

1. Name & address of the building : Nutan Shiksha Sadan

203/2, Moti Ram Road Shahdara, Delhi-110032

2. Building is comprised of

: (Block A=G+2) school is running at G+1 only (2nd floor sealed)

& (Block B=G+1)

3. Type of Occupancy

: Educational

4. Type of Case

: Renewal

5. Details of Previous NOC letter

: F.6/DFS/MS/School/2022/NDZ/80 dated 01/02/2022 : F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011

6. Fire Safety direction letter No

7. Date of Inspection

: 07/04/2025

8. Name of the Inspecting officers

: ADO (Shd.) Deepak Kumar

9. Name and designation of Officer

from the building side

: Mrs. Jagjeet Kaur (HOS)

10. Year of Construction

: 1979

11. Applicant's letter No

: Outdoor Diary No. 12922 dated 25/02/2025

Sr. No	Minimum Standards on fire prevention and fire safety U/R33	Circular Requirement	Provided at Site	Remarks MR/NMR				
01	Access to building.							
		06 mtr.	09 mtr.	MR				
	Road width	N/A	N/A	N/A				
	Gate width	N/A	N/A	N/A				
02	Width of internal road N/A Number, Width, Type and Arrangement of Exits.							
	a. Number of Staircases • Upper Floor	Block A=02 nos. Block B=02 nos.	Block A=02 nos. Block B=02 nos.	MR				
	Basement	N/A	N/A.	N/A				
	B. Width of Staircases							
	Upper Floor	1.50 mtr. In each block	Block A (1.20m & 0.80m) & Block B (1.55 mtr. & 1.20 Mtr.)	MR				
	D	N/A	N/A.	N/A				
	Basement							
	c. Protection of exits	N/A	N/A	N/A				
	Fire check door	N/A	N/A	N/A				
	Pressurization d. No. of continuous staircases	01 nos.	01 nos.	MR				
	to terrace e. Width of Corridor	1.50 mtr.	1.50 mtr.	MR				
	f. Door Size	01.0 mtr.	01.0 mtr.	MR				
3	Compartmentation.							
	Fire check door	N/A	N/A	N/A				
	 Sealing of electrical shafts 	N/A	N/A	N/A				
	 Fire rating of shaft door 	N/A	N/A	N/A				
	Water curtain	N/A	N/A	N/A				
	Fire Dampers	N/A	N/A	N/A				
4	Smoke Management System.							
	Basement	N/A	N/A	N/A				
	Upper floor	N/A	N/A	N/A				
5.	Fire Extinguishers.							
	Total numbers	10 nos.	18 nos.	MR				
	• Types	ABC /CO ₂	ABC/CO ₂	MR				
	 IS marking 	ISI marked	ISI marked	MR				

NIM

06	First-aid-Hose Reels.	NIN					
	Total numbers on each floor	N/A	Provided	N/A			
	 Length of hose reel hose 	N/A	Provided	N/A			
	Nozzle diameter	N/A	Provided	N/A			
07	Automatic fire detection and alarming system	n.	Tiovided	IVA			
	Type of detectors	N/A	T 27/4	NI/A			
	Location of main panel	N/A	N/A N/A	N/A N/A			
	Location of repeater panel	N/A	N/A N/A	N/A			
	Alternate source of power	N/A	N/A	N/A			
	Hooter's location	N/A	N/A	N/A			
08	MOEFA	N/A	N/A	N/A			
09	Public address System.	N/A	N/A	N/A			
10	Automatic Sprinkler System.						
	Basement	N/A	N/A	N/A			
	upper floor	N/A	N/A	N/A			
	sprinkler above false ceiling	N/A	N/A	N/A			
11	Internal Hydrants	518 17	IVA	IN/A			
	size of riser/down-comer	N/A	N/A	N/A			
	Number of hydrants per floor	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
12	Yard Hydrants.		dia a la company	1 1/2 1			
	Total number of hydrants	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
13	Pumping Arrangements.		estelius in 1	14/11			
	➤ Ground Level	N/A	N/A	N/A			
- 1	Discharge of main Pump	N/A	N/A	N/A			
	Head of Main Pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	Jockey pump out put	N/A	N/A	N/A			
	Jockey pump head	N/A	N/A	N/A			
	Standby pump out put	N/A	N/A	N/A			
	Standby pump Head	N/A	N/A	N/A			
	Auto Starting /Manual stopping	N/A	N/A	N/A			
	Pump House Access	N/A	N/A	N/A			
	➤ Terrace Level		1 457 HT 1/4 1				
	Discharge of pump	N/A	Provided	N/A			
	Head of the Pump	N/A	Provided	N/A			
	Power supply	N/A	Provided	N/A			
	Auto Starting of pump	N/A	Provided	N/A			
14	Captive Water Storage for Fire Fighting.		police area	, the			
	Underground tank capacity	N/A	N/A	N/A			
	Draw-off connection	N/A	N/A	N/A			
	Fire service inlet	N/A	N/A	N/A			
	Access to tank	N/A	N/A	N/A			
	Overhead Tank capacity	N/A	10,000 ltrs	N/A			
5	Exit Signage.	N/A	N/A	N/A			
6	Provision of Lifts.						
	Pressurization of Lift Shaft	N/A	N/A	N/A			
	Pressurization of Lift lobby	N/A	N/A	N/A			
	Communication in lift car	N/A	N/A	N/A			
	Firemen's grounding switch	N/A	N/A	N/A			
	Lift Signage	N/A	N/A	N/A			



17	Standby power supply	N/A	N/A	N/A			
18	Refuge Area.						
	Total area	N/A	N/A	N/A			
	Location	N/A	N/A	N/A			
19	Fire Control Room						
	Detector system panel	N/A	N/A	N/A			
	Flow switch panel	N/A	N/A	N/A			
	PA system panel	N/A	N/A	N/A			
		N/A	N/A	N/A			
	Battery backup	N/A	N/A	N/A			
	Building Floor Plans		N/A	N/A			
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	IVA	3			

Note:- The Management has been submitted undertaking attached at C/24, that the 2nd floor sealed and not used for any purpose.

The fire protection systems provided in the building were tested/checked and found

functional at the time of inspection. Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011. The FSC issued vide letter no. F.6/DFS/MS/School/ 2022/NDZ/80 dated 01/02/22 renewal under rule 35 of the Delhi Fire Service Rules, 2010 is recommended.

> Name :- Deepak Kumar :- A.D.O (Shd) Designation

DFA Bloom.