

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001



No F 6/DFS/MS/GH/2025/NDZ/ 513

Dated:

25/09/2025

FIRE SAFETY CERTIFICATE

Certified that the M/s Olive International located at 8641 Old 59, New Street, Arakashan Road, Pahar Ganj, Delhi-110055 comprised of Stilt (Parking), Ground Floor to 3rd floor (04 Guest rooms at each floor) was issued FSC by this department vide letter No F6/DFS/MS/GH/NDZ/2022/413 dated 07.09.2022. The premise was re-inspected by the officer concerned of this department on 15.09.2025 in the presence of Sh. Surya Prakash and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have therefore deemed complied with fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premise is fit for occupancy "Class A, Residential (Guest House for total 16 Guest Rooms from Ground floor to 3rd floor only)" with effect from 25.22. 12.25... for a period of three years in accordance with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40, subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ... 2.5 0.9 2.35 at New Delhi, by

(Virendra Singh) Chief Fire Officer

de n

Copy to: -

- 1. The Commissioner, MCD, Civic Centre, New Delhi- to ensure the occupancy as detailed above.
- 2. M/s. Olive International located at 8641 Old 59, New Street, Arakashan Road, Pahar Ganj, Delhi-110055.
- 3. MCD Portal, ID No. 2025090513203.

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate through MCD portal (https://www.mcdonline.gov.in) along with a copy of this Certificate, six months prior to its expiry.
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. Any flammable material for interior decoration is prohibited.

11-113

INSPECTION REPORT

Name & address of the building: M/s Olive International located at 8641 Old 59, New Street, Arakashan Road, Pahar Ganj, Delhi- 110055.

Type of Occupancy Residential (A-1) (Total 16 Guest Rooms) 3. Building Comprised of

: Stilt (Parking), Ground floor to 3rd (04 rooms at each floor) 4. Type of Case 5. Details of Previous NOC

F6/DFS/MS/GH/NDZ/2022/413 Dated 07/09/2022 6. Fire Safety directives letter No :

7. Date of inspection 15/09/2025 8. Name of Inspecting Officer

R.K.Sinha, ADO (BW) 9. Name and designation of officers

10. From the building side Sh. Surya Prakash 11. Year of Construction 2018 as per MCD Portal 12. Applicant's letter No.

S. No.	Minimum Standards on fire prevention and fire safety U/	S o partet)	Provided at the	Old ca Remarks		
1.	Access to building	arrangements		MR/NMR		
	Road width					
	Gate width	NA NA	6 m	NA		
	Width of internal road	NA NA	NA	NA		
2.	Number, Width, Type & Arr	NA angement of Frits	NA	NA		
	Number of staircases					
	Upper Floors	02	02			
	Basements	NA	NA NA	MR		
	Width of staircases		IVA	NA		
	Upper Floor	1.5 m each	Provided	1.69		
	Basements	NA	NA	MR		
	Protection of exits		INA	NA		
	Fire check door	NA	NA			
	Pressurization	NA	NA NA	NA		
	No. of continuous staircases to		INA	NA		
	terrace	01	01	MR		
	Width of Corridor	NA	NA	NA		
	Door Size	1 m	Provided	NA MR		
3.	Compartmentation			WIK		
	P	III II S		97.5		
	Fire check door	NA	NA	NA		
	Sealing of electrical shafts	NA	NA	NA		
	Fire Rating of shaft door	NA	NA			
	Water Curtain	NA	NA	NA		
_	Fire Dampers	NA	NA	NA NA		
	Smoke Management System	XII		NA		
	Basements	NA	NA	NIA		
	Upper floors	Required	Natural/ Exhaust Fan	NA		
	Fire Extinguishers	-sequinou	ratural Exhaust Fan	MR		
	Total numbers	15 Nos.	Provided	100		
	Types	ABC/Co2 Type	Provided	MR		
	IS marking	Required	Provided	MR		
	First-Aid Hose Reels	required	Flovided	MR		
1	Total numbers on each floor	01	Provided	M		
	ength of hose reel hose	30 m	30 m	MR MR		
N	Nozzle diameter	5 mm	5 mm			
	Automatic fire detection and ala	arming system		MR		
L L	ype of detectors	СО	Provided	MR		
	ocation of Main Panel	Ground Floor	Provided	MR		
	ocation of Repeater Panel	NA	NA	NA NA		
	Iternate source of power	Required	Provided	MR		
	ooters' Location	Required	Provided	MR		
	10EFA	Required	Provided			
	ublic Address System	Required	Provided	MR		

	,	11
M	ા	7

. A	utomatic Sprinkler System		5)			
		NA NA	NA	NA		
В	asement	NA NA	NA	NA		
	pper Floor	NA NA	NA	NA		
	prinkler above false ceiling	A. William	•			
	nternal Hydrants		N.	NA NA		
	C. i / laven comer	NA	NA NA	NA NA		
S	Size of riser/down-comer Number of hydrants per floor	NA	NA NA	NA NA		
	Number of hydrants per moor Hose Box	NA	NA	IVA		
	Yard Hydrants					
		NA	NA	NA		
7	Total number of hydrants	NA NA	NA	NA		
1	Hose Box	134.8				
13.	Pumping Arrangements					
	Ground Level	NA	NA	NA		
	Discharge of main Pump	NA NA	NA	NA		
-	Head of Main pump		NA	NA		
	Number of main pumps	NA	NA NA	NA		
	Jockey Pump out put	NA NA	NA NA	NA		
	Jockey pump head	NA NA	NA NA	NA		
	Standby Pump out put	NA NA	NA NA	NA		
	Standby Pump Head	NA NA	NA	NA		
	Auto Starting/Manual Stopping	NA NA	NA	NA		
	Pump House Access	IVA	GE 40/250			
	Terrace level	145011	Provided	MR		
	Discharge of pump	450 lpm 40 m	Provided	MR		
	Head of the pump		Provided	MR		
	Power Supply	Required	Provided	MR		
	Auto Starting of pump	Required				
14.	Captive Water Storage for fire fight		274	NA		
	Underground tank capacity	NA	NA NA	NA NA		
	Draw-off connection	NA	NA NA	NA NA		
	Fire service inlet	NA	NA NA	NA NA		
	Access to tank	NA	Provided	MR		
	Overhead Tank capacity	10,000 ltrs	Provided	MR		
15.	Exit Signage.	Required	Tiovided	31523		
16.	Provision of Lifts.	- 1				
-	Pressurization of Lift Shaft	NA	NA	NA		
1	Pressurization of Lift lobby	NA	NA	NA		
	Communication In lift Car	NA	NA	NA		
	Fireman's Grounding Switch	NA	NA	NA		
	Lift Signage	NA	NA	NA		
17.		Required	Provided	MR		
				-		
18.						
	Total Area	NA	NA NA	NA NA		
	Location	NA	NA	NA		
19.	Fire Control Room					
	Detector System Panel	NA	NA	NA		
	Flow Switch Panel	NA	NA	NA		
	PA System Panel	NA	NA	NA		
	Battery backup	NA	NA	NA		
	Building Floor Plans	NA /	NA	NA		
house		V	02			

The fire protection system for protection of special Risks, if any: The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. Keeping in view of deemed compliance of the minimum standards of fire prevention and fire safety measures as required under rules it is recommended to renew the fire under Rule 37 of the Delhi Fire Service Rules, 2010. Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W. Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W. Receipt Tolky 125 Dyuffo (2020) Rinelpad Director ADD VARIOUS ADD V	Pin Bustostian C	N-15		
The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. Keeping in view of deemed compliance of the minimum standards of fire prevention and fire safety measures as required under rules it is recommended to renew the fire under Rule 37 of the Delhi Fire Service Rules, 2010. **Rolling** Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO'B.W. **Designation: ADO'B.W.** **Provided Designation: ADO'B.W.**	Special Fire Protection System for Protection of special Risks, if any:	NA	NA	NA
and fire safety measures as required under rules it is recommended to renew the fire safety certificate issued vide letter no. F6/DFS/MS/GH/NDZ/2022/413 dated 07/09/2022 Signature of Inspecting Officer Name: Rajeev Kunara Sinha Designation: ADO/B.W. Signature of Inspecting Officer Name: Rajeev Kunara Sinha Designation: ADO/B.W. Pater 1912 2015 Principal Director Liphus Liph				IVA.
Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W. Adologo Pineipal Dinector Designation and Dinector Adologo Pineipal Dinector Designation and Dinector Adologo Pineipal Dinector	and fire safety measures as requisafety certificate issued and	l compliance of the mi red under rules it is	inimum standarda ef	c
Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W. Action of the Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W. Action of the Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W. Action of the Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W. Action of the Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W. Action of the Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W. Action of the Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W. Action of the Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W. Action of the Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W. Action of the Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W. Action of the Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W. Action of the Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W. Action of the Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W. Action of the Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W. Action of the Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W. Action of the Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W. Action of the Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W. Action of the Signature of Inspecting Officer Name: Adoption of the Signature of Inspection	under Rule 37 of the Delhi Fire Se	er no. F6/DFS/MS/GF	I/NDZ/2022/413 dat	ed 07/09/2022
About the series of the series	Pho i	vice Rules, 2010.		71
About the series of the series				de an
About the series of the series				(1800 (184)
About the series of the series				1697
Andrew Commentary Commentary for grand, and grand of the start of the			Name : Rajee	V Kumar Sinha
Rineipal Dinector Party Services Construction Construct				. ADO/B.W.
Rineipal Dinector Party Services Construction Construct	1. 1			
Rineipal Dinector Party Services Construction Construct	Logo in			
Rineipal Dinector Party Son War of Jesterni Patery for grant, Cofo Must zerr Cofo Must zerr	16/9/25			
Rineipal Dinector Party Son War of Jesterni Patery for grant, Cofo Must zerr Cofo Must zerr	N. (60 (1002) 1			
Rineipal Dinector Party Services Construction Construct	Bysico	17/08/25		
Doc 24/9/2 Doc 24/9/2	6CF.01	·		
Doc 24/9/2 Doc 24/9/2	M.	Ω		
Doc 24/9/2 Doc 24/9/2	10 0	y _		
Doc 24/9/2 Doc 24/9/2	/4.41	, 5002		
Doc 24/9/2 Doc 24/9/2	Principal Dings			
24/9 ADS CAST WORK, FT Letterni Putrey for Sport, Stock 24/9/2			\$0 10	John.
24/9 ADS CAST WORK, FT Letterni Putrey for Sport, Stock 24/9/2			6	R
24/9 ADS CAST WORK, FT Letterni Putrey for Sport, Stock 24/9/2		æ	- 4	
24/9 ADS CAST WORK, FT Letterni Putrey for Sport, Stock 24/9/2			1 22	05/125
cfof thurst sers		Cat !	3	
cfof thurst sers				
cfof thurtzers	<i>f</i>		V	7
cfof thurst sers	La Later)		
cfof thurst sers				call
cfof thurst sers	124/9	D Char as	GT letteri	Outer for spins,
cfof thurst sers		811	, \ ,	() A LONG
				A GOLDE
		1		24/71
Me uploaded cfscy	cfo	Muy sers	**	
My uploaded Ctsc)			6 1	
		MS_	- uplo	neded Ctsc)
26 9			_	26 9