

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

आज़ादी क अमृत महोत्सव

F6/DFS/MS/Hotel/SZ/2025/ 02

Dated: 27 02 2025

## **FIRE SAFETY CERTIFICATE**

Certified that the M/s Park Inn by Radisson located at 1 & 2, Ring Road, Lajpat Nagar-IV, New Delhi-24, comprised of Basement + Ground + Mezzanine floor + 04 upper floors was granted FSC by this department vide letter no. F6/DFS/MS/Hotel/SZ/2022/46 dated 15.06.2022. The building/premises was re-inspected by Assistant Divisional Officer (M. Road) from this department on 21.02.2025 in presence of Sh. R.K. Mondal (Liasoning Manager) & Sh. Abhishek Chaudhary (CSO) and found that the building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the premises is fit for occupancy of "Residential Group-A" (Hotel Building) and valid upto 31.03.2028 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire service Rules, 2010 printed below.

Issued on 27/02/2025 at New Delhi by

(Aful Garg)
Director

Delhi Fire Service

Copy to:-

1. The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defence Colony, New Delhi.

2. The Licensee, M/s Park Inn by Radisson located at 1 & 2, Ring Road, Lajpat Nagar-IV, New Delhi-24.

## Conditions for the validity of Fire Safety Certificate

- 1. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- Any loss of life or property due to non functional fire safety measures shall be at the responsibility
  of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.

Mai

		INSP	ECTION REPORT			
1		& address of the building	M/s Park Inn by Radisson located at 1 & 2, Ring Road, Lajpat Nagar-IV, New Delhi-24.			
2		ng is comprised of	Basement + Ground + Mezzanine + 04 upper floors			
3	Type of occupancy		Residential "Hotel Building"			
4	Type of case		Renewal			
5	Detail	s of Previous FSC	F6/DFS/MS/Hotel/SZ/2022/46 dated 15.06.2022			
6	Fire S	afety direction letter no.	Nil			
7	Date o	of inspection	21.02.2025			
8	Name	of the inspecting officers	Rajesh Kumar Shukla ADO (M. Road)			
9		of the designation of officer	Sh. R.K. Mondal (Liasoning Manager) & Sh. Abhishek Chaudhary (CSO)			
		the building side				
10	Year of construction Applicant's letter no.  Minimum Standards on fire Prevention and fire safety requirements U/R 33		1968 Email dated 20.02.2025			
11						
S.N			Requirement as	Provided at Site	Remarks MR/NM R	
0			Requirement as Rule 35 (6)	Provided at Site		
1	100000000000000000000000000000000000000	ess to building				
	A	Road width	Required	10.0 mtrs	MR	
	В	Gate width	Required	5. 0 mtrs	MR(Old Case)	
	C	Width of internal road	Required	7.0 mtrs (one side)	MR(Old Case)	
2	Nu	mber, Width, Type and Arrange	ement of Exits			
	A	Number of staircases				
		a Upper floor	1 <sup>st</sup> floor to 4 <sup>th</sup> floor =2 nos. Ground to mezzanine floor = 1 no.	1 <sup>st</sup> floor to 4 <sup>th</sup> floor =2 no Ground to mezzanine floor = 1 no	MR (old case)	
	1	b Basement	Required	2 nos.	MR	
	В	Width of staircases				
		a Upper floor	Required	1.50 mtrs & 0.95 mtrs	MR	
		b Basement	Required	1.50 mtrs & 0.95 mtrs	MR	
	C	Protection of exits		· ·		
		a Fire check door	NA	NA	NA	
	LOLLY	b Pressurization	NA	NA	NA	
	D.	No. of continuous staircases to terrace	Required	2 nos.	MR	
	E	Width of corridor	Required	1.70 mtrs	MR	
	F	Door size	Required	1.0 mtrs (final exit)	MR	
3		mpartmentation	Total Carlo	I II		
	A	Fire check door	Required in basement	Provided	MR	
	В	Sealing of electrical shafts	Required	Provided	MR	
	C	Fire rating of shaft door	Required	Provided	MR	
	D	Water curtain	NA	NA	NA	
	E	Fire dampers	NA	NA	NA	
4	Smoke Management System.					
	A	Basement	Required	Provided	MR	
	B	Upper floor	Required	Provided	MR	

M/.	Park	Inn	by Radisson located at 1 & 2 B: B	N192	u . 24		
5.	Fire Extinguisher			Road, Lajpat Nagar-IV, New Delhi-24			
	A	I.	otal numbers	52 nos.	52 nos.	MR	
	B		ypes	ABC W.CO <sub>2</sub> CO <sub>2</sub> &	ABC W.CO <sub>2</sub> , CO <sub>2</sub> &	MR	
				Mechanical Form	Mechanical Form	1	
	C		SI marking	Required	ISI marked	MR	
6	F	irst	-Aid-Hose Reels				
	A	T	otal numbers of each floor	1 no.	1 no.	MR	
	В	L	ength of hose reel hose	30 mtrs.	30 mtrs.	MR	
	C	N	lozzle diameter	5 mm	5 mm	MR	
7	A	uto	matic Fire Detection And Ala	Section (Control Control Contr			
	A	1	Type of detectors	Smoke & heat	Provided	MR	
	В		Location of main panel	Required	Ground floor	MR	
	C	1	Location of repeater panel	NA	NA	NA	
	D	1	Alternate source of power	NA	NA	NA	
	E	I	Hooters	Entire building	Provided	MR	
8	100000	OE		Required	Provided	MR	
9			c Address System.	Required	Provided	MR	
10	A		natic Sprinkler System.				
	A	Ba	asement	Required	Provided	MR	
	В	Gı	round & Upper floor	Required	Provided	MR	
	C	Sp	prinkler above false ceiling	Required	Provided	MR	
1	Internal Hydrants						
	A size of riser/down-comer			100 mm	100 mm	MR	
	В		imber of hydrants per floor	01 no.	01 no.	MR	
	C		ose box	01 nos.	01 nos.	MR	
2	Yard Hydrants.						
_	A		tal number of hydrants	Required	02 nos.	MR	
	B			Required	02 nos.	MR	
2			STATE CONTRACT	Required	02 1103.	IVIIC	
3		mpi	ing Arrangements.			-	
	A		Ground Level	Required	1800 LPM	MR	
		a	Discharge of main Pump	HALL THE PROPERTY OF THE	60 mtrs	MR	
		b	Head of Main Pump	Required		MR	
		c	Number of main pumps	Required	1 nos.	MR	
		d	Jockey pump out put	Required	180 LPM	September 1	
12		е	Jockey pump head	Required	60 mtrs 2280 LPM (DG	MR NA	
	>	f	Standby pump out put	NA	Pump provided)	Control of the Contro	
		g	Standby pump Head	NA	70 m	NA	
		h	Auto Starting /Manual stopping	Required	Provided	MR	
	1	i	Pump house access	Required	Provided	MR	
	В	Te	errace Level	Marian	000 Y P1 /	MD	
-		a	Discharge of pump	Required	900 LPM	MR	
		b	Head of the Pump	Required	40 mtrs.	MR	
		c	Power supply	Required	Provided	MR	
	- 1	50 D	Auto starting of pump	Required	Provided	MR	

4	Captive Water Storage for Fire Fighting.			
	A Underground tank capacity	80,000 ltrs	Provided MP	
	B Draw-off connection	Required	Provided	MR
1	C Fire service inlet	Required	Provided	MR
1	D Access to tank	Required	Provided	MR
	E Overhead tank capacity	25,000 ltrs	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.		Tiovided	MR
+	A Pressurization of lift shaft	NA	T	
	B Pressurization of lift lobby	NA	NA	NA
	C Communication in lift car	NA	NA	NA
1	D Firemen's grounding switch	Required	NA	NA
1	E Lift signage	Required	Provided	MR
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area.	required	Provided	MR
	A Total area	NA		
	B Location	NA NA	NA	NA
19	Fire Control Room	NA	NA	
1	A Detector system panel	NA	Ta .	
	B Flow switch panel	NA	Provided	NA
	C PA system panel	NA	NA	NA
	D Battery backup	NA NA	Provided	NA
	E Building floor plans	NA NA	Provided	NA
20	Special Fire Protection Systems For Prote	NA	NA	
	Risks, If Any:	CO <sub>2</sub> flooding	MR	
	(A) (2) (T. T. T. V. S.		system	
			provided in	
			HT & LT	
			panel	

## Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided but Not Functional (PNF), Not Provided (NP).

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. F6/DFS/MS/Hotel/SZ/2022/46 dated 15.06.2022 is recommended to be renewed under Rule 35 of the Delhi Fire Service Rules

> Signature of the Inspecting Officer Rajesh Kumar Shukla Name Designation

ADO (M. Road)